REPORT #: 4074593 REPORT DATE: 3/24/2025

Your SMART 1 Page NHD™

Click any section below for instant navigation or View the full NHD Report Click Here





FORMS

View Forms

View, read, & print forms



QUICKVIEW

Read complete disclosure report summary



FLOOD

View Results

4 source(s) analyzed

2 Federal / 2 State / 0 Local



OIL & GAS

View Results

8 source(s) analyzed

1 Federal / 3 State / 4 Local



FIRE

View Results

8 source(s) analyzed

1 Federal / 6 State / 1 Local



NOISE

View Results

3 source(s) analyzed

1 Federal / 1 State / 1 Local



SEISMIC

View Results

7 source(s) analyzed

1 Federal / 5 State / 1 Local



LAND USE

View Results

14 source(s) analyzed

5 Federal / 4 State / 5 Local



GEOLOGIC

View Results

11 source(s) analyzed

3 Federal / 7 State / 1 Local



ENVIRONMENTAL View Results

6 source(s) analyzed

2 Federal / 4 State / 0 Local



Property Tax Records View

Future Tax Estimator (click to calculate)




Terms & Conditions

Read our Terms & Conditions

PROPERTYID.COM | (800) 626-0106 | MAX@PROPERTYID.COM



MAX Commercial NHD with Environmental Hazards & Forms



5454 VIRGINIA AVE LOS ANGELES, CA 90029 LOS ANGELES COUNTY

REPORT #: 4074593

ORDER DATE: 03/24/2025

RESEARCH DATE: 03/24/2025

My Home

My Maps



Have Questions? We have answers.
Chat with Sami here.



5454 VIRGINIA AVE, LOS ANGELES, CA 90029 OS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

This statement applies to the following property: 54	54 VIRGINIA AVE LOS ANGELES, CA 90029;	LOS ANGELES COUNTY; APN: 5536-010-006	Date: 03/24/2025
This disclosure statement is intended to be a part of AIR STANDARD OFFER AGREEMENT AND ES		EAL ESTATE or	
		(the "Purchase Agreement") dated	
wherein	is the Seller and	is the Buyer.	
Note: This disclosure statement is <u>not</u> designed nor THIS REAL PROPERTY LIES WITHIN THE FO	•	d Property Information Sheet.	
A SPECIAL FLOOD HAZARD AREA (Any type Yes No _X_ Do not know	Zone "A" or "V") designated by the Federa v and information not available from local		ort.
AN AREA OF POTENTIAL FLOODING SHOW Yes No _X Do not know	N ON A DAM FAILURE INUNDATION MAI v and information not available from local		t Code. Refer to Report.
A HIGH or VERY HIGH FIRE HAZARD SEVER (commencing with Section 4201) of Chapter 1 of Pa Government Code. Refer to Report. Yes No _X		r of Forestry and Fire Protection pursuant to Section The owner of this property is subject to the maintena	
High FHSZ in a state responsibility area Very High FHSZ in a state responsibility area Very High or High FHSZ in a local responsibili			
A WILDLAND AREA THAT MAY CONTAIN SUproperty is subject to the maintenance requiremany building or structure located within the wildlapurposes pursuant to Section 4142 of the Public Yes No _X	ents of Section 4291 of the Public Resource ands unless the Department of Forestry and I	s Code. Additionally, it is not the state's respons	ibility to provide fire protection services to
AN EARTHQUAKE FAULT ZONE pursuant to S	Section 2622 of the Public Resources Code.	Refer to Report.	
A SEISMIC HAZARD ZONE pursuant to Sectio Yes (Landslide Zone) Yes (Lique	n 2696 of the Public Resources Code. Refer faction Zone) No _X_ Map not	to Report. syet released by state	
The items listed below indicate additional statutory d	sclosures and legal information that are provide	ed in the report.	
ASSESSMENTS pursuant to Section 53311-533€ Additional Local Jurisdiction Hazards - May incluc Airports, Airport Influence Area, Avalanche Level Rise, Landslide, Liquefaction, Methane Gas Williamson Act, Wind Erosion. Refer to Report. General Notices: Methamphetamine Contamination, Megar Plumbing Fixtures, Notice of Supplemental Properto Report. Governmental Guides are delivered with printed re	closed if ordered) IION (where available) (B) MILITARY ORDNANCE FA 5.7 / 5.3754 of the California Government Code; Re le the following: e, Coastal Protection, Conservation Areas, Critical Ha; Mines, Naturally Occurring Asbestos, Oil and Gas V of Staw – Sex Offender Database, Mold, Abandoned ty Tax Bill, AB 38 Notice, CALFIRE Defensible Spaceports and linked on electronically delivered reports (abitats, Dam Failure Inundation, Duct Sealing Requiremen Well Proximity, Petrochemical Contamination, Property Ta I Wells. Carbon Monoxide Devices, Natural Gas and Haza e, CALFIRE Low Cost Retrofit List, SGMA Groundwater E	nts, Erosion, Fault Zone, Fire, Groundwater, Sea Ixes, Radon, Right to Farm, Soil Stability, Tsunam Irdous Liquid Pipelines, Water Conserving Basin Priority, Historical Significance Notice. Refer
The above disclosure statement, legal, and governm by any broker as to the legal sufficiency, legal effect, Statement do not constitute all of the seller's or ager	or consequences of this document, or the purc	s or warranties the principal(s) may wish to obtain. N hase agreement to which it relates. The representation	
This Report contains the Mandatory Commercial Na please contact Property I.D. Customer Service at 80	· · · · · · · · · · · · · · · · · · ·	ntal Risk Report is only enclosed if it has been ordered	d. To order the Environmental Risk Report,
Signature of Seller(s)		Date	
Print Name			
Signature of Seller(s) Print Name		Date	
Signature of Buyer(s)		Date	
Print Name			
Signature of Buyer(s)		Date	
Print Name			

Return to 1 Page NHD™

REPORT DATE: 3/24/2025



⋙ FLOOD

DISCLOSURE	SOURCE	RESULT	PAGE
Flood Zone	Federal	NOT IN	<u>12</u>
FEMA Community Rating System	State	IN	14
Dam Inundation	State	NOT IN	<u>15</u>
USACE Reservoir Proximity	Federal	NOT IN	<u>16</u>
Standard Flood Hazard Determination Form	Federal	INCLUDED	<u>138</u>

H FIRE

DISCLOSURE	SOURCE	RESULT	PAGE
High or Very High Fire Zone	State	NOT IN	<u>18</u>
Fire Hazard Severity Zone Rating	State	IN LOW	<u>18</u>
Very High Fire Hazard	City	NOT IN	<u>19</u>
City of Los Angeles Brush Clearance Requirements	City	INCLUDED	<u>19</u>
Wildland Fire Area (SRA)	State	NOT IN	<u>20</u>
Defensible Space Flyer	State	INCLUDED	<u>21</u>
Wildland-Urban Interface Fire Hazard	Federal	NOT IN	<u>22</u>
Wildland-Urban Interface Fire Hazard	State	NOT IN	<u>22</u>
Utility Infrastructure Fire Hazard	State	NOT IN	<u>22</u>
Tree Mortality Fire Hazard	State	NOT IN	<u>23</u>
Firewise USA®	National	INCLUDED	<u>24</u>

Return to 1 Page NHD™







DISCLOSURE	SOURCE	RESULT	PAGE
Assembly Bill 38 Notice	State	INCLUDED	<u>25</u>
CALFIRE Low Cost Retrofit List	State	INCLUDED	<u>26</u>

SEISMIC

DISCLOSURE	SOURCE	RESULT	PAGE
Alquist-Priolo Fault Zone	State	NOT IN	<u>27</u>
Earthquake Faults	Federal	NOT WITHIN 1/4 MILE	<u>28</u>
Earthquake Faults	State	NOT WITHIN 1/4 MILE	<u>28</u>
Earthquake Faults	County	WITHIN 1/4 MILE	<u>28</u>
Ground Shaking	State	IN VIOLENT	<u>29</u>
Earthquake-Induced Liquefaction	State	NOT IN	<u>30</u>
Earthquake-Induced Liquefaction	State	IN	<u>30</u>

GEOLOGIC

DISCLOSURE	SOURCE	RESULT	PAGE
Landslide Hazard Zones	State	NOT IN	<u>31</u>
Landslide Deposits	Federal	NOT IN	<u>31</u>
Landslide Inventory	State	NOT IN	<u>31</u>
Expansive Soils	Federal	IN UNMAPPED AREA	<u>33</u>

Return to 1 Page NHDTM



REPORT DATE: 3/24/2025





DISCLOSURE	SOURCE	RESULT	PAGE
Soil Subsidence/Settling Earth	Federal	NOT IN	<u>33</u>
Wind Erosion	Regional	IN VERY LOW	<u>34</u>
Naturally Occuring Asbestos	State	NOT IN	<u>35</u>

I OIL & GAS

DISCLOSURE	SOURCE	RESULT	PAGE
Oil and Gas Wells	State	NOT WITHIN 500 FEET, BUT WITHIN 1/2 MILE,	<u>36</u>
Oil and Gas Field Administrative Boundary	State	NOT WITHIN	<u>36</u>
Natural Gas Storage Facilities	Federal	NOT WITHIN 2 MILES	<u>37</u>
Radon Gas	State	IN LOW	<u>38</u>
Methane Gas	County	NOT IN	<u>39</u>
Methane Producing Landfill	County	NOT WITHIN 1000 FEET	<u>39</u>
Methane Gas	City	NOT IN	<u>39</u>
Oil and Gas Industrial Area	County	NOT IN	<u>40</u>







₩ NOISE

DISCLOSURE	SOURCE	RESULT	PAGE
Airport Influence Area	County	NOT IN	<u>41</u>
Airport Vicinity	Federal	WITHIN 2 MILES	<u>41</u>
SoCal Metroplex Airspace Optimization Notice Area	Federal	IN	<u>42</u>
Railroads	State	NOT WITHIN 1/4 MILE	<u>43</u>

▲ LAND USE

DISCLOSURE	SOURCE	RESULT	PAGE
Mining Operations	State	NOT WITHIN 1 MILE	<u>45</u>
Abandoned Mining Operations	State	NOT WITHIN 1 MILE	<u>45</u>
Mine Sites	Federal	NOT WITHIN 1/4 MILE	<u>45</u>
Former Military Facilities (FUDS)	Federal	NOT WITHIN 1 MILE	<u>47</u>
Military Facilities	Federal	NOT WITHIN 1 MILE	<u>47</u>
Methane Producing Landfill	County	NOT WITHIN 1000 FEET	<u>49</u>
Landfills (SWIS)	State	NOT WITHIN 3 MILES	<u>49</u>
Landfills (Envirostor)	State	NOT WITHIN 3 MILES	<u>49</u>
Landfills (Geotracker)	State	NOT WITHIN 3 MILES	<u>49</u>
Landfills (RCRA)	State	NOT WITHIN 3 MILES	<u>49</u>
Industrial/Commercial Land Use	City	IN	<u>51</u>
Industrial/Commercial Zoning	City	IN	<u>51</u>





REPORT DATE: 3/24/2025



▲ LAND USE

DISCLOSURE	SOURCE	RESULT	PAGE
Industrial / Commercial Use	Regional	IN	<u>51</u>
Historic-Cultural Monuments	City	NOT IN	<u>53</u>
Historic Preservation Overlay Zones	City	NOT IN	<u>53</u>
Historical Significance Notice	State	INCLUDED	<u>54</u>
Critical Habitats	Federal	NOT IN	<u>55</u>
Protected Species / Habitats in Proximity	Federal	NOT IN	<u>55</u>
Protected Species / Habitats in Proximity	State	IN	<u>55</u>
Right to Farm	State	NOT WITHIN ONE MILE	<u>57</u>

ENVIRONMENTAL

DISCLOSURE	SOURCE	RESULT	PAGE
Groundwater Management and Monitoring (Potential Well Regulation)	State	IN VERY LOW PRIORITY	<u>67</u>
Environmental Report	EPA, DTSC, CalRecycle. SWRCB	INCLUDED	<u>68</u>

Return to 1 Page NHDTM



NOTE: Your signature on the NHDS Report Receipt page is sufficient to acknowledge delivery/receipt of this page and all the information herein.





ENVIRONMENTAL HAZARDS SUMMARY

This Environmental Hazards Report provides information on known, existing and historic hazardous substance contaminated sites that may be on or near the Subject Property, as listed by the Environmental Protection Agency and/or other specified regulatory bodies.

MAPPED

DISCLOSURE	REGULATORY	SITE COUNT	PAGE
NPL/SEMS National Priorities List / Superfund Enterprise Management System	EPA	0	<u>69</u>
RCRA Resource Conservation and Recovery Act	EPA	61	<u>69</u>
ENVIROSTOR Hazardous Substance Contamination Sites, Site Mitigation & Brownfield Reuse Program Sites	CA Department of Toxic Substances Control	14	<u>100</u>
SWIS Solid Waste Information System	CalRecycle	0	<u>107</u>
GEOTRACKER Underground Storage Tanks, Department of Defense Site Cleanup Program, Land Disposal Sites	CA Water Resources Control Board	13	<u>107</u>

UNMAPPED

DISCLOSURE	REGULATORY	SITE COUNT	PAGE
NPL/SEMS - Unmapped National Priorities List / Superfund Enterprise Management System	EPA	1	<u>113</u>
RCRA - Unmapped Resource Conservation and Recovery Act	EPA	28	<u>114</u>
ENVIROSTOR - Unmapped Hazardous Substance Contamination Sites, Site Mitigation & Brownfield Reuse Program Sites	CA Department of Toxic Substances Control	0	NA









UNMAPPED

DISCLOSURE	REGULATORY	SITE COUNT	PAGE
SWIS - Unmapped Solid Waste Information System	CalRecycle	0	NA
GEOTRACKER - Unmapped Underground Storage Tanks, Department of Defense Site Cleanup Program, Land Disposal Sites	CA Water Resources Control Board	0	NA

GENERAL NOTICES OF REQUIRED DISCLOSURES & FORMS

NOTICE		
Building Energy Use Benchmarking and Public Disclosure Program	INCLUDED	<u>128</u>
Methamphetamine & Fentanyl Disclosure Requirement	INCLUDED	<u>129</u>
Megan's Law - Sex Offender Database	INCLUDED	<u>129</u>
Mold Notice	INCLUDED	<u>129</u>
Abandoned Wells	INCLUDED	<u>130</u>
Radon Notice	INCLUDED	<u>130</u>
Well Stimulation Treatments Notice: Hydraulic Fracturing	INCLUDED	<u>131</u>
Carbon Monoxide Devices	INCLUDED	<u>131</u>
Natural Gas and Hazardous Liquid Pipelines	INCLUDED	<u>132</u>
Water Conserving Plumbing Fixtures	INCLUDED	<u>132</u>
Notice of Duct Sealing Requirements	INCLUDED	<u>133</u>







5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES & FORMS

NOTICE		PAGE
Notice of Assembly Bill 1482: Tenant Protection Act of 2019	INCLUDED	<u>133</u>
California Waterway Setback Requirements	INCLUDED	<u>134</u>

PROPERTY TAX RECORDS

The following Total Annual Tax amount represents the annual property taxes based on the levies and property valuation as listed in the assessor's tax records as of the beginning of the identified tax year. This amount is subject to change pursuant to the purchase price of the property and/or changes to the assessed value, and does not include supplemental tax bills or penalty fees.

\triangle	At the variable tax rate of	\$4	80.34	
TILLIF	1.199691%		025Property Bill Total	
Mello-Roos	Total		0.00	
Direct Charg	je (Special Asmt/1915) T	otal	\$480.34	
Variable (Ad	Valorem) Tax Total:		0.00	

Proceed to Property Tax Page

To see an estimate of the future taxes based on purchase price, please click the Property I.D. Future Tax Estimator below.











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

⋙ FLOOD

DISCLOSURE	SOURCE	RESULT	PAGE
Flood Zone	Federal	NOT IN	<u>12</u>
FEMA Community Rating System	State	IN	14
Dam Inundation	State	NOT IN	<u>15</u>
USACE Reservoir Proximity	Federal	NOT IN	<u>16</u>
Standard Flood Hazard Determination Form	Federal	INCLUDED	<u>138</u>

FLOOD HAZARD ZONES

NHDS DETERMINATION

A SPECIAL FLOOD HAZARD AREA (Any type Zone "A" or "V") designated by the Federal Emergency Management Agency. Yes ___ No _X_ Do not know and information not available from local jurisdiction ___

FEMA FLOOD ZONE

Based on PROPERTY I.D.'s research of the Flood Insurance Rate Maps issued by the Federal Emergency Management Agency, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A SPECIAL FLOOD HAZARD AREA (SFHA).

IT IS IN ZONE X (NOT AN SFHA).

DISCUSSION:

Through its Flood Hazard Mapping Program, FEMA identifies flood hazards, assesses flood risks, and partners with communities to provide flood hazard maps to guide planning and mitigation actions. The National Flood Insurance Program (NFIP) relies on FEMA's Flood Insurance Rate Maps (FIRMs) and documents in determining a property's flood insurance requirements.


FEMA's assessment of flood hazards categorizes geographic zones by their likelihood to flood. Areas with a 1-percent or greater chance of flooding in any given year (i.e. a "100-year floodplain") are considered Special Flood Hazard Areas (SFHA). Properties found to be in an SFHA may be subject to Federal flood insurance requirements. Federally regulated lenders are required by law to determine if the structure is located in a SFHA and must provide the buyer with written notice that flood insurance will be required. For more information on FEMA's flood mapping and National Flood insurance Program (NFIP) go to www.floodsmart.gov.

You can also contact the FEMA Flood Map Service Center at (877) 336-2627, or by email at FEMAMapSpecialist@riskmapcds.com.

Return to Quickview

Return to 1 Page NHDTM

Property ID











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

A FEMA Standard Flood Hazard Determination Form (SFHDF) for this property has been included with this report. The SFHDF identifies whether a structure is located in a special flood hazard area, if the borrower is required to obtain flood insurance, and if federal flood insurance is available. Click Here to View

FEMA FLOOD ZONE DESIGNATIONS

A, AE, AH, AO, AR, A1-A30, A99	Special Flood Hazard Area (SFHA): Areas of 100-Year flood
V, V1-V30, VE	Coastal SFHA: Areas of 100-Year coastal flood
ACC, ACB, AEC*, AC*	Contained Flooding: Areas where flooding is contained by a flood control measures such as a channel (ACC) or basin(ACB). Not an SFHA. While a property may be impacted by an AC* zone, structures on that property will not be impacted. (* represents a wildcard character)
XPL, X500PL	Protected Areas: Areas protected from 100-year flood by levee, dike, or other structure. Not an SFHA.
B, C, X, X500	Non-SFHA: Areas outside of 100-year floodplain or of undetermined flood hazards. Not an SFHA.
D	Not Studied: Areas where no analysis of flood hazards has been conducted, flood hazards are undetermined but possible. Not an SFHA.

Multiple Flood Zones Note: Property I.D.'s research is done for the entire lot. Flood hazard zones do not follow property boundaries, therefore it is possible for your property to be located in more than one zone. In these cases, the report will reflect multiple flood zones. Federally mandated flood insurance is required if any portion of the structure(s) is in a special flood hazard area. To determine your property's flood insurance requirements, please check with your lender or insurance agent.

LOCAL FLOOD PROTECTION PLANNING

For land use planning, some cities and counties have developed and implemented plans to meet the urban level of flood protection, taking into account localized understanding of risk and issues facing local flood protection systems, and defining local flood hazard areas. Updated construction and development regulations may be implemented, potentially affecting project scope, and requiring greater consideration of potential flood hazards, outside of the federally mapped special flood hazard areas. Please check with your local planning department for further information.

Biggert-Waters Flood Insurance Reform Act of 2012 (BW-12)

The Biggert-Waters Flood Insurance Reform Act of 2012 (BW-12) as modified by the Homeowner Flood Insurance Affordability Act of 2014 may cause flood insurance premium rates to increase. Homeowners and business owners are encouraged to learn their flood risk and talk to their insurance agent regarding flood insurance. Insurance companies may require an elevation certificate to offer flood insurance for properties located in Special Flood Hazard Areas (SFHA). A property's seller, builder or developer may have a copy of the elevation certificate, or it may be recorded with a property's deed. The Community Floodplain Manager at the local city or county government office may also have a copy of the elevation certificate. If an elevation certificate is not available, one can be completed with an on-site inspection by a land surveyor, engineer, or architect legally authorized to certify elevation information. For further information on BW-12, go to:

http://www.fema.gov/media-library-data/20130726-1912-25045-9380/bw12 ga 04 2013.pdf

For further information on Elevation Certificates, see:

https://agents.floodsmart.gov/elevation-certificate-fact-sheet

Return to Quickview

Return to 1 Page NHDTM

Property ID











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

FLOOD HAZARD ZONES (continued)

FEMA COMMUNITY RATING SYSTEM

Based on PROPERTY I.D.'s research of the Community Rating System issued by the National Flood Insurance Program (NFIP), the following determination is made:

SUBJECT PROPERTY IS LOCATED IN A COMMUNITY THAT WAS GIVEN A CLASS 7 RATING FOR FLOOD PREPAREDNESS BY THE NFIP. PROPERTIES IN THIS COMMUNITY MAY BE ELIGIBLE FOR DISCOUNTED FLOOD INSURANCE.

DISCUSSION:

The National Flood Insurance Program (NFIP) evaluates entire communities for flood preparedness under their Community Rating System (CRS). (A community's participation in the program does NOT mean the subject property is in a Special Flood Hazard Area; that determination is made separately in this report.)

Communities can achieve higher CRS ratings by using flood management practices that exceed the minimum NFIP standards, with the goal of reducing flood damage. Property owners in a rated community are then eligible for discounted flood insurance according to their community's rate class. Depending on the level of participation, a community earns a class rating from 1 to 10, with class 1 communities being the best prepared. The rating can reduce premiums up to 45% in class 1 communities, with no discounts in class 10 communities. A specific property's discount is then based on the age and elevation of the insured structures, and which flood zone the structure is in.

For more information about the Community Rating System and eligibility, you may contact the FEMA Insurance Services Office by email at nfipers@iso.com, or visit:

https://www.fema.gov/national-flood-insurance-program-community-rating-system

Return to Quickview







5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

DAM FAILURE INUNDATION

NHDS DETERMINATION
AN AREA OF POTENTIAL FLOODING SHOWN ON A DAM FAILURE INUNDATION MAP pursuant to Section 8589.5 of the
Government Code. Yes No X Do not know and information not available from local jurisdiction
NOTE: Due to local dam inundation determination, the NHDS may be marked "Yes" for potential flooding, in contrast with the
OES determination.

Based on PROPERTY I.D.'s research of specific maps or information from the Department of Water Resources, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A DESIGNATED DAM INUNDATION AREA

DISCUSSION:

Dam inundation refers to the area(s) downstream of dams that would flood in the event of a dam failure (breach), or an uncontrolled release of water. Dam failures may be structural, mechanical, or hydraulic in nature, and the flooding, damage, and potential for loss of life caused by said failures, can be much greater than that of a traditional flood from a body of water such as a stream, river, or lake. While the inundation maps outline the extent of damage to life and property that would occur in a worst case scenario, like a complete and sudden dam failure at full capacity, the likelihood of such an event is not disclosed in this report.


In response to Dam Failure Hazards in California, SB 92 and Section 8589.5 of the California Government Code, require dam owners to submit inundation maps to the Department of Water Resources for approval, which will then be used in creation and submittal of Emergency Action Plans to the California Office of Emergency Services. Updated plans and inundation maps must be submitted every 10 years, or sooner under certain conditions.

For more information, please visit the California Department of Water Resources Division of Safety of Dams website at https://www.water.ca.gov/Programs/All-Programs/Division-of-Safety-of-Dams.

Return to Quickview













5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

DAM FAILURE INUNDATION (continued)

USACE RESERVOIRS

Based on PROPERTY I.D.'s research of specific maps or data from the United States Army Corps of Engineers (USACE), the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN OR ADJACENT TO A USACE RESERVOIR

DISCUSSION:


The USACE operates reservoirs to retain water and delay water runoff. In times of heavy rainfall, storms, and other natural events, reservoirs have the potential to overflow and flood the surrounding lands. Dam inundation hazards may also be present in the area(s) downstream of dams that would flood in the event of a dam failure (breach), or an uncontrolled release of water. Dam failures may be structural, mechanical, or hydraulic in nature, and the flooding, damage, and potential for loss of life caused by said failures, can be much greater than that of a traditional flood from a body of water such as a stream, river, or lake. While the likelihood of such an event is not disclosed in this report, proximity to a reservoir is disclosed here.

Note: This determination includes only those reservoirs regulated and/or controlled by the USACE. Some reservoirs under local jurisdiction may not be present in this report.

Return to Quickview

Return to 1 Page NHD™













REPORT #: 4074593

REPORT DATE: 3/24/2025



DISCLOSURE	SOURCE	RESULT	PAGE
High or Very High Fire Zone	State	NOT IN	<u>18</u>
Fire Hazard Severity Zone Rating	State	IN LOW	<u>18</u>
Very High Fire Hazard	City	NOT IN	<u>19</u>
City of Los Angeles Brush Clearance Requirements	City	INCLUDED	<u>19</u>
Wildland Fire Area (SRA)	State	NOT IN	<u>20</u>
Defensible Space Flyer	State	INCLUDED	<u>21</u>
Wildland-Urban Interface Fire Hazard	Federal	NOT IN	<u>22</u>
Wildland-Urban Interface Fire Hazard	State	NOT IN	<u>22</u>
Utility Infrastructure Fire Hazard	State	NOT IN	<u>22</u>
Tree Mortality Fire Hazard	State	NOT IN	<u>23</u>
Firewise USA®	National	INCLUDED	<u>24</u>
Assembly Bill 38 Notice	State	INCLUDED	<u>25</u>
CALFIRE Low Cost Retrofit List	State	INCLUDED	<u>26</u>

Return to Quickview







5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

FIRE HAZARDS

HIGH OR VERY HIGH FIRE HAZARD SEVERITY ZONE

NHDS DETERMINATION A HIGH or VERY HIGH FIRE HAZARD SEVERITY ZONE (FHSZ) as identified by the Director of Forestry and Fire Protection pursuant to Section 51178 of the Government Code or Article 9 (commencing with Section 4201) of Chapter 1 of Part 2 of Division 4 of the Public Resources Code. The owner of this property is subject to the maintenance requirements of Section 51182 of the Government Code. Refer to Report. No X High FHSZ in a state responsibility area Very High FHSZ in a state responsibility area Very High or High FHSZ in a local responsibility area NOTE: California Government Code §51179 provides that a local agency may choose to include or exclude areas from the State identified VHFHSZs in order to provide effective fire protection and fire prevention in the local jurisdiction. This provision allows a local agency, at its discretion, to make changes to the boundaries of VHFHSZs that may not be reflected on maps released by the CDF. In these cases, the NHDS may be marked "Yes" for very high fire in contrast with the CDF determination.

Based on PROPERTY I.D. 's research of the current maps and information issued by the California Department of Forestry and Fire Protection and Los Angeles County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A HIGH OR VERY HIGH FIRE HAZARD SEVERITY ZONE

DISCUSSION:

In an effort to prepare measures to retard the spread of fires, and reduce the potential intensity of uncontrolled fires that could destroy resources, life, or property, the California Department of Forestry and Fire Protection identifies High and Very High Fire Hazard Severity Zones (HFHSZ/VHFHSZ). These areas are classified as such based upon fuel loading, slope, fire history, weather, and other relevant factors. For an area designated as a high or very high fire hazard severity zone, vegetation removal or management must be undertaken for fire prevention or suppression purposes. Other measures may be required, such as the maintenance of fire breaks around the property, clearance of brush and other flammable substances, the provision and maintenance of screens on chimneys and stovepipes, and a prescribed fire retardant roof.

FIRE HAZARD SEVERITY ZONE RATING


Based on PROPERTY I.D. 's research of the maps and information from the California Department of Forestry and Fire Protection, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA WITH A LOW FIRE HAZARD SEVERITY ZONE RATING

Return to Quickview

Return to 1 Page NHDTM

Property ID



5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

FIRE HAZARDS (continued)

DISCUSSION:

Fire hazard severity zone ratings can be used to estimate the potential for impacts on areas susceptible to fire. Impacts are more likely to occur and/or be of increased severity for the higher ratings. These fire hazard severity zone ratings are modeled based on vegetation fuels, terrain, weather, and fire history, and are broken down into four classes as follows: low, moderate, high, and very high.

The determination above is based on preliminary mapping by the California Department of Forestry and Fire Protection, and is provided in this report as supplemental information where comprehensive fire zone maps have not been released. Buyers are strongly encouraged to consult their local Fire, Emergency Services, and/or Building Departments to determine localized fire risk, building codes, and which, if any, local vegetation management ordinances may apply.

NOTE: This section will reflect changes to local responsibility area maps from the Office of the State Fire Marshal (OSFM) as they are released.

LOCAL FIRE HAZARD DETERMINATION(S)

Based on PROPERTY I.D. 's research of specific maps or data for the City of Los Angeles, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A VERY HIGH FIRE HAZARD SEVERITY ZONE

DISCUSSION:

The Director of the California Department of Forestry (CDF) identifies Very High Fire Hazard Severity Zones (VHFHSZ) based on statewide criteria. California Government Code §51179 provides that a local agency may choose to include or exclude areas from the State identified VHFHSZs in order to provide effective fire protection and fire prevention in the local jurisdiction. This provision allows a local agency, at its discretion, to make changes to the boundaries of VHFHSZs that may not be reflected on maps released by the CDF. For these reasons, the NHDS may be marked "Yes" for very high fire.

NOTE: The Fire Safety, Home Hardening, & Defensible Space Form is not included in this Report as the subject property is not located in a high or very high fire hazard severity zone, or in the State Responsibility Area, Wildland Fire Zone.

CITY OF LOS ANGELES BRUSH CLEARANCE REQUIREMENTS

The Los Angeles City Council has approved an ordinance to increase requirements for brush clearance and fire safety in the Very High Fire Hazard Severity Zones (VHFHSZ). This ordinance establishes appropriate safety measures necessary to mitigate the occurrence of such fires. General requirements are below, along with links to the complete list of enforceable Brush Clearance requirements.


Owners of property located in the Very High Fire Hazard Severity Zone (VHFHSZ) shall maintain their property in accordance with the Fire Code (L.A.M.C. 57.322). Year-round compliance shall be maintained as described below on all native brush, weeds, grass, trees and hazardous vegetation within 200 feet of any structures/buildings, whether those structures are on the owner's property or adjoining properties, and within 10 feet of any combustible fence or roadway/driveway used for vehicular travel.

1. Areas within 200 feet of structures and/or 10 feet of roadside surfaces or combustible fence: Grass shall be cut to three inches in height. Native brush shall be reduced in quantity to three inches in height. This does not apply to individual native shrubs spaced a minimum of 18 feet apart, provided such shrubs

Return to Quickview

Return to 1 Page NHDTM

Property ID









5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

FIRE HAZARDS (continued)

are trimmed up from the ground to 1/3 of their height with all dead material being removed (see diagram below).

- 2. For trees taller than 18 feet, trim lower branches so no foliage is within six feet of the ground, and remove all dead material. For trees and shrubs less than 18 feet, remove lower branches to 1/3 of their height, and remove all dead material (see diagram below).
- 3. Trees shall be trimmed up so the foliage is no closer than 10 feet from the outlet of a chimney (see diagram below).
- 4. All roof surfaces shall be maintained free of substantial accumulation of leaves, needles, twigs and any other combustible matter. Maintain five feet of vertical clearance between roof surfaces and portions of overhanging trees (see diagram below).
- 5. All cut vegetation and debris shall be removed in a legal manner. Cut vegetation may be machine processed (i.e., chipped) and spread back onto the property at a depth not to exceed three inches within 30 feet of structures and six inches beyond 30 feet of structures. In addition, spread material shall not be placed within 10 feet of any usable roadside (in accordance with Fire Prevention Bureau Procedure No. 25)

The above general requirements also apply to landscape vegetation.

For further information on the Brush Clearance Requirements, visit the websites below:

LAFD Brush Clearance Requirements Page:

https://www.lafd.org/fire-prevention/brush/brush-clearance-requirements

LAFD Complete List of Clearance Requirements (see "Clearance Requirements" tab): https://vms3.lafd.org/

WILDLAND FIRE (STATE FIRE RESPONSIBILITY AREA)

NHDS DETERMINATION

A WILDLAND AREA THAT MAY CONTAIN SUBSTANTIAL FOREST FIRE RISKS AND HAZARDS pursuant to Section 4125 of the Public Resources Code. The owner of this property is subject to the maintenance requirements of Section 4291 of the Public Resources Code. Additionally, it is not the state's responsibility to provide fire protection services to any building or structure located within the wildlands unless the Department of Forestry and Fire Protection has entered into a cooperative agreement with a local agency for those purposes pursuant to Section 4142 of the Public Resources Code.

No _X_ Yes

Based on PROPERTY I.D. 's research of the current maps issued by the California Department of Forestry and Fire Protection, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A STATE FIRE RESPONSIBILITY AREA/WILDLAND THAT MAY CONTAIN SUBSTANTIAL FOREST FIRE RISKS AND **HAZARDS**

DISCUSSION:

Return to Quickview

Return to 1 Page NHDTM

Property ID

REPORT #: 4074593

REPORT DATE: 3/24/2025



FIRE HAZARDS (continued)

A State Fire Responsibility Area (SRA) is the area where the State of California is financially responsible for the prevention and suppression of wildfires. The SRA does not include lands within incorporated city boundaries or federally owned land.

Pursuant to Assembly Bill X1 29 (ABX1 29), an annual SRA Fire Prevention Benefit Fee is applied to all habitable structures within the SRA. Effective July 1, 2013, the fee was levied at the rate of \$152.33 per habitable structure, to be adjusted annually for inflation. This fee funds fire prevention services in the SRA, such as fuel reduction, defensible space inspections, fire prevention engineering, evacuation planning, fire prevention education, fire hazard mapping, implementation of Fire Plans, and fire-related law enforcement activities. Owners of habitable structures that are also within the boundaries of a local fire protection agency may receive a reduction of \$35 per habitable structure.

With the passing of Assembly Bill 398 (AB 398), the Fire Prevention Fee has been suspended for the 2017-2018 fiscal year, and will remain suspended through January 1, 2031. For the exact text of AB 398, please visit

https://leginfo.legislature.ca.gov/faces/billNavClient.xhtml?bill_id=201720180AB398.

FIRE

If you have questions regarding the Fire Prevention Fee program, or your SRA determination, please contact the Board of Forestry and Fire Protection at PublicComments@bof.ca.gov.

Note: If the property is located in a State Fire Responsibility area, Seller shall, within the time specified, disclose this fact in writing to Buyer (Public Resources Code Section 4136). Government regulations may impose building restrictions and requirements that may substantially impact and limit construction and any remodeling or improvement.

<u>DEFENSIBLE SPACE</u>

WILDFIRE	IS COMING.	
ARE	OU RE	ADY?
		No. of the last
**		ZONE 2
•	ZONE 1	100
N CLIMA		
Defensible Space is your property's front line defense against wildfire. Creating	TWO ZONES MAKE UP THE REQUIRED 100 FEET OF DEFENSIBLE SPACE: ZONE 1: 32 feet of Lean, Clean & Green	A 2
and maintaining defensible space around your home can dramatically increase your	Ennow old dead plants, grass and weeks. Ennow dead or dry leaves and pice needles from your cord, not and not native.	227.00
home's chance of surviving a wildline and improves	Keep two branches 10 feet away from your channey and offer here.	VEETICAL SPACING longe heas do not have to be out and removed
the safety of firelighters defending your property. 100 feet of defensible space	ZONE 2: 30-300 feet of Biodoced Foel Out or now onwel graw down to a maximum height of 4 trebes.	as long as all of the plants beneath them are necessed. This elements is vertical "line leables."
is required by law."	Create herizontal specing lettreen shribs and tree. Create vertical specing between	全体
ONE LESS	gross, shrubs and trees. Use Equipment Property to Keep from Spanking a Wildline	The same of the last
To more information or control planning abstraction of the control	• Alow before 10 e.m., and never on a hor or windy day. String trimmers one a safer option by. Incommonwent for clearing vegetation.	HORIZONTAL SPACING Cream horizontal and vertical spacing between plants, the amount of spacing will depend on how steep the slope is and the size of the plants.
CLICK H	ERE TO VIE	W FLVER

ZONE 1: 30 feet of Lean, Clean & Green	ZONE 2: 30–100 feet of Reduced Fuel	Use Equipment Properly to Keep from Sparking a Wildfire
Remove all dead plants, grass and weeds. Remove dead or dry leaves and pine needles from your yard, roof and rain gutters. Keep tree branches 10 feet away from your chimney and other trees.	Cut or mow annual grass down to a maximum height of 4 inches. Create a horizontal spacing between shrubs and trees. Create vertical spacing between grass, shrubs and trees.	Mow before 10 a.m., and never on a hot or windy day. String trimmers are a safer option (vs. lawnmowers) for clearing vegetation.


Defensible Space is your property's front line defense against wildfire. Creating and maintaining defensible space around your home can dramatically increase your home's chance of surviving a wildfire and improves the safety of firefighters defending your property. 100 feet of defensible space is required by law.

For information on creating defensible space and legal requirements, visit <u>READYFORWILDFIRE.ORG</u>
*NOTE: Your signature on the NHDS Report Receipt page is sufficient to acknowledge delivery/receipt of this information.

Return to Quickview


Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

FIRE HAZARDS (continued)

WILDLAND-URBAN INTERFACE

Based on PROPERTY I.D.'s research of the current maps and information issued by the United States Forest Service, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN THE WILDLAND-URBAN INTERFACE

Based on PROPERTY I.D. 's research of the current maps and information issued by the California Department of Forestry and Fire Protection's Fire Resource and Assessment Program (FRAP), the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN THE WILDLAND-URBAN INTERFACE

DISCUSSION:

The wildland-urban interface (WUI) is the area where structures and other human development meet or intermingle with undeveloped wildland, and is an environment in which fire can move readily between vegetation fuels and structures, increasing the threat to property and human life. As more and more homes are made in woodland settings, they face the very real and growing danger of wildfire. Every year across the country, homes are affected by wildfires. Those that survive the fire almost always do so because their owners had prepared for the eventuality of fire, which is an inescapable force of nature in fire-prone wildland areas. Living in a Wildland-Urban interface zone comes with some added need for understanding of fire dangers, and preparedness methods to protect your home and family.

Wildland Urban Intermix: Areas where structures and wildland vegetation directly intermingle Wildland Urban Interface: Areas with sparse or no wildland vegetation in close proximity to dense wildland vegetation

Wildfire Influence Zone: Wildland vegetation up to 1.5 miles from Interface or Intermix

For more information on Wildfire protection and preparedness, please visit the following websites from CAL FIRE:

http://www.readyforwildfire.org/

https://osfm.fire.ca.gov/divisions/wildfire-planning-engineering/wildland-hazards-building-codes/

https://www.fire.ca.gov/dspace

CPUC UTILITY ASSOCIATED FIRE THREAT

Based on PROPERTY I.D. 's research of the current maps issued by the California Public Utilities Commission (CPUC) and the California Department of Forestry and Fire Protection, the following determination is made:


SUBJECT PROPERTY IS NOT LOCATED IN THE CPUC HIGH FIRE-THREAT DISTRICT

DISCUSSION:

Return to Quickview

Return to 1 Page NHDTM

Property ID











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

FIRE HAZARDS (continued)

The California Public Utilities Commission (CPUC) has delineated a High Fire-Threat District (HFTD) designed specifically for the purpose of identifying areas where there is an increased risk for utility associated wildfires. Within the HFTD, revised and strengthened fire safety regulations have been implemented to further protect people and property from the effects of utility associated wildfires, and provide guidance on how to curtail fire threat during periods of extreme fire conditions.

Further information on the regulations, and the HFTD can be found on the CPUC Fire Threat page at https://www.cpuc.ca.gov/industries-and-topics/wildfires/fire-threat-maps-and-fire-safety-rulemaking.

TREE MORTALITY FIRE THREAT

Based on PROPERTY I.D. 's research of the current maps issued by California Department of Forestry and Fire Protection, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A HIGH HAZARD ZONE

DISCUSSION:

Several consecutive years of drought between 2012 and 2017 in California exacerbated wildfire conditions and precipitated a large outbreak of insects that attacked and killed large areas of conifer and hardwood trees in the Sierra Nevada mountains, and along the coast range in Southern and Northern California. The millions of recently dead trees have created locally increased hazards related to fire and potential falling trees, and greatly impacts public safety and forest health. In addition, the buildup in fuel loadings from higher tree mortality has the potential to increase emissions when wildfires occur. In response to the expanding areas impacted by elevated tree mortality, Governor Brown declared a State of Emergency on October 30, 2015, and established the California Tree Mortality Task Force (now the Tree Mortality Working Group of the Forest Management Task Force). One goal of the task force was to identify and map areas of tree mortality that pose the greatest potential of harm to people and property. These areas, known as High Hazard Zones, are the areas prioritized for tree removal. Tier 1 High Hazard Zones: Areas where tree mortality, caused by drought, coincides with critical infrastructure, including but not limited to roads, utilities, and public schools. They represent a direct threat to public safety and identify areas to be prioritized for hazardous tree removal.

Tier 2 High Hazard Zones: Areas defined by: 1) watersheds (HUC12, average 24,000 acres) that have significant tree mortality combined with community and natural resource assets; or 2) the perimeter of any wildland fire since 2012 (the beginning of the drought). Work at the Tier 2 level addresses the immediate threat of falling trees and fire risk, and supports broader forest health and landscape level fire planning issues. They represent areas to be prioritized for hazard mitigation as well as forest health restoration.

For further information on tree mortality fire threat, visit the California Department of Forestry and Fire Protection's Fire and Resource Assessment Program (FRAP) website at https://www.fire.ca.gov/what-we-do/fire-resource-assessment-program.

Return to Quickview

Return to 1 Page NHDTM

Property ID

Ve have answers



REPORT #: 4074593 | REPORT DATE: 3/24/2025

FIRE HAZARDS (continued)

Firewise USA®

The national Firewise USA program, administered by the National Fire Protection Association (NFPA), helps communities to organize, plan, and mobilize to reduce wildfire risks at the local level, via homeowner education and action, community-wide wildfire risk reduction projects, and regular comprehensive wildfire risk assessments. Communities who engage in active wildfire risk reduction, while meeting specific compliance standards, including full community participation, and creation of defensible space around all homes, can be deemed a Site of Excellence, noting their continued focused approach, and resilience to wildfire.

For more information on the Firewise USA program, visit the following:

https://www.readyforwildfire.org/prepare-for-wildfire/firewise-communities/

https://www.nfpa.org/Education-and-Research/Wildfire/Firewise-USA

To check if your community is part of the Firewise USA program, please view their interactive map at: https://nfpa.maps.arcgis.com/apps/Viewer/index.html?appid=c4a788340df748f18d98d8363145bb67

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

NOTICE OF ASSEMBLY BILL 38: FIRE SAFETY, LOW-COST RETROFITS, REGIONAL CAPACITY REVIEW, WILDFIRE MITIGATION

Assembly Bill 38 (Wood) was signed into law by the Governor on October 2, 2019 and will establish a first ever statewide fire retrofit program to help communities and owners of homes in the fire zones (built prior to updated building codes in 2008), to harden their homes and make them more likely to survive future fires.

According to the California Department of Forestry and Fire Protection (CDF), approximately 2 Million residential structures (one in four homes) in California are located in "high" or "very high" fire hazard severity zones. Based on California's recent wildfires and firestorms, the imminent and pressing need for wildfire prevention and minimization strategies in California prompted the passage of this law.

- Effective January 1, 2020, after completing construction, if Seller receives a final inspection report (where that report covers compliance with home hardening laws), Seller must give a copy of that report to Buyer, or information on where Buyer can get a copy of that report.
- e Effective January 1, 2021, for homes built before 2010, Seller must give Buyer a written notice that includes language on how to harden a home against fire, and a list of features on the property that make the home vulnerable to wildfires and flying embers. The notice must state: "This home is located in a high or very high fire hazard severity zone and this home was built before the implementation of the Wildfire Urban Interface building codes which help to fire harden a home. To better protect your home from wildfire, you might need to consider improvements. Information on fire hardening, including current building standards and information on minimum annual vegetation management standards to protect homes from wildfires, can be obtained on the internet website http://www.readyforwildfire.org." The list of features on the property that make a home vulnerable to wildfires and flying embers include, but are not limited to: Eave, soffit, and roof ventilation where the vents have openings in excess of one-eighth of an inch or are not flame and ember resistant, Roof coverings made of untreated wood shingles or shakes, Combustible landscaping or other materials within five feet of the home and under the footprint of any attached deck, Single pane or non-tempered glass windows, Loose or missing bird stopping or roof flashing, Rain gutters without metal or noncombustible gutter covers.
- Effective July 1, 2021, in a local jurisdiction that has enacted an ordinance requiring the owner of real property to obtain documentation that the property complies with Public Resources Code § 4291 <u>Law section (ca.gov)</u> or a local vegetation management ordinance, Seller must provide Buyer with the documentation and information on the local agency from which a copy of that documentation may be obtained, and Buyer shall comply with that ordinance.
- Effective July 1, 2021, in a local jurisdiction that has NOT enacted an ordinance requiring the owner of real property to obtain documentation that the property complies with Public Resources Code § 4291 Law section (ca.gov) or a local vegetation management ordinance, but a governmental entity, local agency, or other qualified nonprofit entity does provide inspections with documentation in the jurisdiction in which the property is located, Seller shall provide to Buyer documentation stating that the property (within 6 months preceding the sale) is in compliance with state and/or local vegetation management ordinances. If Seller has not obtained documentation of compliance, Seller and Buyer shall enter into a written agreement pursuant to which Buyer agrees to obtain documentation of compliance with Public Resources Code § 4291 Law section (ca.gov) or a local vegetation management ordinance within one year of the date of the close of escrow.
- Effective July 1, 2025, Seller must provide Buyer with a list of low-cost retrofits to harden a home against fire, and Seller must specify which items on the list Seller has completed.

NOTE: The Fire Safety, Home Hardening, & Defensible Space Form is not included in this Report as the subject property is not located in a high or very high fire hazard severity zone, or in the State Responsibility Area, Wildland Fire Zone.

Return to Quickview

Return to 1 Page NHDTM

Property ID

ers





5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025



Low Cost Retrofit List

Low Cost Ways to Harden Your Home

- 1. When it is time to replace your roof, replace it with a Class A fire rated roof. OFSM Wildland Urban Interface (WUI) Products
- 2. Block any spaces between your roof covering and sheathing with noncombustible materials (bird stops).
- 3. Install a noncombustiblegutter cover on gutters to prevent the accumulation of leaves and debris in the gutter.
- 4. Cover your chimney and stovepipe outlets with a noncombustible corrosion resistant metal mesh screen (spark arrestor), with 3/8-inch to 1/2-inch openings.
- 5. Install ember and flame-resistant vents. OFSM Wildland Urban Interface (WUI) Products
- 6. Caulk and plug gaps greater than 1/8-inch around exposed rafters and blocking to preventember intrusion into the attic or other enclosed spaces.
- 7. Inspect exteriorsiding for dry rot, gaps, cracks, and warping. Caulk or plug gaps greater than 1/8-inch in siding and replace any damaged boards, including those with dry rot.
- 8. Install weather-strippingto gaps greater than 1/8-inch between garage doors and door frames to prevent ember intrusion. The weather-strippingmust be compliant with UL Standard 10C.
- 9. When it's time to replace your windows, replace them with multi-paned windows that have at least one pane of tempered glass. OFSM Wildland Urban Interface (WUI) Products
- 10. When it's time to replace your siding or deck, use compliant noncombustible, ignition-resistant, or other OFSM Wildland Urban Interface (WUI) Products
- 11. Cover openings to operable skylights with noncombustible metal mesh screen with openings in the screen not to exceed 1/8-inch.
- 12. Install a minimum 6-inch metal flashing, applied vertically on the exterior of the wall at the deck-to-wall intersection to protect the combustible siding material.

Low-Cost Ways to Create Defensible Space and Enhance the Effects of a Hardened Home

- 1. Regularly clean your roof, gutters, decks, and the base of walls to avoid the accumulation of fallen leaves, needles, and other flammable materials (see Defensible Space Webpage for more details).
- 2. Ensure that all combustible materials are removed from underneath, on top of, or within five feet of a deck.
- 3. Removevegetationor other combustible materials that are within five feet of windows and glass doors.
- 4. Replace wood mulch products within five feet of all structures with noncombustible products such as dirt, stone, or gravel.
- 5. Remove all dead or dying grass, plants, shrubs, trees, branches, leaves, weeds, and pine needles within 30 feet of all structures or to the propertyline.
- 6. Ensure exposed firewood is stored at least 30 feet away from structures or completely covered in a fire-resistant material that will not allow embers to penetrate. Additionally, make sure you have 10 feet of clearance around your wood piles.
- 7. Be sure to store combustible outdoor furnishings away from your home when not in use.
- 8. Rememberto properly store retractable awnings and umbrellas when not in use so they do not collect leaves and embers.


*This list was developed as a best practices guide and to assist homeowners to ensure their home is more ignition-resistant from wildfires. Low cost can be subjective. Some of these items are based on upgrading to more stringent materials when that feature is up for replacement due to normal maintenance or lifespan, i.e. roofs.

Updated 2/17/2022

Return to Quickview


Return to 1 Page NHDTM

Property ID











SEISMIC

5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

SEISMIC

DISCLOSURE	SOURCE	RESULT	PAGE
Alquist-Priolo Fault Zone	State	NOT IN	<u>27</u>
Earthquake Faults	Federal	NOT WITHIN 1/4 MILE	<u>28</u>
Earthquake Faults	State	NOT WITHIN 1/4 MILE	<u>28</u>
Earthquake Faults	County	WITHIN 1/4 MILE	<u>28</u>
Ground Shaking	State	IN VIOLENT	<u>29</u>
Earthquake-Induced Liquefaction	State	NOT IN	<u>30</u>
Earthquake-Induced Liquefaction	State	IN	<u>30</u>

EARTHQUAKE FAULT ZONES

NHDS DETERMINATION

AN EARTHQUAKE FAULT ZONE pursuant to Section 2622 of the Public Resources Code. Yes ___ No _X_

Based on PROPERTY I.D.'s research of maps or data obtained from the State of California in accordance with the Alquist-Priolo Earthquake Fault Zone Act, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN ALQUIST-PRIOLO EARTHQUAKE FAULT ZONE

DISCUSSION:


If the Subject Property is partially or wholly within an OFFICIAL EARTHQUAKE FAULT ZONE, it may be subject to (city, county, or state) requirements necessitating geologic study prior to any new or additional construction. When a property is located in this zone, it may not mean that a fault line exists on the property. In certain areas, the zones around the faults being studied are more than one-quarter of a mile wide.

Earthquake Fault Zones are delineated and adopted by the State of California as part of the Alquist-Priolo Earthquake Fault Zone Act of 1972 to assure that homes, offices, hospitals, public buildings, and other structures for human occupancy are not built on active faults. Earthquake Fault Zones are areas on both sides of known or suspected active earthquake faults. The State Mining and Geology Board has adopted policies and criteria for implementing the zones.

Return to Quickview

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

EARTHQUAKE FAULT ZONES (continued)

ADDITIONAL SOURCES

Based on PROPERTY I.D.'s research of maps or data obtained from the United States Geological Survey, following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A MAPPED FAULT

Based on PROPERTY I.D.'s research of specific maps and/or information from the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A MAPPED FAULT

Based on PROPERTY I.D.'s research of specific maps or data for Los Angeles County, the following determination is made:

SUBJECT PROPERTY IS LOCATED WITHIN 1/4 MILE OF A MAPPED FAULT, INCLUDING THE FOLLOWING:

· SANTA MONICA FAULT - POTENTIALLY ACTIVE

DISCUSSION:

As a part of long-term planning, localities are required to include mapping of known seismic or other geologic hazards on a local level. Information may vary between jurisdictions, and may include information about all locally-known seismic hazard zones, including an area's susceptibility to strong ground shaking, liquefaction, landslides or other ground failure.

The absence of earthquake activity at a particular location does not necessarily mean that earthquakes will not occur there in the future. Moderate to large earthquakes have often been preceded by or followed by long periods of quiescence. The apparent correlation between seismic activity and mapped faults should confine the areas of higher probability of earthquake occurrence to somewhat restricted zones.

Fault rupture can occur during moderate to large earthquakes and is a function of magnitude and the total length of the fault. Fault rupture accounts for only a small percentage of earthquake damage and may be rapid and sudden, as with a major earthquake, or can occur over an extended period of time.

DEFINITIONS:

For fault disclosures that contain fault activity information, the definitions below describe these activity designations.

Active - "Active" faults are defined as faults that have been active within the last 0 to 11,000 years.

Potentially Active - "Potentially Active" faults are defined as faults that may have been active between 11,000 years and 500,000 years ago.

Conditionally Active - "Conditionally Active" faults are defined as faults that may have had activity 750,000 years ago or uncertain activity.

Return to Quickview


Return to 1 Page NHD™

Property ID









REPORT #: 4074593 REPORT DATE: 3/24/2025

EARTHQUAKE GROUND SHAKING

Based on PROPERTY I.D.'s research of maps and data from the California Integrated Seismic Network (CISN), the following determinations are made:

SUBJECT PROPERTY IS LOCATED IN AN AREA SUBJECT TO VIOLENT GROUND SHAKING AND HEAVY DAMAGE TO PROPERTY (MM IX) IN POTENTIAL EARTHQUAKE SCENARIOS

MODIFIED MERCALLI (MM) INTENSITY SCALE - POTENTIAL SHAKING AND DAMAGE **LEVELS**

- IV. Light Shaking, Minimal Damage: Hanging objects swing, vibration like heavy trucks passing, windows and doors rattle
- V. Moderate Shaking, Minimal Damage: Pictures move, liquids disturbed, sleepers awakened
- VI. Strong Shaking, Nonstructural Damage: Objects fall, felt by all, pictures may fall off walls, shrubbery shakes
- VII. Very Strong Shaking, Moderate Damage: Difficult to stand, some cracks in plaster, some damage to unreinforced masonry buildings
- VIII. Severe Shaking, Moderate-Heavy Damage: Critical or extensive damage to stone buildings, steering of cars affected, fall of stucco and some masonry walls, fall of chimneys, homes move if on weak foundations
- IX. Violent Shaking, Heavy Damage: Potential collapse of masonry buildings, many homes shifted off foundations, frames racked, underground pipes broken

DISCUSSION:

Ground Shaking studies provide a prediction of what may happen in future earthquakes, including what kind of damage can occur and what types of soils will have problems. As a prediction, the information from Ground Shaking studies provide a generalized view of what can occur during a large earthquake, but specific damage to specific buildings cannot be predicted. Loose, soft, recently deposited soils are the most susceptible to ground shaking amplification, and other hazards associated with seismic activity.

Ground shaking hazards exist throughout California. The potential damages in strong earthquake scenarios range from minimal to extreme, with corresponding shaking severity ranging from very weak to very violent. Seismologists modeled various ground shaking scenarios for active faults to highlight the hazards shaking can present in a strong earthquake.


For further information about the CISN:

http://www.cisn.org/ and http://www.cisn.org/shakemap/sc/shake/about.html

Return to Quickview

Return to 1 Page NHDTM

Property ID





SEISMIC

5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

LIQUEFACTION SUSCEPTIBILITY

NHDS DETERMINATION

A SEISMIC HAZARD ZONE pursuant to Section 2696 of the Public Resources Code.

Yes (Landslide Zone) ____ Yes (Liquefaction Zone) ____ No _X_ Map not yet released by state ____

Based on PROPERTY I.D.'s research of the current maps and information issued by the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIALLY DESIGNATED LIQUEFACTION HAZARD ZONE

Note: Additional / local determination(s) below, when listed, may differ from the seismic hazard determination found in the Natural Hazard Disclosure Statement ("NHDS"). Differentiation can occur because the determination made in the NHDS is based on maps prepared by the California Geologic Survey in accordance with the State Seismic Hazard Mapping Act, while the determinations below are based on official maps prepared for another mapping program.

ADDITIONAL SOURCES

Based on PROPERTY I.D.'s research of specific maps from the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA OF LIQUEFACTION (POTENTIALLY LIQUEFIABLE SOILS)

DISCUSSION:

Liquefaction is the sudden loss of soil strength resulting from shaking during an earthquake. The effect on structures and buildings can be devastating, and is a major contributor to urban seismic risk. Areas most susceptible to liquefaction are underlain by non-cohesive soils, such as sand and silt, that are saturated by groundwater typically between 0 and 30 feet below the surface. State and local governments use this information in creating and updating their hazard mitigation plans and to delineate geologically hazardous areas.

Mapped liquefaction areas are those where historic occurrence of liquefaction, or local geological, geotechnical conditions indicate a potential for permanent ground displacement such that mitigation as defined in Public Resources Code Section 2693(c) would be required. Section 2693(c) defines "mitigation" to mean those measures that are consistent with established practice and that will reduce seismic risk to acceptable levels.

Note: The map upon which this determination is based may not show all areas that have the potential for liquefaction or other earthquake and geologic hazards. Also, a single earthquake capable of causing liquefaction may not uniformly affect the entire area. Liquefaction zones may also contain areas susceptible to the effects of earthquake induced landslides. This situation typically exists at or near the toe of existing landslides, down slope from rock fall or debris flow source areas, or adjacent to steep stream banks.

Return to Quickview


Return to 1 Page NHDTM

Property ID











GEOLOGIC

5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

GEOLOGIC

DISCLOSURE	SOURCE	RESULT	PAGE
Landslide Hazard Zones	State	NOT IN	<u>31</u>
Landslide Deposits	Federal	NOT IN	<u>31</u>
Landslide Inventory	State	NOT IN	<u>31</u>
Expansive Soils	Federal	IN UNMAPPED AREA	<u>33</u>
Soil Subsidence/Settling Earth	Federal	NOT IN	<u>33</u>
Wind Erosion	Regional	IN VERY LOW	<u>34</u>
Naturally Occuring Asbestos	State	NOT IN	<u>35</u>

LANDSLIDE SUSCEPTIBILITY

NHDS DETERMINATION

A SEISMIC HAZARD ZONE pursuant to Section 2696 of the Public Resources Code. Yes (Liquefaction Zone) _ Yes (Landslide Zone) ____ No <u>X</u>_ Map not yet released by state

Based on PROPERTY I.D.'s research of the current maps and information issued by the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN OFFICIALLY DESIGNATED EARTHQUAKE-INDUCED LANDSLIDE HAZARD ZONE

Note: Additional / local determination(s) below, when listed, may differ from the seismic hazard determination found in the Natural Hazard Disclosure Statement ("NHDS"). Differentiation can occur because the determination made in the NHDS is based on specific maps prepared by the California Geological Survey (State Seismic Hazard Mapping Act), while the determination(s) below are based on different official maps and/or information.

ADDITIONAL SOURCES


Based on PROPERTY I.D.'s research of maps and/or information obtained from the United States Geological Survey (USGS), the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A LANDSLIDE AREA

Return to Quickview

Return to 1 Page NHDTM

Property ID











GEOLOGIC

REPORT #: 4074593 | REPORT DATE: 3/24/2025

LANDSLIDE SUSCEPTIBILITY (continued)

Based on PROPERTY I.D.'s research of specific maps or data from the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA OF IDENTIFIED EARTH MOVEMENT

DISCUSSION:

Landslides and other ground failures may occur during earthquakes, triggered by the strain induced in soil and rock by the ground shaking vibrations, and during non-earthquake conditions, most frequently during the rainy season. Both natural and man-made factors contribute to these slope failures.

Although landslides due to slope failure are most frequent in "wet years" with above-average rainfall, they can occur at any time. The presence or absence of deep-rooted vegetation; surface and subsurface drainage conditions; thickness and engineering characteristics of soils and underlying weathered, partially-decomposed rock; orientation of bedding or locally-high rainfall can all affect slope stability.

The influence of bedrock lithology, steepness of slope, and rates of erosion, at the very least, must all be considered to generate an accurate susceptibility map. Any slope can be rendered unstable by construction activities and almost any unstable slope can also be mitigated by accepted geotechnical methods.


Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

SOIL HAZARDS

EXPANSIVE SOILS

Based on PROPERTY I.D.'s research of specific maps or data from the United States Department of Agriculture Natural Resources Conservation Service, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA NOT MAPPED FOR EXPANSIVE SOILS

DISCUSSION:

Shrink/Swell Potential or Soil Expansivity is the relative change in volume to be expected with changes in moisture content, that is, the extent to which the soil shrinks as it dries out or swells when it gets wet. Shrinking and swelling of soils can cause damage to building foundations, roads and other structures. Soil expansivity can cause damage due to differential settlement and could progressively deteriorate structures over time. As such, stricter construction and development requirements may apply that could affect building materials and standards used, including, but not limited to depth of footings, slab thickness and rebar installation. Structures located on expansive soils can experience more hairline cracks in the walls and slabs, however certain precautions can be taken in order to minimize cracking. These precautions include proper drainage after rain, installation of gutters and downspouts to direct water away from the structure, maintaining a uniform moisture condition around foundations, repairing any plumbing leaks, refraining from planting trees within approximately ten feet of the structure because trees tend to extract moisture in soil causing shrinkage, and contacting a soils engineer who specializes in expansive soils matters.

SUBSIDENCE

Based on PROPERTY I.D.'s research of specific maps or data from the United States Geological Survey (USGS), the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA OF IDENTIFIED SOIL SUBSIDENCE


DISCUSSION:

Subsidence is the gradual settling or sinking of the earth's surface with little or no horizontal motion due to the loss of solids or liquids from the subsurface. The compaction of alluvium and settling of the land surface is a process that occurs over several years, except when prompted by seismic shaking. Subsidence can cause property damage and could progressively deteriorate structures over time. As such, stricter construction and development requirements may apply that could affect building materials and standards used. Structures may experience more hairline cracks in the walls and slabs. Inundation or flooding may also be a secondary effect of subsidence.

Return to Quickview


Return to 1 Page NHDTM

Property ID











GEOLOGIC

REPORT #: 4074593 | REPORT DATE: 3/24/2025

WIND EROSION AND BLOWN SAND

Based on PROPERTY I.D.'s research of specific maps or data obtained from the Southern California Association of Governments, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA WITH VERY LOW SUSCEPTIBILITY TO WIND EROSION


DISCUSSION:

Wind erosion most commonly occurs when barren sand or sandy loam soils are exposed to high wind in the absence of moisture. Human activity can increase wind erosion by disrupting soil formations and compaction, disturbing the stabilizing and wind-breaking effect of dunes, and most significantly, removing surface vegetation and its stabilizing effects. Blown sand, the most severe form of wind erosion, occurs largely due to natural conditions. Blown sand can cause significant damage to property, and also results in the nuisance and expense of removing sand from roadways and other property. Additionally, blown sand introduces a high level of suspended particulates into the air, and can create respiratory problems due to poor air quality.

Return to Quickview















GEOLOGIC

REPORT #: 4074593 | REPORT DATE: 3/24/2025

NATURALLY OCCURRING ASBESTOS

Based on PROPERTY I.D.'s research of current maps and/or information issued by the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA LIKELY TO CONTAIN NATURALLY OCCURRING ASBESTOS


DISCUSSION:

Natural asbestos commonly occurs in association with altered ultramafic rocks, including serpentinite or serpentine - the California state rock. State and federal officials consider all types of asbestos to be hazardous because asbestos is a known carcinogen. Wind and water can carry asbestos fibers, and certain human activities such as mining, grading, quarrying operations, construction or driving over unpaved roads or driving on a road paved in part with asbestos-bearing rock, can release dust containing asbestos fibers. As with any other potential environmental hazard, it is recommended that Buyers fully investigate and satisfy themselves as to the existence of exposed naturally occurring asbestos / serpentine rock on the Property or within its vicinity or any serpentine-surfaced roads within the vicinity of the Property and the hazards, if any, posed thereby. That investigation should include consulting with appropriate expert(s) who can identify and test any exposed naturally occurring asbestos / serpentine rock on the Property or within its vicinity to determine whether it may present a health risk to Buyers. Buyers are encouraged to review all relevant information resulting from these studies and other information pertaining to the risk of exposure to harmful forms of naturally occurring asbestos fibers prior to removing their inspection contingency. Exposure to asbestos may create a significant health risk, and the presence of asbestos-bearing minerals may result in restrictions on the use or development of the Property. You should consider the potential risks associated with the Property before you complete your purchase and determine whether they are acceptable to you.

Return to Quickview















OIL & GAS

REPORT #: 4074593 | RE

REPORT DATE: 3/24/2025

I OIL & GAS

DISCLOSURE	SOURCE	RESULT	PAGE
Oil and Gas Wells	State	NOT WITHIN 500 FEET, BUT WITHIN 1/2 MILE,	<u>36</u>
Oil and Gas Field Administrative Boundary	State	NOT WITHIN	<u>36</u>
Natural Gas Storage Facilities	Federal	NOT WITHIN 2 MILES	<u>37</u>
Radon Gas	State	IN LOW	<u>38</u>
Methane Gas	County	NOT IN	<u>39</u>
Methane Producing Landfill	County	NOT WITHIN 1000 FEET	<u>39</u>
Methane Gas	City	NOT IN	<u>39</u>
Oil and Gas Industrial Area	County	NOT IN	<u>40</u>

OIL AND GAS WELL PROXIMITY

Based on PROPERTY I.D.'s research of specific maps or data from the California Dept. of Conservation, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN THE ADMINISTRATIVE BOUNDARY OF AN OIL AND GAS FIELD

SUBJECT PROPERTY IS NOT LOCATED WITHIN 500 FEET, BUT IS LOCATED WITHIN 1/2 MILE, OF AN IDENTIFIED OIL OR GAS WELL, ACTIVE OR ABANDONED, INCLUDING THE FOLLOWING:

UNION OIL COMPANY OF CALIFORNIA PLUGGED DRY HOLE


DISCUSSION:

Abandoned oil and gas wells dot the landscape of California. Identified wells have been mapped and are monitored by the California Department of Conservation; and are generally regulated by State and Local agencies. While abandoned wells that are properly capped and monitored present a low hazard risk, improper capping or plugging of abandoned wells can lead to a variety of problems. Improperly capped wells can release noxious chemicals into the air, or allow chemicals to leach into groundwater. Abandoned oil and gas wells are prone to buildup of methane gas which can create an explosion hazard if not properly monitored and cleaned. Improperly capped wells can lead to sinkhole development. Wells

Return to Quickview

Return to 1 Page NHD™

Property ID











OIL & GAS

5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

OIL AND GAS WELL PROXIMITY

(continued)

can pose a serious threat to the safety of humans, especially children, and to animals. Administrative field boundaries roughly outline the areal extent of an oil or gas field. Questions of jurisdiction and responsibility in regards to capping and maintenance of abandoned wells may exist.

For more information regarding abandoned oil and gas wells in California, contact the following agencies: State of California Dept. of Conservation - Geologic Energy Management Division:

https://www.conservation.ca.gov/calgem/Pages/Index.aspx

California Environmental Protection Agency: http://www.calepa.ca.gov

Note: This hazard determination only identifies properties in proximity to abandoned wells that have been mapped by the California Department of Conservation. Unmapped abandoned wells that are not identified in this disclosure could exist on or near the Subject Property. Unmapped and unidentified wells can pose a greater risk to health and safety as they are not monitored and may not have received the appropriate mitigation measures.

NATURAL GAS STORAGE FACILITIES

Based on PROPERTY I.D.'s research of specific maps or data from the U.S. Energy Information Administration (EIA), the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 2 MILES OF A NATURAL GAS STORAGE FACILITY

DISCUSSION:

Natural Gas Storage Facilities are present throughout the United States. Most commonly, natural gas is held in underground storage facilities in depleted reservoirs in oil and/or natural gas fields, aquifers, or salt cavern formations. Natural gas can also be stored in liquid or gaseous form in above-ground tanks. Generally, these facilities are in proximity to consumption centers, and take advantage of existing infrastructure found at depleted fields. The ability to quickly deliver gas to areas in need, and store large amounts of inventory to meet fluctuating demand, are important features of these facilities. Underground gas storage facilities in California are regulated by the California Geologic Energy Management Division (CalGEM), helping to maintain safe storage operations throughout the state.

For further information on Natural Gas, and Natural Gas storage, visit the following agency websites:

U.S. EIA: https://www.eia.gov/energyexplained/natural-gas/delivery-and-storage.php

CalGEM: https://www.conservation.ca.gov/calgem/Pages/UndergroundGasStorage.aspx

CPUC: https://www.cpuc.ca.gov/industries-and-topics/natural-gas/natural-gas-and-california

Return to Quickview







OIL & GAS

REPORT #: 4074593 | REPORT DATE: 3/24/2025

RADON GAS POTENTIAL

Based on PROPERTY I.D.'s research of specific maps or data from the California Geological Survey, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA WITH LOW POTENTIAL FOR INDOOR RADON LEVELS ABOVE 4.0 PICOCURIES PER LITER

DISCUSSION:

Radon is a naturally occurring colorless, odorless radioactive gas formed by the natural disintegration of uranium in soil, rock and ground water as it radioactively transmutes to form stable lead.

Radon gas forms from the decay of radioactive elements at depth. Air pressure inside a building is usually lower than pressure in the soil around the building's foundation. Because of this difference in pressure, buildings can act like a vacuum, drawing radon in through foundation cracks and other openings. As cracks develop in rocks, radon gas can rise into the local ground water and may also be present in well water and can be released into the air in buildings when water is used for showering and other household uses. In most cases, radon entering a building through water is a small risk compared with radon entering a building from the soil. In a small number of homes, the building materials can give off radon, although building materials alone rarely cause radon problems. The Surgeon General has warned that radon is the second leading cause of lung cancer in the United States. Only smoking causes more lung cancer deaths. Smokers that live in homes with high radon levels, are at an especially high risk for developing lung cancer.

The U.S. Environmental Protection Agency's (EPA) action level for indoor radon levels is 4 pCi/L, at which homes should be fixed. Even at lower levels Radon can still be dangerous, so the EPA recommends homeowners consider fixing their homes when the radon levels are between 2 pCi/L and 4 pCi/L.

The only way to determine radon levels for a specific property is by testing. For further information about radon testing and mitigation, contact the following:

California Department of Public Health:

https://www.cdph.ca.gov/Programs/CEH/DRSEM/Pages/EMB/Radon/Radon.aspx

National Environmental Health Association (NEHA): http://www.neha.org National Environmental Radon Safety Board (NRSB): http://www.nrsb.org

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

METHANE GAS ZONE

Based on PROPERTY I.D.'s research of specific maps or data for Los Angeles County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA OF KNOWN SHALLOW METHANE ACCUMULATION

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1000 FEET OF AN IDENTIFIED METHANE PRODUCING DISPOSAL SITE

Based on PROPERTY I.D.'s research of specific maps or data for the City of Los Angeles, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A METHANE GAS ZONE

DISCUSSION:

Properly venting or shielding areas and/or buildings from probable methane gas seepage can safely redirect the gas into the atmosphere.

Single Family Dwellings (Existing & New Construction): Except as described below, if the property is in a potential or high potential methane gas zone, all single family dwellings with basements should have a gas-detection system installed which is periodically calibrated and maintained in proper condition in accordance with manufacturer's installation and maintenance specifications.

Exception (Existing Construction): If the property is in a (i) potential methane gas zone, dwellings on raised foundations - having basements open above ground level on at least three sides (where the openings are to a suitably ventilated underfloor area) - are not required to have a gas detection system installed. If the property is in a (ii) high potential methane gas zone, dwellings on raised foundations - having basements open above ground level on at least two sides (where the openings are to a suitably ventilated underfloor area) - are not required to have a gas detection system installed.

Multiple Residential Buildings: If the property is in a potential or high potential methane gas zone, all multiple residential buildings shall have adequate ventilation or a gas-detection system installed in basements or on the lowest level on grade, and within the underfloor space of buildings with raised foundations.

Los Angeles County methane gas policy includes special regulations for properties within 1,000 ft of methane producing disposal sites. According to the county building code, "permits shall not be issued for buildings or structures regulated by this code within 1,000 ft of fills containing rubbish or other decomposable materials unless the fill is isolated by natural or artificial protective systems...." If your property is found to be located in a methane hazard zone, or within 1,000 ft of a methane producing landfill, certain building restrictions may be placed on your property. For further information, please contact the Los Angeles County Dept of Public Works at (626)458-5100.

[Los Angeles County Code-Title 26, Ordinance 110.3 and Ordinance 110.4]


For further information on the City of Los Angeles Methane Mitigation Standards, visit

https://www.ladbs.org/services/core-services/plan-check-permit/methane-mitigation-standards.

Return to Quickview

Return to 1 Page NHDTM


Property ID











REPORT #: 4074593 | REPORT DATE: 3/24/2025

PETROCHEMICAL COMPLEX PROXIMITY

Based on PROPERTY I.D.'s research of specific maps or data for Los Angeles County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A PETROCHEMICAL COMPLEX AREA

DISCUSSION:

The hazard associated with petrochemical complex areas is the susceptibility to destructive post-earthquake fires. In areas of poor soil conditions or where pipelines cross active faults and liquefiable sediments, the hazard potential is significant, but can be mitigated with sufficient emergency response after an earthquake.

A petrochemical complex area may include active and abandoned oil fields, offshore oil production sites, tanks farms, and refineries. These facilities can pose a hazard due to the presence of volatile gas and solid waste on site.

Return to Quickview















NOISE

5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

MOISE

DISCLOSURE	SOURCE	RESULT	PAGE
Airport Influence Area	County	NOT IN	<u>41</u>
Airport Vicinity	Federal	WITHIN 2 MILES	<u>41</u>
SoCal Metroplex Airspace Optimization Notice Area	Federal	IN	<u>42</u>
Railroads	State	NOT WITHIN 1/4 MILE	<u>43</u>

AIRPORT PROXIMITY

AIRPORT INFLUENCE AREA

Based on PROPERTY I.D.'s research of specific maps or data obtained from local land use commissions, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AIRPORT INFLUENCE AREA

AIRPORT VICINITY

Based on PROPERTY I.D.'s research of specific maps or data from the Federal Aviation Administration (FAA) and the U.S. Department of Transportation, the following determination is made:

SUBJECT PROPERTY IS LOCATED WITHIN 2 MILES OF AN FAA APPROVED LANDING FACILITY:

- · ABC-TV HELIPORT (PRIVATE)
- · CHILDRENS HOSPITAL LOS ANGELES HELIPORT (PRIVATE)
- · CHILDRENS HOSPITAL OF LOS ANGELES HP
- · CHILDRENS HOSPITAL OF LOS ANGELES HP 2
- · CHILDREN'S HOSPITAL OF LOS ANGELES II HELIPORT (PRIVATE)
- QUEEN OF ANGEL-HOLLYWOOD PRESBYTERIAN HOS HELIPORT (PRIVATE)


DISCUSSION:

NOTICE OF AIRPORT IN VICINITY - Pursuant to Section 1103.4 of the Civil Code: If the above-referenced property is located in the vicinity of an airport, within what is known as an Airport Influence Area, the property may be subject to some of the annoyances or inconveniences associated with proximity to airport operations, such as noise, vibration, or odors. Per the California Code of Regulations Section 5006, the level of noise acceptable to a reasonable person residing in the vicinity of an airport is established as a community noise equivalent level (CNEL) value of 65 dB. This criterion level

Return to Quickview


Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

AIRPORT PROXIMITY

(continued)

has been chosen for reasonable persons residing in urban residential areas where houses are of typical California construction and may have windows partially open. Individual sensitivities to those annoyances can vary from person to person. You may wish to consider what airport annoyances, if any, are associated with the property before you complete your purchase and determine whether they are acceptable to you.

SOCAL METROPLEX AIRSPACE OPTIMIZATION NOTICE

The Next Generation Air Transportation System (NextGen) is the FAA-led modernization of America's air transportation system to make flying even safer, more efficient, and more predictable. As part of NextGen, the SoCal METROPLEX Project means to improve the efficiency of airspace in the Southern California Metroplex by optimizing aircraft arrival and departure procedures, which may involve changes in aircraft flight paths and altitudes in certain areas. While further ground disturbance, or increases in the number of aircraft operations within the Southern California airspace are not projected, some areas may experience changes in overflight frequency.

The following airports are part of the project: Bob Hope (Burbank) Airport (BUR), Camarillo Airport (CMA), McClellan-Palomar Airport (Carlsbad) (CRQ), Fullerton Municipal Airport (FUL), Los Angeles International Airport (LAX), Long Beach Airport (Daugherty Field) (LGB), Camp Pendleton MCAS (Munn Field) Airport (NFG), Point Mugu Naval Air Station (NTD), North Island Naval Air Station (NZY), Ontario International Airport (ONT), Oxnard Airport (OXR), Palm Springs International Airport (PSP), San Diego International Airport (SAN), Santa Barbara Municipal Airport (SBA), Brown Field Municipal Airport (SDM), Santa Monica Municipal Airport (SMO), John Wayne-Orange County Airport (SNA), Jacqueline Cochran Regional Airport (TRM), Bermuda Dunes (UDD), Miramar Marine Corps Air Station (NKX) and Van Nuys Airport (VNY).

For more information on the SoCal METROPLEX Project, visit

http://www.metroplexenvironmental.com/socal_metroplex/socal_introduction.html

For community involvement updates, and current news affecting specific airports, please see the following:

Ontario: https://www.faa.gov/air_traffic/community_involvement/ont/

Southern California: https://www.faa.gov/air_traffic/community_involvement/socal/

Note: In some instances the location of an airport facility's property line was not made available by the FAA. In those cases the FAA-designated central point of the facility was used as the center for the two mile proximity determination.

Return to Quickview

Return to 1 Page NHDTM







NOISE

5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

NOISE HAZARDS

Based on PROPERTY I.D.'s research of specific maps or data from the United States Department of Transportation and local rail services, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A RAIL LINE


DISCUSSION:

Prolonged and excessive noise can affect both physiological and psychological well-being. In addition to causing hearing loss, noise can interfere with activities such as communication, sleep, and thought. Detrimental effects can start at average noise levels as low as 55 decibels (dB), where noise can be a source of annoyance for many, with increasing problems at higher levels. Continued exposure at average levels of 70dB or more can lead to hearing loss. Attention to noise in community planning and through noise ordinances is designed to minimize noise attenuation along major regional/arterial streets and rail lines. Noise ordinances may deal with zoning, site design, architectural standards, barriers, or street materials. These effort are designed to minimize the increase in ambient noise levels, the spread of noise producing activities into formerly quiet areas, and the negative impact of noise on human health and amenity.

Return to Quickview

Return to 1 Page NHD™













REPORT #: 4074593

REPORT DATE: 3/24/2025

A LAND USE

DISCLOSURE	SOURCE	RESULT	PAGE
Mining Operations	State	NOT WITHIN 1 MILE	<u>45</u>
Abandoned Mining Operations	State	NOT WITHIN 1 MILE	<u>45</u>
Mine Sites	Federal	NOT WITHIN 1/4 MILE	<u>45</u>
Former Military Facilities (FUDS)	Federal	NOT WITHIN 1 MILE	<u>47</u>
Military Facilities	Federal	NOT WITHIN 1 MILE	<u>47</u>
Methane Producing Landfill	County	NOT WITHIN 1000 FEET	<u>49</u>
Landfills (SWIS)	State	NOT WITHIN 3 MILES	<u>49</u>
Landfills (Envirostor)	State	NOT WITHIN 3 MILES	<u>49</u>
Landfills (Geotracker)	State	NOT WITHIN 3 MILES	<u>49</u>
Landfills (RCRA)	State	NOT WITHIN 3 MILES	<u>49</u>
Industrial/Commercial Land Use	City	IN	<u>51</u>
Industrial/Commercial Zoning	City	IN	<u>51</u>
Industrial / Commercial Use	Regional	IN	<u>51</u>
Historic-Cultural Monuments	City	NOT IN	<u>53</u>
Historic Preservation Overlay Zones	City	NOT IN	<u>53</u>
Historical Significance Notice	State	INCLUDED	<u>54</u>
Critical Habitats	Federal	NOT IN	<u>55</u>
Protected Species / Habitats in Proximity	Federal	NOT IN	<u>55</u>

Return to Quickview

Return to 1 Page NHDTM

Property ID









5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

A LAND USE

DISCLOSURE	SOURCE	RESULT	PAGE
Protected Species / Habitats in Proximity	State	IN	<u>55</u>
Right to Farm	State	NOT WITHIN ONE MILE	<u>57</u>

NOTICE OF MINING OPERATIONS

Based on PROPERTY I.D.'s research of specific maps or data from the Division of Mines and Reclamation (DMR) at the Department of Conservation, pursuant to Section 2207 of the Public Resources Code, the following determinations are made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1 MILE OF MINING OPERATIONS

Based on PROPERTY I.D.'s research of specific maps or data from the Division of Mines and Reclamation's Abandoned Mine Lands Unit, the following determinations are made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1 MILE OF ABANDONED MINING OPERATIONS

Based on PROPERTY I.D.'s research of specific maps or data from the United States Geological Survey (USGS), the following determinations are made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1/4 MILE OF A MINE SITE IDENTIFIED BY THE U.S. GEOLOGICAL SURVEY

Return to Quickview











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

NOTICE OF MINING OPERATIONS (continued)

DISCUSSION:

If this property is located within one mile of a mine operation for which the mine owner or operator has reported mine location data to the Department of Conservation pursuant to Section 2207 of the Public Resources Code, then the property may be subject to inconveniences resulting from mining operations. You may wish to consider the impacts of these practices before you complete your transaction.

Mines have been dug and abandoned throughout the State of California. The result is that in the state there are tens of thousands of active and abandoned mines, many unmapped, that can pose inconveniences resulting from mining operations and potential safety, health, and environmental hazards. Sites can possess serious physical safety hazards, such as open shafts or tunnels, and many mines have the potential to contaminate surface water, groundwater.

Further information is available from the following:

Division of Mines and Reclamation: http://www.conservation.ca.gov/dmr

Division of Mines and Reclamation, Abandoned Mine Lands Unit:


http://www.conservation.ca.gov/dmr/abandoned_mine_lands

U.S. Geological Survey: http://minerals.usgs.gov

Return to Quickview













REPORT #: 4074593 | REPORT DATE: 3/24/2025

MILITARY ORDNANCE AND DEFENSE SITES

FUDS PROGRAM SITES

Based on PROPERTY I.D.'s research of specific maps and information issued by the U.S. Army Corps of Engineers from the Defense Environmental Restoration Program Annual Report to Congress, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1 MILE OF A FORMERLY USED DEFENSE SITE

DISCUSSION:

The Defense Environmental Restoration Program-Formerly Used Defense Site Program (DERP-FUDS) was established in 1984 by the United States Army with the mission to protect human health and safety, the environment, and natural resources by removing hazardous material from the environment. The FUDS Program is responsible for all properties that were formerly owned by, leased to, or otherwise possessed by the United States under the jurisdiction of the Department of Defense prior to October 1986, and is executed by the U.S. Army Corps of Engineers. The type of cleanup required, if any, varies from property to property and could include: removal of hazardous, toxic and radioactive waste, ordnance and explosives waste, building demolition and/or debris removal.

For more information, please see:

http://www.usace.army.mil/Missions/Environmental/FormerlyUsedDefenseSites.aspx

ADDITIONAL MILITARY SITES

Based on PROPERTY I.D.'s research of specific maps or information issued by the U.S. Army Corps of Engineers in conjunction with the Department of Defense, individual base cleanup organizations, and local sources, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1 MILE OF A MILITARY SITE

DISCUSSION:

Former and current military sites exist throughout the country in various stages of use, closure, and cleanup. While some of these military sites are included in the FUDS program, those owned by, leased to, or otherwise possessed by the United States and under the jurisdiction of the Department of Defense after October 1986, are not eligible for inclusion in the FUDS program. These sites include but are not limited to sites where environmental cleanup has been completed such as previous FUDS program sites, or those that have been closed or realigned as part of the Base Realignment and Closure (BRAC) process.

Active military sites conduct a wide variety of military activities, including active training, that may generate noise from gunfire, ordnance detonations, aerial maneuvers, and other training exercises, which may be disruptive to those nearby. While some sounds may be directly attributed to the training activities noted above, such as an explosion, other sounds and vibrations may be due to low frequency sounds

Return to Quickview

Return to 1 Page NHDTM

Property ID











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

MILITARY ORDNANCE AND DEFENSE SITES (continued)

traveling through the air, with varying levels of disturbance based on the type of activity, and the current weather.

For further general information, visit the following:

https://www.epa.gov/fedfac/base-realignment-and-closure-brac-sites-state


https://www.bracpmo.navy.mil/

http://www.usace.army.mil/Missions/Environmental/FormerlyUsedDefenseSites.aspx

Note: The Military sites and their boundaries used in making these determinations are based on data made available at the source's discretion, and may be incomplete from the source. Certain sections of a site may be disclosed with other sections left out by the source. Some active military sites and bases may not be disclosed herein based on the discretion of the source.

Return to Quickview













5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

LANDFILLS

Based on PROPERTY I.D.'s research of specific maps or data for Los Angeles County, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 1000 FEET OF AN IDENTIFIED METHANE PRODUCING DISPOSAL SITE

Based on PROPERTY I.D.'s research of specific maps or data from CalRecycle's SWIS Database, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 3 MILES OF A LANDFILL OR SIMILAR DISPOSAL SITE

Based on PROPERTY I.D.'s research of specific maps or data from the California Department of Toxic Substances Control's Envirostor Database, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 3 MILES OF A LANDFILL OR SIMILAR DISPOSAL SITE

Based on PROPERTY I.D.'s research of specific maps or data from the California State Water Control Board's Geotracker Database, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 3 MILES OF A LANDFILL OR SIMILAR DISPOSAL SITE

Based on PROPERTY I.D.'s research of specific maps or data from the EPA's RCRA Database, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN 3 MILES OF A LANDFILL OR SIMILAR DISPOSAL SITE

DISCUSSION:

Landfills and others disposal facilities present special challenges to nearby residents. Air quality concerns, odors, vehicular traffic, dust, and potential contamination of the groundwater in and around the disposal facilities due to leaking or non-existent liners, create an environment of concern for properties in proximity. While some of these hazards are related to quality of life, and not direct adverse health effects, the accumulated potential for hazardous conditions in and around landfills, is a constant threat.

Note: In most cases, the official sources of landfill locations provide only a point location, not the overall boundaries of the landfill sites. Distances to those landfills, which are measured in making the hazard determinations above, are therefore measured and accurate to that point location, not to the outside boundaries of the landfill site.

Return to Quickview

Return to 1 Page NHDTM









OIL & GAS

REPORT #: 4074593 | REPORT DATE: 3/24/2025

LANDFILLS (continued)

Los Angeles County methane gas policy includes special regulations for properties within 1,000 ft of methane producing disposal sites. According to the county building code, "permits shall not be issued for buildings or structures regulated by this code within 1,000 ft of fills containing rubbish or other decomposable materials unless the fill is isolated by natural or artificial protective systems...." If your property is found to be located in a methane hazard zone, or within 1,000 ft of a methane producing landfill, certain building restrictions may be placed on your property. For further information, please contact the Los Angeles County Dept of Public Works at (626)458-5100.

[Los Angeles County Code-Title 26, Ordinance 110.3 and Ordinance 110.4]

Return to Quickview

Return to 1 Page NHD™









REPORT #: 4074593 | F

REPORT DATE: 3/24/2025

AREAS OF INDUSTRIAL / COMMERCIAL USE

LAND USE AND PLANNING

Based on PROPERTY I.D.'s research of specific maps or data for the City of Los Angeles, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN OR ADJACENT TO AN AREA OF INDUSTRIAL AND/OR COMMERCIAL LAND USE:

· NEIGHBORHOOD OFFICE COMMERCIAL

ZONING

Based on PROPERTY I.D.'s research of specific maps or data for the City of Los Angeles, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN OR ADJACENT TO AN INDUSTRIAL AND/OR COMMERCIAL USE ZONE:

· COMMERCIAL ZONE

PLANNING

SUBJECT PROPERTY IS LOCATED WITHIN 1 MILE OF COMMERCIAL OR INDUSTRIAL USE

Based on PROPERTY I.D.'s research of specific maps or data obtained from the Southern California Association of Governments, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN OR ADJACENT TO AN AREA OF INDUSTRIAL AND/OR COMMERCIAL LAND USE

DISCUSSION:

Industrial or commercial use zones or districts may be established by cities and/or counties wherein certain manufacturing, commercial or airport uses are expressly permitted.

Pursuant to Section 1102.17 of the Civil Code, the seller of residential real property subject to this article who has actual knowledge that the property is affected by, or zoned to allow, an industrial use described in Section 731a of the Code of Civil Procedure, which allows manufacturing, commercial or airport uses in zones that have been established under authority of law for those uses, shall give written notice of that knowledge as soon as practicable before transfer of title.

The existence of various conditions such as traffic, noise, odors, pollution, obstructed views, and other such conditions that are reasonable and necessary in Industrial Use Zones, cannot be enjoined or restrained, nor shall such use be deemed a nuisance as outlined in Section 731a of the Code of Civil Procedure.

Return to Quickview

Return to 1 Page NHDTM

Property ID











5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

AREAS OF INDUSTRIAL / COMMERCIAL USE (continued)


Note: The composition of Planned Developments may not be finalized and may eventually include areas of commercial or industrial use. For more information about a Planned Development in your area, contact the local planning department.

Note: Where not specifically identified, determinations may be based on maps or data made for Land Use and Planning purposes, and may not reflect all local zoning. Zoning changes occur often. This report should not be relied upon to provide any specific determination of the current zoning or allowed activities on or near the the Subject Property.

Return to Quickview

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 REPORT DATE: 3/24/2025

HISTORIC AND ARCHAEOLOGICAL SITES

Based on PROPERTY I.D.'s research of specific maps or data for the City of Los Angeles, the following determinations are made:

SUBJECT PROPERTY IS NOT LOCATED IN OR ADJACENT TO A HISTORIC PRESERVATION OVERLAY ZONE

SUBJECT PROPERTY IS NOT LOCATED IN OR ADJACENT TO A HISTORIC-CULTURAL. MONUMENT SITE

DISCUSSION:

Recognizing the need to identify and protect neighborhoods with distinct architectural and cultural resources, the City of Los Angeles has developed an expansive program of Historic Preservation Overlay Zones (HPOZs). HPOZs, commonly known as historic districts, provide for review of proposed exterior alterations and additions to historic properties within designated districts.

The City Council adopted the ordinance enabling the creation of HPOZs in 1979; Angelino Heights became Los Angeles' first HPOZ in 1983. Today, the City of Los Angeles has 29 designated HPOZs, with many more under consideration (Proposed HPOZs). HPOZ areas range in size from neighborhoods of approximately 50 parcels to more than 3,000 properties. While most districts are primarily residential, many have a mix of single-family and multi-family housing, and some include commercial and industrial properties. HPOZs are established and administered by the Los Angeles City Planning Department (in concert with the City Council). Individual buildings in an HPOZ need not be of landmark quality on their own; it is the collection of a cohesive, unique, and intact collection of historic resources that qualifies a neighborhood for HPOZ status. Projects within the HPOZ may be subject to an extra level of review per the HPOZ ordinance, number 175891 in Section 12.20.3 of the City of Los Angeles Municipal code.


Likewise, the City of Los Angeles Cultural Heritage Ordinance, enacted in 1962, has made possible the designation of buildings and sites as individual local landmarks, called "Historic-Cultural Monuments". The City currently has over 1,000 Historic-Cultural Monuments, providing official recognition and protection for Los Angeles' most significant and cherished historic resources. Buyers of Historic-Cultural monument sites may be eligible for certain property tax breaks, though several restrictions do apply in regards to alteration or rehabilitation of these properties.

For further information, please contact the City of Los Angeles Office of Historic Resources at (213) 847-3676 or on the web at https://planning.lacity.org/preservation-design/program-overview.

Return to Quickview
















5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

HISTORIC AND ARCHAEOLOGICAL SITES (continued)

HISTORICAL SIGNIFICANCE NOTICE

Recognizing the need to identify and protect neighborhoods with distinct architectural and cultural resources, national, state, and local agencies have developed review processes for properties with historical significance. While the review process varies based on jurisdiction, a property deemed to be of historical significance may be subject to special rules, regulations, or building codes that could affect your ability to alter or improve said property.

While Property I.D. has not discovered if the subject property has any historical significance, and has no duty to do so, it is important to be aware that properties that contain older structures may have some historical significance, and you should contact your local Planning and/or Building Department(s) to confirm how your property may be affected, especially if any improvements are to be made.

For more information on historical sites in general, please visit the following:

National Register of Historic Places: https://www.nps.gov/subjects/nationalregister/index.htm

CA Register of Historical Resources: http://ohp.parks.ca.gov/?page_id=21238

CA Points of Historical Interest: http://ohp.parks.ca.gov/?page_id=21750

Return to Quickview













REPORT #: 4074593 REPORT DATE: 3/24/2025

PROTECTED SPECIES / HABITATS

Based on PROPERTY I.D.'s research of the current maps and/or information obtained from the U.S. Fish & Wildlife Service (USFWS), the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN A CRITICAL HABITAT AREA

Based on PROPERTY I.D.'s research of the current maps and/or information obtained from federal, state, county, or local habitat conservation departments, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED IN AN AREA WITH PROTECTED SPECIES OR **HABITATS**

Based on PROPERTY I.D.'s research of the California Natural Diversity Database (CNDDB), the following determination is made:

SUBJECT PROPERTY IS LOCATED IN AN AREA WHERE SIGHTINGS OF RARE SPECIES. AND/OR NATURAL COMMUNITIES HAVE BEEN RECORDED, INCLUDING THE FOLLOWING:

- · AMERICAN BADGER
- · BURROWING OWL
- · SOUTHWESTERN WILLOW FLYCATCHER (ENDANGERED)

DISCUSSION:

The species and/or habitat(s) listed above, if any, represent rare, sensitive, threatened, endangered, or special status plants, animals, natural communities, or habitats. Some of the species listed may not currently be considered endangered, threatened, sensitive, or protected, at the time of the report, but do have the potential of receiving an upgraded status.

Landowners with property in conservation areas may be subject to development fees at the time a grading permit is obtained, and/or may be required to secure a habitat assessment conducted by a biologist or specialist approved by the United States Fish and Wildlife Service, and/or the California Department of Fish and Wildlife, and/or the local jurisdiction habitat conservation department. Fee revenues are generally expended for land acquisition, biologic research and other conservation and mitigation activities necessary to help implement the applicable species habitat conservation plans. A habitat assessment involves a field survey to ascertain the actual presence of the particular species upon the Subject Property. These habitat preservation measures may also limit the landowner's ability to develop the property. Affected landowners should check the applicable jurisdiction's ordinances, mitigation fees, and local planning jurisdictions.

Return to Quickview

Return to 1 Page NHDTM







5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 | REPORT DATE: 3/24/2025

PROTECTED SPECIES / HABITATS (continued)

The CNDDB provides location and natural history information on special status plants, animals, and natural communities to the public, government agencies, and conservation organizations. The data can help drive conservation decisions, aid in environmental review of projects, and provide baseline data helpful in recovering endangered species. Although proximity to a CNDDB identified historic species and/or habitat sighting does not necessarily impact the landowner(s) directly, homeowners and buyers may wish to check applicable ordinances, mitigation fees, and local planning jurisdictions.

Contact information for your Department of Fish and Wildlife Regional Office can be found at https://www.wildlife.ca.gov/Regions.


Note: A lack of listed species and/or habitats in this report does not necessarily mean that there are no rare species or habitats in this area. Areas that have not been surveyed for rare species will not show results in this report. Land that has not been surveyed for rare plants and animals retains the potential to support rare elements.

Return to Quickview

Return to 1 Page NHD™

Property ID

•









5454 VIRGINIA AVE, LOS ANGELES, CA 90029 LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

NOTICE OF RIGHT TO FARM

Based on PROPERTY I.D.'s research of the current county-level GIS "Important Farmland Map," issued by the California Department of Conservation, Division of Land Resource Protection, the following determination is made:

SUBJECT PROPERTY IS NOT LOCATED WITHIN ONE MILE OF AN OFFICIALLY DESIGNATED AREA OF AGRICULTURAL ACTIVITY

The following notice applies to properties located within one mile of agricultural activity.

NOTICE:

This property is located within one mile of farm or ranch land designated on the current county-level GIS "Important Farmland Map," issued by the California Department of Conservation, Division of Land Resource Protection. Accordingly, the property may be subject to inconveniences or discomforts resulting from agricultural operations that are a normal and necessary aspect of living in a community with a strong rural character and a healthy agricultural sector. Customary agricultural practices in farm operations may include, but are not limited to, noise, odors, dust, light, insects, the operation of pumps and machinery, the storage and disposal of manure, bee pollination, and the ground or aerial application of fertilizers, pesticides, and herbicides. These agricultural practices may occur at any time during the 24-hour day. Individual sensitivities to those practices can vary from person to person. You may wish to consider the impacts of such agricultural practices before you complete your purchase. Please be advised that you may be barred from obtaining legal remedies against agricultural practices conducted in a manner consistent with proper and accepted customs and standards pursuant to Section 3482.5 of the Civil Code or any pertinent local ordinance.

Return to Quickview







REPORT #: 4074593 | REPORT DATE: 3/24/2025

PROPERTY TAX RECORDS

PROPERTY TAX BILL SUMMARY

Tax Totals for the 2024-2025 tax year:

Mello-Roos Total: 0.00

Direct Charge (Special Assessment/1915) Total: \$480.34

Variable (Ad Valorem) Tax Total: 0.00

at the variable tax rate of 1.199691%

2024-2025 Property Tax Bill Total:* \$480.34

*The Annual Tax Total amount represents the total property tax fees on the subject property as billed at the beginning of the listed tax year. The levies and amounts listed in this report are based on the levies and property valuation on record at the beginning of the listed tax year. Items not found on the property tax bill provided by the county for the listed tax year, and/or deferred items, may not be found in this report. (Property I.D. reserves the right to update these records during the course of the tax year, at Property I.D.'s discretion.)

NOTE: The taxes listed are for the tax year shown above. The amounts and levies are subject to change pursuant to the purchase price of the property, changes to the assessed value, changes due to a recent sale/flip of the property, or changes in the tax rolls. Some supplemental tax bills and/or penalty fees are not included in this report. To see an estimate of the future taxes based on purchase price, please click the Property I.D. Future Tax Estimator below.



Mello-Roos Community Facilities District Levies - Details Notice of Special Tax

SUBJECT PROPERTY DOES NOT CURRENTLY HAVE MELLO-ROOS TAXES LEVIED AGAINST IT

The Mello-Roos Community Facilities District Act, enacted in 1982, allows local governments to create tax districts to finance infrastructure, services, and public facilities such as sewers, parks, electrical upgrades, etc. Establishing a Mello-Roos tax requires a 2/3 majority vote. The electors in a Mello-Roos vote consist of the registered voters in the new tax district, provided the district contains at least 12 registered voters. Otherwise, the qualified electors are the land owners within the district, with each land owner entitled to one or more voters based on the amount of land owned within the district. In some cases, there may be a single owner or developer voting.

Note: By voter approval new Mello-Roos taxes may be levied against this property in the future. Items not found on the property tax bill provided by the county for the listed tax year, and/or deferred items, may not be found in this report.

Return to Quickview

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593

REPORT DATE: 3/24/2025

<u>Direct Charge (Special Assessment/1915 Bond Act) Levies - Details</u> <u>Notice of Special Assessment</u>

SUBJECT PROPERTY IS LOCATED IN A SPECIAL TAX ASSESSMENT DISTRICT

Special Assessments are taxes levied against parcels for public projects in which the amount of the charge is based on the benefit of the project to the parcel. Assessments based on the 1915 Bond Act are among special assessments, and are generally used to fund public improvement projects such as streets and sewer systems.

Note: By voter approval new Special Assessment taxes may be levied against this property in the future. Items not found on the property tax bill provided by the county for the listed tax year, and/or deferred items, may not be found in this report.

Code	Description	Contact	Phone	Amount
00170	TRAUMA/EMERG SRV	LOS ANGELES COUNTY DEPARTMENT OF HEALTH SERVICES	(866)587-2862	\$340.00
03071	FLOOD CONTROL	LOS ANGELES COUNTY PUBLIC WORKS	(626)979-5498	\$57.89
18869	LA STORMWATER	CITY OF LOS ANGELES/DEPARTME NT OF PUBLIC WORKS	(213)485-4094	\$46.15
18850	LACITY PARK DIST	DPW/BUREAU OF ENGINEERING, PROPOSITION K	(213)485-4795	\$26.05
06111	LA WEST MOSQ AB	LOS ANGELES COUNTY WEST VECTOR CONTROL DISTRICT	(310)915-7370 X230	\$10.25

Direct Charge (Special Assessment/1915) Total: \$480.34

<u>Property Value Adjusted (Ad Valorem) Levies - Details</u>

SUBJECT PROPERTY IS SUBJECT TO AD VALOREM TAXES

Ad Valorem taxes, also known as "Rate-Based Taxes" are charges calculated as a percentage of the total value of real property, including improvement and land values as determined by the county assessor. California's standard 1% property tax is included among these rate based taxes.

Note: By voter approval new Ad Valorem taxes may be levied against this property in the future.

Return to Quickview

Return to 1 Page NHD™

Property ID











REPORT #: 4074593 | REPORT DATE: 3/24/2025

Code	Description	Contact	Phone	Rate	Amount
00100	PROP. 13 STANDARD 1% TAX	LOS ANGELES COUNTY AUDITOR	(213)974-8301	1%	\$0.00 *
80588	LA CCD DS 2008, SER M	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000381%	\$0.00 *
80589	LA CCD DS 2016, SER D	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.005520%	\$0.00 *
80590	LA CCD DS 2022, SER A-1	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.005867%	\$0.00 *
80592	LA CCD DS 2022, SER B	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001689%	\$0.00 *
80593	LA CCD DS 2024 REF BONDS	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.005488%	\$0.00 *
80594	LA CCD DS 2016, SER E	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.002000%	\$0.00 *
80576	LA CCD DS 2008, SER I	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000864%	\$0.00 *
80577	LA CCD DS 2008, SER J	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001413%	\$0.00 *
80578	LA CCD DS 2016 REF BDS	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000441%	\$0.00 *
80581	LA CCD DS 2008, SER K	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000724%	\$0.00 *
80584	LA CCD DS 2020 REF BDS	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.006070%	\$0.00 *
80586	LA CCD DS 2016, SER C-1	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.005539%	\$0.00 *

Return to Quickview

Return to 1 Page NHD™

Property ID











REPORT #: 4074593 REPORT DATE: 3/24/2025

Code	Description	Contact	Phone	Rate	Amount
80556	L.A. CCD DS 2001 SER 2004A	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000011%	\$0.00 *
80565	LA CCD DS 2008, 09 TXBL SER B	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000454%	\$0.00 *
80566	LA CCD DS 2008, 2010 TXBL SER D	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000671%	\$0.00 *
80567	LA CCD DS 08,2010 TX SR E (BABS)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.004136%	\$0.00 *
80571	LA CCD DS 2008, SER G	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000686%	\$0.00 *
80575	LA CCD DS 2015 REF, SER C	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.003417%	\$0.00 *
88899	LA USD DS SER QRR(2023) MEAS RR	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.002072%	\$0.00 *
88951	LA USD DS 2024 REF SER A MEAS R	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.012587%	\$0.00 *
88952	LA USD DS 2024 REF SER A MEAS Y	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.004030%	\$0.00 *
88953	LA USD DS SER QRR(2024) MEAS Q	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.013619%	\$0.00 *
88954	LA USD DS SER QRR(2024) MEAS RR	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.014917%	\$0.00 *
80555	L.A. CCD DS 2003 SER 2004B	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000686%	\$0.00 *
88893	LA USD DS SER RYRR(2021) MEAS Y	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000391%	\$0.00 *

Return to Quickview

Return to 1 Page NHD™

Property ID

COPYRIGHT © 2025 PROPERTY I.D. All rights reserved. We have answers.



REPORT #: 4074593 | REPORT DATE: 3/24/2025

Code	Description	Contact	Phone	Rate	Amount
88894	LA USD DS SER RYRR(2021) MEAS RR	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001676%	\$0.00 *
88895	LA USD 2021 REF SER B MEAS K	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001521%	\$0.00 *
88896	LA USD DS SER QRR(2022) MEAS RR	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.003668%	\$0.00 *
88897	LA USD DS SER QRR(2022) MEAS Q	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000510%	\$0.00 *
88898	LA USD DS SER QRR(2023) MEAS Q	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.002149%	\$0.00 *
88885	LA USD DS SER RYQ (2020-B)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.006835%	\$0.00 *
88886	LA USD 20 RF SR A MS K 10 SR KRY	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000610%	\$0.00 *
88887	LA USD 20 RF SR A MS R 10 SR KRY	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001366%	\$0.00 *
88888	LA USD 20 RF SR A MS Y 10 SR KRY	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000359%	\$0.00 *
88891	LA USD 21RF SR A MEAS Q SR A 16	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.002376%	\$0.00 *
88892	LA USD DS SER RYRR(2021) MEAS R	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000693%	\$0.00 *
88878	LA USD DS 19 REF,02 S D (MEAS K)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001433%	\$0.00 *
88879	LA USD DS 19 REF,04 S I (MEAS R)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.003181%	\$0.00 *

Return to Quickview

Return to 1 Page NHDTM

Property ID





LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

Code	Description	Contact	Phone	Rate	Amount
88880	LA USD DS 19 REF,05 S F (MEAS Y)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000860%	\$0.00 *
88882	LA USD MEAS R, 2020 SER RYQ	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000169%	\$0.00 *
88883	LA USD MEAS Y, 2020 SER RYQ	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000856%	\$0.00 *
88884	LA USD MEAS Q, 2020 SER RYQ	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.003414%	\$0.00 *
88870	LA USD DS 2016 REF BONDS SER A	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.004937%	\$0.00 *
88871	LA USD DS 2016 REF BONDS SER B	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.004406%	\$0.00 *
88872	LA USD DS 17 REF SER A (PROP BB)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001679%	\$0.00 *
88873	LA USD DS 17 REF SER A (MEAS K)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.019176%	\$0.00 *
88874	LA USD DS 2005,SER M-1 (2018)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000833%	\$0.00 *
88876	LA USD DS 2008,SER B-1 (2018)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.007844%	\$0.00 *
18908	CITY LOS ANGELES TD 1 HOLLYWD RP	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.013312%	\$0.00 *
88789	LA USD DS 2005, SER H (QSCBS)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.005134%	\$0.00 *
88855	LA USD 2005,2010 SER J-1 (QSCBS)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001355%	\$0.00 *

Return to Quickview


Return to 1 Page NHDTM

Property ID









REPORT #: 4074593

REPORT DATE: 3/24/2025

Code	Description	Contact	Phone	Rate	Amount
88856	LA USD 2005,2010 SER J-2 (QSCBS)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.000687%	\$0.00 *
88868	LA USD DS 2015 REF BONDS, SER A	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001332%	\$0.00 *
88869	LA USD DS 2008 SER A (2016)	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.001343%	\$0.00 *
80595	LA CCD DS 2022, SER C	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.005304%	\$0.00 *
31030	CITY OF LA AREA REMAINDER-1104	LOS ANGELES COUNTY AUDITOR	(213)974-8301	0.007000%	\$0.00 *

Variable (Ad Valorem) Tax Total: 0.00 @ 1.199691%


DISCUSSION:

THIS IS A NOTIFICATION TO YOU PRIOR TO YOUR PURCHASING THIS PROPERTY. If this property is within the above-named assessment district(s), the assessment district(s) issued bonds to finance the acquisition or construction of the certain public improvements that are of direct and special benefit to property within the assessment districts. The bonds will be repaid from annual assessment installments on the property within the assessment districts. If this property is subject to annual assessment installments, the assessment districts will appear on the property tax bills, in addition to the regular property taxes and any other charges and levies that will be listed on the property tax bill. Assessment installments will be collected each year until the assessment bonds are repaid. These facilities may not yet have all been constructed or acquired and it is possible that some may never be constructed or acquired. If you fail to pay this tax when due each year, the property may be foreclosed upon and sold. The tax is used to provide public facilities and/or services that are likely to particularly benefit the property. YOU SHOULD TAKE THIS TAX AND THE BENEFITS FROM THE PUBLIC FACILITIES AND SERVICES FOR WHICH IT PAYS INTO ACCOUNT IN DECIDING WHETHER TO BUY THIS PROPERTY. By signing the NHDS and Disclosure Report Receipt, Buyer(s) ACKNOWLEDGE THAT BUYER(S) HAVE RECEIVED A COPY OF THIS NOTICE. BUYER(S) UNDERSTAND THAT BUYER(S) MAY TERMINATE THE CONTRACT TO PURCHASE OR DEPOSIT RECEIPT AFTER RECEIVING THIS NOTICE FROM THE OWNER OR AGENT SELLING THE PROPERTY. THE CONTRACT MAY BE TERMINATED WITHIN THREE DAYS IF THE NOTICE WAS RECEIVED IN PERSON OR WITHIN FIVE DAYS AFTER IT WAS DEPOSITED IN THE MAIL BY GIVING WRITTEN NOTICE OF THAT TERMINATION TO THE OWNER OR AGENT SELLING THE PROPERTY. This disclosure notice is made pursuant to Government Code Sections 53340.2, 53754 and Civil Code Section 1102.6b and satisfies the 1915 Bond and Special Assessment disclosure requirements.

Return to Quickview

Return to 1 Page NHDTM

Property ID









^{*}This amount represents the fees based on the property valuation as listed in the identified tax records as of the beginning of the identified tax year. This amount is subject to change pursuant to the purchase price of the property and/or changes to the assessed value and does not include supplemental tax bills. Items not found on the property tax bill provided by the county for the listed tax year, and/or deferred items, may not be found in this report.

REPORT #: 4074593 | REPORT DATE: 3/24/2025

Note: The applicable county tax assessor/collector and Property I.D. update their Tax Assessment information yearly or quarterly. Only Assessments that were levied against properties at the time Property I.D. obtained the tax records are disclosed. This information is subject to change and Property I.D. is not responsible for any changes that may occur. No study of the public records was made by Property I.D. to determine the presence of any other tax or assessment. The above explanation of Special Assessments is intended to be general in nature and is not a substitute for a tax bill, title report or title insurance. Detailed information may be available by contacting the agency that administers the Special Assessment. If detailed information is desired, Property I.D. recommends that an appropriate professional consultant be retained.

In some cases (including some condos, mobile homes, and new subdivisions), the tax roll data disclosed may represent the entire amount for the main parcel when the individual parcels have not been segregated. In other cases, taxes levied on the main parcel may not show up on bills for the individual units, but paid for via HOA dues or other fees.

NOTICE OF YOUR SUPPLEMENTAL PROPERTY TAX BILL

California property tax law requires the Assessor to revalue real property at the time the ownership of the property changes. Because of this law, you may receive one or two supplemental tax bills, depending on when your loan closes. The supplemental tax bills are not mailed to your lender. If you have arranged for your property tax payments to be paid through an impound account, the supplemental tax bills will not be paid by your lender. It is your responsibility to pay these supplemental bills directly to the Tax Collector. If you have any question concerning this matter, please call your local Tax Collector's Office. To see an estimate of the future taxes based on purchase price, please visit the Property I.D. Future Tax Estimator below.

Note: This is a notice to you that the County Assessor will revalue the property and you will be responsible for paying the taxes due according to the reassessed value. It is not a disclosure of actual supplemental property taxes. If the subject property has recently sold, after the closure of the tax roll for the tax year noted above, the supplemental tax estimate may change, and should be verified with the County.



GENERAL NOTICE OF TRANSFER FEE DISCLOSURE

Some properties may be affected by transfer fees. In the event that the property being transferred is subject to a transfer fee, the transferor is required to make this disclosure. A transferor may request the title company that issued the preliminary title report to provide copies of the documents for review in order for the transferor to determine if the property being transferred is subject to a transfer fee.

A "transfer fee" is any fee payment requirement imposed within a covenant, condition or restriction (CC&R), contained in any deed, contract, security instrument, or other document affecting the transfer or sale of, or any interest in, real property that requires a fee be paid upon transfer of the real property.

If the property being transferred is subject to a transfer fee, the transferor shall provide, at the same time as the transfer disclosure statement is provided, an additional disclosure that includes (1) notice that payment of a transfer fee is required upon transfer of the property; (2) the amount of the fee required for the asking price of the real property and a description of how the fee is calculated; (3) notice that the final amount of the fee may be different if the fee is based upon a percentage of the final sale price; (4) the entity to which funds from the fee will be paid; (5) the purpose for which the funds from the fee will be used; (6) the date or circumstances under which the obligation to pay the transfer fee expires, if any.

You may wish to investigate and determine whether the imposition of a transfer fee, if any, is acceptable to you and your intended use of the property before you complete your transaction.

Return to Quickview

Return to 1 Page NHD™

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

ACCELERATED FORECLOSURE NOTICE

It is extremely important that the real property tax bill be paid on time to prevent accelerated foreclosure. If this property is part of a Mello-Roos District (Community Facilities District), a 1915 Act Assessment District, or certain other special financing districts, it may be subject to accelerated foreclosure. Even though the County must wait five years to foreclose on a property because of delinquent taxes, unpaid Mello-Roos and Assessment districts can begin foreclosure proceedings 150-180 days after one of their tax charges becomes delinquent. If the real property is subject to such an assessment and the taxes are not paid promptly, the real property may be foreclosed upon and sold at public auction on an expedited basis.

PROPOSITION 19: THE HOME PROTECTION FOR SENIORS, SEVERELY DISABLED, FAMILIES, AND VICTIMS OF WILDFIRE OR NATURAL DISASTERS ACT


On November 3, 2020, California voters approved Proposition 19. This amendment to California Constitution Article XIII A provides for property tax savings for taxpayers in several exclusion and base year value transfer areas. Beginning on and after April 1, 2021, an owner of a primary residence who is over 55 years of age, severely disabled, or a victim of a wildfire or natural disaster, is allowed to transfer the taxable value, defined as the base year value plus inflation adjustments, of their primary residence to a replacement primary residence located anywhere in the state, regardless of the location or value of the replacement primary residence, that is purchased or newly constructed as that person's principal residence within 2 years of the sale of the original primary residence. The measure would limit a person who is over 55 years of age or severely disabled to 3 transfers under these provisions. Proposition 19 also includes provisions modifying the transfer of property exclusions within families, previously defined under Propositions 58/193.

For further information, visit the State Board of Equalization's Prop. 19 page at

https://www.boe.ca.gov/prop19

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

ENVIRONMENTAL

DISCLOSURE	SOURCE	RESULT	PAGE
Groundwater Management and Monitoring (Potential Well Regulation)	State	IN VERY LOW PRIORITY	<u>67</u>
Environmental Report	EPA, DTSC, CalRecycle. SWRCB	INCLUDED	<u>68</u>

GROUNDWATER

Based on PROPERTY I.D.'s research of specific maps or data from the California Department of Water Resources, the following determination is made:

SUBJECT PROPERTY IS LOCATED IN A CALIFORNIA STATEWIDE GROUNDWATER ELEVATION MONITORING PROGRAM VERY LOW PRIORITY GROUNDWATER BASIN

DISCUSSION:

The Sustainable Groundwater Management Act (SGMA), signed into law on September 16, 2014, is a package of three bills (AB 1739, SB 1168, and SB 1319) that provides local agencies with a framework for managing groundwater basins in a sustainable manner. Recognizing that groundwater is most effectively managed at the local level, the SGMA empowers local agencies to achieve sustainability within 20 years. As part of this process, the Department of Water Resources (DWR), via the California Statewide Groundwater Elevation Monitoring (CASGEM) Program, has identified and prioritized groundwater basins throughout the state. Based on the priority designation, local agencies may form Groundwater Sustainability Agencies (GSAs), tasked with developing Groundwater Sustainability Plans (GSPs) within a certain time frame. The SGMA requires GSAs in high and medium priority basins to develop GSPs, while GSAs in low and very low priority basins are encouraged, but not required, to do so. With the adoption of these plans, potential changes to local groundwater management practices may affect your property. Any concerns should be directed to your local Planning Department, Groundwater Management Agency, and other related agencies.


Further information on the SGMA can be found at the following sites:

https://www.waterboards.ca.gov/water_issues/programs/sgma/docs/resources/dom_well_brchr.pdf https://www.waterboards.ca.gov/water_issues/programs/sgma/

Return to Quickview













ENVIRONMENTAL HAZARDS REPORT

This Environmental Hazards Report provides information on known, existing and historic hazardous substance contaminated sites that may be on or near the Subject Property, as listed by the Environmental Protection Agency and/or other specified regulatory bodies.

MAPPED

DISCLOSURE	REGULATORY	SITE COUNT
NPL/SEMS National Priorities List / Superfund Enterprise Management System	EPA	0
RCRA Resource Conservation and Recovery Act	EPA	61
ENVIROSTOR Hazardous Substance Contamination Sites, Site Mitigation & Brownfield Reuse Program Sites	CA Department of Toxic Substances Control	14
SWIS Solid Waste Information System	CalRecycle	0
GEOTRACKER Underground Storage Tanks, Department of Defense Site Cleanup Program, Land Disposal Sites	CA Water Resources Control Board	13


UNMAPPED

DISCLOSURE	REGULATORY	SITE COUNT
NPL/SEMS - Unmapped	EPA	1
RCRA - Unmapped	EPA	28
ENVIROSTOR - Unmapped	CA Department of Toxic Substances Control	0
SWIS - Unmapped	CalRecycle	0
GEOTRACKER - Unmapped	CA Water Resources Control Board	0

Return to Quickview














REPORT #: 4074593 | REPORT DATE: 3/24/2025

NPL/SEMS Site Details

The SEMS is the Superfund Enterprise Management System that contains information on hazardous waste sites, potentially hazardous waste sites and remedial activities across the nation. SEMS is based on the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), commonly known as Superfund, enacted by Congress on December 11, 1980. The database includes sites that are on the National Priorities List (NPL), proposed for the NPL, partially and/or fully deleted from the NPL. The NPL is the Environmental Protection Agency's (EPA) database of uncontrolled or abandoned hazardous waste sites identified for remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system (HRS) score to be eligible for placement on the NPL. Only sites on the NPL are eligible for Superfund Trust Fund-financed remedial actions. More information can be obtained from https://www.epa.gov/superfund.

This report lists SEMS sites identified as being within 1 mile of Subject Property, if any are found.

*NOTE: Properties marked as "Inactive" and/or "Archived" may have been remediated, with no further activities on site that could be subject to CERCLA, or to a state's authorized hazardous waste program. This designation has no legal significance and does not constitute a legally enforceable or binding determination about the status of a particular site or the obligations of an owner or operator.

NO MAPPED NPL/SEMS SITES WERE FOUND IN PROXIMITY OF THE SUBJECT PROPERTY

RCRA Site Details

RCRA is the Resource Conservation and Recovery Act, which was enacted by Congress in 1976. RCRA's primary goals are to protect human health and the environment from the potential hazards of waste disposal, to conserve energy and natural resources, to reduce the amount of waste generated, and to ensure that wastes are managed in an environmentally sound manner. Specifically, RCRA regulates the management of hazardous wastes from the point of origin to the point of final disposal. Additional information is available at https://www.epa.gov/rcra.

This report lists RCRA sites identified as being within 1/2 mile of Subject Property, if any are found.

*NOTE: Properties marked as "Inactive" have been removed from this report, and may have been remediated, with no further activities on site subject to the Resource Conservation and Recovery Act, Subtitle C, or to a state's authorized hazardous waste program. This designation has no legal significance and does not constitute a legally enforceable or binding determination about the status of a particular site or the obligations of an owner or operator. Please contact us for more information on "Inactive" sites.

Return to Quickview

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000307569 Floridalma Linares D.D.S., Inc 5465 Santa Monica Blvd Ste 102 Los Angeles, CA, 90029-2339	Distance: 0.04 mi Direction: SE Lat, Lon: 34.0910, -118.3081
Owner/Operator: Floridalma Linares D.D.S. Inc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000445226		
Sugar Coat	Distance: 0.04 mi	
1172 N Western Ave	Direction: N	
Los Angeles, CA, 90029	Lat, Lon: 34.0924, -118.3089	
Owner/Operator: Juan Luis Munoz Jr	Owner/Operator Type: Other /	
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator	
Institutional Controls:	Environmental Controls: Environmental controls not in place	
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control	
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair	
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination, haz waste recycler		
Active Site Activities: Handler activities		

Return to Quickview

Return to 1 Page NHD™

Property ID





LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAD982474199 Winston Tire Company 1172 - 74 N Western Ave Los Angeles, CA, 90029	Distance: 0.05 mi Direction: NW Lat, Lon: 34.0923, -118.3093	
Owner/Operator: Oliver & Wiston	Owner/Operator Type: Private /	
Land Type: Other land type	Activity/Generator Status: Active / Small quantity generator	
Institutional Controls:	Environmental Controls: Environmental controls not in place	
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control	
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:	
Misc Site Activities:		
Active Site Activities: Handler activities		

RCRA SITE ID: CAL000434588 J & H Auto Repair 1172 N Western Ave Los Angeles, CA, 90029	Distance: 0.06 mi Direction: N Lat, Lon: 34.0926, -118.3089	
Owner/Operator: Jose Castillo And Herbert Osorio	Owner/Operator Type: Other /	
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator	
Institutional Controls:	Environmental Controls: Environmental controls not in place	
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control	
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair	
Misc Site Activities: On site universal waste destination, universal waste generator or receiver		
Active Site Activities: Handler activities		

Return to Quickview

Return to 1 Page NHDTM

Property ID



LOS ANGELES COUNTY | APN: 5536-010-006

REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000435973 Mjr Motorsport 1172 N Western Ave Los Angeles, CA, 90029	Distance: 0.06 mi Direction: N Lat, Lon: 34.0926, -118.3089	
Owner/Operator: Herbert A Osorio	Owner/Operator Type: Other /	
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator	
Institutional Controls:	Environmental Controls: Environmental controls not in place	
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control	
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Automotive body, paint, and interior repair and maintenance	
Misc Site Activities: On site universal waste destination, universal waste generator or receiver		
Active Site Activities: Handler activities		

RCRA SITE ID: CAL000434838 Affordable Tires 1176 N Western Ave	Distance: 0.06 mi Direction: N	
Los Angeles, CA, 90029	Lat, Lon: 34.0926, -118.3089	
Owner/Operator: Claudia V Diaz Benavides	Owner/Operator Type: Other /	
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator	
Institutional Controls:	Environmental Controls: Environmental controls not in place	
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control	
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair	
Misc Site Activities: On site universal waste destination, universal waste generator or receiver		
Active Site Activities: Handler activities		

Return to Quickview

Return to 1 Page NHDTM

Property ID

We have answers.



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000437880 J&J Auto Repair 1172 N Western Ave Los Angeles, CA, 90029	Distance: 0.06 mi Direction: N Lat, Lon: 34.0926, -118.3089
Owner/Operator: Jose D Castillo	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD983671686 Republic Paint Inc 5421 Santa Monica Blvd Los Angeles, CA, 90029	Distance: 0.08 mi Direction: SE Lat, Lon: 34.0907, -118.3076
Owner/Operator: Gerald Wahlin	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Paint, varnish, and supplies wholesalers
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID





REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAD982466963 First 45 Minute Photo & Video 5520 Santa Monica Blvd #102 Los Angeles, CA, 90038	Distance: 0.09 mi Direction: SW Lat, Lon: 34.0907, -118.3099
Owner/Operator: Ng Hankhyn	Owner/Operator Type: Private /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000386292 Seon Roh's Dental Office 5520 Santa Monica Blvd Ste 104 Los Angeles, CA, 90038	Distance: 0.1 mi Direction: SW Lat, Lon: 34.0902, -118.3101
Owner/Operator: Seon Roh	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Offices of dentists
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM





REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAL000382684 Exclusive Motorcars Inc Dba Rick's Auto Body & Distance: 0.1 mi Direction: SE Paint 5416 Santa Monica Blvd Lat, Lon: 34.0904, -118.3071 Los Angeles, CA, 90029 Owner/Operator: Exclusive Motorcars Inc Owner/Operator Type: Other / Land Type: Not provided, though not located on Activity/Generator Status: Active / Not a generator indian land Environmental Controls: Environmental controls not Institutional Controls: in place Ground Water Controls: Groundwater controls not Human Exposure Controls: Human exposure not in place under control Industrial Activity Classification: Automotive body, Used Oil/Haz. Waste Type: / paint, and interior repair and maintenance Misc Site Activities: Universal waste generator or receiver, on site universal waste destination Active Site Activities: Handler activities

RCRA SITE ID: CAL000312840 Hobart Auto Center 5255a Santa Monica Blvd Los Angeles, CA, 90029-1209	Distance: 0.2 mi Direction: E Lat, Lon: 34.0910, -118.3043
Owner/Operator: Galust Shkhrdumyan	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID







REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAR000112243 Glidden Company 5600 Santa Monica Blvd Hollywood, CA, 90038	Distance: 0.2 mi Direction: W Lat, Lon: 34.0907, -118.3116
Owner/Operator: Glidden Co	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000316325 De Vela Dental Corporation 5300 Santa Monica Blvd Ste 404 Los Angeles, CA, 90029-1260	Distance: 0.2 mi Direction: E Lat, Lon: 34.0905, -118.3055
Owner/Operator: De Vela Dental Corporation	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Diagnostic imaging centers
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Have Questions?

Return to 1 Page NHD™

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAL000139177 Tosco 30550 1300 N Western Ave Los Angeles, CA, 90027	Distance: 0.2 mi Direction: N Lat, Lon: 34.0952, -118.3092
Owner/Operator:	Owner/Operator Type: / Not provided
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Other gasoline stations
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD983661547 Simons Camera 1316 N Western Ave Los Angeles, CA, 90027	Distance: 0.2 mi Direction: N Lat, Lon: 34.0954, -118.3092
Owner/Operator: Simon Ong	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID





REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAC002971061 Sunrise Energy, Inc. 1300 N Western Ave Los Angeles, CA, 90027	Distance: 0.2 mi Direction: N Lat, Lon: 34.0951, -118.3088
Owner/Operator: Marrall Bagerdjian	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Gasoline stations with convenience stores
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000182436 Exxonmobil Oil Corp 10422 1277 N. Western Avenue Los Angeles, CA, 90029	Distance: 0.2 mi Direction: N Lat, Lon: 34.0946, -118.3092
Owner/Operator: Exxonmobil Oil Corporation	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Gasoline stations with convenience stores
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID

We have answers.





REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAD980892285 Green Hornet Santa Monica 5601 Santa Monica Blvd Hollywood, CA, 90038	Distance: 0.2 mi Direction: W Lat, Lon: 34.0907, -118.3113
Owner/Operator: St Andrews Santa Monica Llc	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Motion picture and video production
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000379475 Smart & Final #363 939 N Western Ave Los Angeles, CA, 90029	Distance: 0.2 mi Direction: S Lat, Lon: 34.0880, -118.3097
Owner/Operator: Smart & Final Stores Corp	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Warehouse clubs and supercenters
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID

We have answers.

REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAC003014011 1353 Western Llc 1353 Western Ave. Los Angeles, CA, 90027	Distance: 0.3 mi Direction: N Lat, Lon: 34.0959, -118.3094
Owner/Operator: Pacific Pallisades	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	


RCRA SITE ID: CAC002970333 St. Andrews Second Home, Llc 1370 North St. Andrews Place Los Angeles, CA, 90028	Distance: 0.3 mi Direction: N Lat, Lon: 34.0965, -118.3105
Owner/Operator: St Andrews Second Home, Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

Return to Quickview

Have Questions?

Return to 1 Page NHDTM

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000413764 Motorsport Exotica Llc 1056 N Ridgewood Pl Los Angeles, CA, 90038	Distance: 0.3 mi Direction: W Lat, Lon: 34.0904, -118.3144
Owner/Operator: Motorsport Exotica Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000127993 Kingsley Elementary School 5200 W Virginia Ave Los Angeles, CA, 90029	Distance: 0.3 mi Direction: E Lat, Lon: 34.0919, -118.3025
Owner/Operator: Los Angeles Unified School Dist	Owner/Operator Type: District /
Land Type: District	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Elementary and secondary schools
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID





REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CA5180090479 Usps 1375 N Western Los Angeles, CA, 90027	Distance: 0.3 mi Direction: N Lat, Lon: 34.0964, -118.3096
Owner/Operator: Us Postal Svc	Owner/Operator Type: Federal /
Land Type: Federal	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities: Mixed waste generator	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD981450281 Deluxe Laboratories Inc 1377 N. Serrano Avenue Hollywood, CA, 90027	Distance: 0.3 mi Direction: N Lat, Lon: 34.0965, -118.3070
Owner/Operator: Deluxe Laboratories	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Other motion picture and video industries
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID



REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAD981575731 Photo Duc Inc 5704 Santa Monica Los Angeles, CA, 90038	Distance: 0.3 mi Direction: W Lat, Lon: 34.0907, -118.3138
Owner/Operator: Not Required	Owner/Operator Type: / Not provided
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000143483 M & M Auto Inc 1072 North Wilton Los Angeles, CA, 90038-0000	Distance: 0.3 mi Direction: W Lat, Lon: 34.0901, -118.3133
Owner/Operator: Mark Azeez	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAC002984000 St. Andrews Second Home, Llc 1370 North St. Andrews Place Los Angeles, CA, 90028	Distance: 0.3 mi Direction: N Lat, Lon: 34.0965, -118.3105
Owner/Operator: St. Andrews Second Home, Lc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD057352916 Superior Data/Graphics Corp 5717 Santa Monica Blvd Los Angeles, CA, 90038	Distance: 0.3 mi Direction: W Lat, Lon: 34.0907, -118.3142
Owner/Operator: J Wolford	Owner/Operator Type: Private /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000411931 Sally Beauty Supplies 5806 Santa Monica Blvd Los Angeles, CA, 90038	Distance: 0.4 mi Direction: W Lat, Lon: 34.0904, -118.3161
Owner/Operator: Sally Beauty Holding Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Cosmetics, beauty supplies, and perfume stores
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000447152	
La Car Repair Specialist Inc	Distance: 0.4 mi
5168 Fountain Ave	Direction: NE
Los Angeles, CA, 90029	Lat, Lon: 34.0948, -118.3019
Owner/Operator: Amihan Almerol	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Automotive body, paint, and interior repair and maintenance
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID

re







REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAR000090670 Santa Auto Center 5150 Santa Monica Blvd No A Los Angeles, CA, 90029-2428	Distance: 0.4 mi Direction: E Lat, Lon: 34.0908, -118.3021
Owner/Operator: Song I Choe	Owner/Operator Type: Private /
Land Type: County	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: Transporter /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	


RCRA SITE ID: CAC002987432 Guardian Advisors Llc 5814 La Mirada Ave Los Angeles, CA, 90038	Distance: 0.4 mi Direction: W Lat, Lon: 34.0935, -118.3162
Owner/Operator: Guardian Advisors Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAD981962772 La Fire Station 52 1010 N Van Ness Ave Los Angeles, CA, 90012	Distance: 0.4 mi Direction: W Lat, Lon: 34.0892, -118.3159
Owner/Operator: City Of La	Owner/Operator Type: Municipal /
Land Type: Other land type	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000099176 Professional Tire And Auto 811 N Western Ave Los Angeles, CA, 90029	Distance: 0.4 mi Direction: S Lat, Lon: 34.0852, -118.3091
Owner/Operator: Alan F Longacre	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAC003021404 Service Master 5500 W. Sunset Blvd. Los Angeles, CA, 90028	Distance: 0.4 mi Direction: N Lat, Lon: 34.0978, -118.3092
Owner/Operator: Service Master	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAC003024741 Target Corporation 5500 W Sunset Blvd Los Angeles, CA, 90028	Distance: 0.4 mi Direction: N Lat, Lon: 34.0978, -118.3092
Owner/Operator: Minneapolis Support Group	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID







REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAC002978295 5074 Romaine, LIc 5074 Romaine St Los Angeles, CA, 90029	Distance: 0.4 mi Direction: SE Lat, Lon: 34.0882, -118.3028
Owner/Operator: 5074 Romaine, Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000128975 Hollywood New Cont H S No 1 5755 Fountain Ave Hollywood, CA, 90028	Distance: 0.4 mi Direction: NW Lat, Lon: 34.0947, -118.3150
Owner/Operator: L A Unified School District	Owner/Operator Type: District /
Land Type: District	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAD982374795 Kordet Graphics West 5419 Sunset Blvd Los Angeles, CA, 90027	Distance: 0.4 mi Direction: N Lat, Lon: 34.0981, -118.3079
Owner/Operator: Robert Weiner	Owner/Operator Type: Municipal /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000128355 Bernstein High School 1309 Wilton Pl Hollywood, CA, 90028	Distance: 0.4 mi Direction: NW Lat, Lon: 34.0950, -118.3136
Owner/Operator: Lausd	Owner/Operator Type: District /
Land Type: District	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Elementary and secondary schools
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000435314 Hollywood Tires 5180 Fountain Ave Los Angeles, CA, 90029	Distance: 0.4 mi Direction: NE Lat, Lon: 34.0949, -118.3021
Owner/Operator: Miguel Maco	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000271659 Sherwin Williams Store #8249 883 N Western Ave Los Angeles, CA, 90029-3759	Distance: 0.4 mi Direction: S Lat, Lon: 34.0862, -118.3091
Owner/Operator: The Sherwin Williams Company	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Paint and wallpaper stores
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID

We have answers.



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000393178 O'reilly Auto Parts Store 3512 881 N Western Ave Los Angeles, CA, 90029	Distance: 0.4 mi Direction: S Lat, Lon: 34.0864, -118.3095
Owner/Operator: O'reilly Auto Parts	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Automotive parts and accessories stores
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD981624984 La Usd Santa Monica Elem 1022 N Van Ness Ave Los Angeles, CA, 90038	Distance: 0.4 mi Direction: W Lat, Lon: 34.0895, -118.3157
Owner/Operator: La Usd	Owner/Operator Type: District /
Land Type: Other land type	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Elementary and secondary schools
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID

NATS

REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)

	-
RCRA SITE ID: CAL000313383	
Happy Auto Center	Distance: 0.4 mi
870 N Western Ave Ste 2	Direction: S
Los Angeles, CA, 90029-3200	Lat, Lon: 34.0860, -118.3088
Owner/Operator: In So Park	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair
Misc Site Activities: On site universal waste destination, haz waste recycler, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000278015 Sarkis N Dabbagh 5165 Santa Monica Blvd Ste B Los Angeles, CA, 90029-2427	Distance: 0.4 mi Direction: E Lat, Lon: 34.0910, -118.3017
Owner/Operator: Sarkis N Dabbagh	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Offices of dentists
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID







REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000344137 Food 4 Less #362 5420 Sunset Blvd Hollywood, CA, 90027	Distance: 0.4 mi Direction: N Lat, Lon: 34.0981, -118.3084
Owner/Operator: Ralphs Grocery Co	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Supermarkets and other grocery (except convenience) stores
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000370639 Valvoline Instant Oil Change Gn0064 5317 W Sunset Blvd Los Angeles, CA, 90027-5611	Distance: 0.5 mi Direction: N Lat, Lon: 34.0984, -118.3064
Owner/Operator: Henley Pacific La Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other automotive repair and maintenance
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM











REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAL000369754 99 Cents Only Stores 5270 W Sunset Blvd Los Angeles, CA, 90027-5710	Distance: 0.5 mi Direction: NE Lat, Lon: 34.0976, -118.3050
Owner/Operator: 99 Cents Only Stores	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other general merchandise stores
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD982013518 Hollywood Radiator 5278 Sunset Hollywood, CA, 90027	Distance: 0.5 mi Direction: NE Lat, Lon: 34.0981, -118.3053
Owner/Operator: George Bonoughounian	Owner/Operator Type: Private /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAL000323476 Walgreens #7036 5451 W Sunset Blvd Los Angeles, CA, 90027	Distance: 0.5 mi Direction: N Lat, Lon: 34.0985, -118.3087
Owner/Operator: Sunset & Western Llc	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Pharmacies and drug stores
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAD084342716 Multi Lab 5333 Sunset Blvd Hollywood, CA, 90027	Distance: 0.5 mi Direction: N Lat, Lon: 34.0981, -118.3060
Owner/Operator: Wick Nacor	Owner/Operator Type: Private /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview













REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAD982010803 Service Auto Body & Repair 5624 Sunset Blvd Hollywood, CA, 90028	Distance: 0.5 mi Direction: N Lat, Lon: 34.0981, -118.3119
Owner/Operator: Corporation	Owner/Operator Type: Private /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CA0000138024 Paramount Studios Garage Trans 5675 Lemon Grove Los Angeles, CA, 90038	Distance: 0.5 mi Direction: SW Lat, Lon: 34.0871, -118.3149
Owner/Operator: Paramount Studios	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAR000167940 Home Depot 6616 5600 Sunset Blvd Hollywood, CA, 90028	Distance: 0.5 mi Direction: N Lat, Lon: 34.0981, -118.3114
Owner/Operator: Home Depot Usa	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Home centers
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000319491 Walgreens #7036 5451 W Sunset Blvd Los Angeles, CA, 90027	Distance: 0.5 mi Direction: N Lat, Lon: 34.0985, -118.3087
Owner/Operator: Sunset & Western Llc	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active /
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Pharmacies and drug stores
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA Site Details (continued)


RCRA SITE ID: CAL000398626 Apro Llc Dba United Oil #148 800 N Western Ave Los Angeles, CA, 90029	Distance: 0.5 mi Direction: S Lat, Lon: 34.0846, -118.3089
Owner/Operator: Apro Llc	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Other gasoline stations
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

RCRA SITE ID: CAL000418719	
Sunset Auto Repair Inc	Distance: 0.5 mi
5280 W Sunset Blvd	Direction: NE
Los Angeles, CA, 90027	Lat, Lon: 34.0979, -118.3051
Owner/Operator: Guillermo Avila	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General automotive repair
Misc Site Activities: Haz waste recycler, on site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHD™

Property ID









REPORT #: 4074593 REPORT DATE: 3/24/2025

RCRA Site Details (continued)

RCRA SITE ID: CAC002967105 Min Kyung Yoon 5430 Monroe St. Los Angeles, CA, 90038	Distance: 0.5 mi Direction: SW Lat, Lon: 34.0855, -118.3125
Owner/Operator: Min Kyung Yoon	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: On site universal waste destination, universal waste generator or receiver	
Active Site Activities: Handler activities	

EnviroStor Site Details

The California Department of Toxic Substances Control (DTSC) has developed the EnviroStor database system with information about sites that are known to be contaminated with hazardous substances as well as information on uncharacterized properties where further studies may reveal problems, including but not limited to, sites or facilities where DTSC is involved with site investigation or cleanup that fit the broad federal definition of brownfields. Brownfields are properties that are contaminated, or thought to be contaminated, and are underutilized due to perceived remediation costs and/or liability concerns. The EnviroStor database is used by the Site Mitigation and Brownfield Reuse Program's staff as a tool to evaluate and track activities at properties that may have been affected by the release of hazardous substances.

Further information can be found at the following locations:

http://www.envirostor.dtsc.ca.gov/public/EnviroStor%20FAQ.pdf


https://www.waterboards.ca.gov/water_issues/programs/brownfields

This report lists EnviroStor sites identified as being within 1/2 mile of Subject Property, if any are found.

Return to Quickview

Return to 1 Page NHDTM

Property ID



REPORT #: 4074593 | REPORT DATE: 3/24/2025

EnviroStor Site Details (continued)


EnviroStor ID: 60000058	
Central Region Middle School #5 Fountain Avenue/Serrano Avenue Los Angeles, CA 90029	Distance: 0.2 mi Direction: N Lat, Lon: 34.0945, -118.3084
NPL Status: No	Site Type: School Cleanup
Regulatory Agency: Smbrp	Site Status: Inactive - Action Required
Lead Agency: Smbrp	Status Date: 2006-01-18
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: Soil, Indoor Air, Soil Vapor	
Past Uses: Residential Area	
Potential Contaminants: Methyl Tertbutyl Ether (Mtbe), Polychlorinated Biphenyls (Pcbs), Lead, Benzene, Tetrachloroethylene (Pce)	
Confirmed Contaminants: None Specified	

EnviroStor ID: 19880046	
Ramona Primary Site No. 3 Oxford Avenue/Romaine Avenue/Serrano Ave Los Angeles, CA 90029	Distance: 0.2 mi Direction: SE Lat, Lon: 34.0884, -118.3069
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Withdrawn
Lead Agency: Smbrp	Status Date: 2000-02-10
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	
Confirmed Contaminants: None Specified	

EnviroStor ID: 19880049	
Belmont/Hollywood No. 3 La Mirada Avenue/Serrano Avenue Los Angeles, CA 90029	Distance: 0.2 mi Direction: NE Lat, Lon: 34.0938, -118.3059
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Needs Evaluation
Lead Agency: Smbrp	Status Date: 2000-02-11

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 REPORT DATE: 3/24/2025

EnviroStor Site Details (continued)

Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	
Confirmed Contaminants: None Specified	

EnviroStor ID: 19880060	
Santa Monica/Vine Primary Site No. 3a La Mirada Ave/Lexington Ave/Wilton Place Los Angeles, CA 90038	Distance: 0.2 mi Direction: W Lat, Lon: 34.0927, -118.3126
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Withdrawn
Lead Agency: Smbrp	Status Date: 2002-08-20
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	
Confirmed Contaminants: None Specified	

EnviroStor ID: 19880059	
Santa Monica/Vine Primary Site No. 3 La Mirada Ave/Lexington Ave/Wilton Place Los Angeles, CA 90038	Distance: 0.2 mi Direction: W Lat, Lon: 34.0927, -118.3126
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Withdrawn
Lead Agency: Smbrp	Status Date: 2002-08-20
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	
Confirmed Contaminants: None Specified	

Return to Quickview

Return to 1 Page NHDTM

Property ID

We have answers.

REPORT #: 4074593 | REPORT DATE: 3/24/2025

EnviroStor Site Details (continued)


EnviroStor ID: 19880070	
Ramona Primary Site No. 6 Oxford Avenue/Romaine Avenue/Serrano Ave Los Angeles, CA 90029	Distance: 0.2 mi Direction: SE Lat, Lon: 34.0884, -118.3069
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Withdrawn
Lead Agency: Smbrp	Status Date: 2013-02-20
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: Soil	
Past Uses: Residential Area	
Potential Contaminants: Under Investigation	
Confirmed Contaminants: None Specified	

EnviroStor ID: 60002458		
Proposed Cfa Restaurant 3798	Distance: 0.2 mi	
1011 N. Western Avenue	Direction: S	
Los Angeles, CA 90029	Lat, Lon: 34.0890, -118.3094	
NPL Status: No	Site Type: Voluntary Cleanup	
Regulatory Agency: Smbrp	Site Status: Active	
Lead Agency: Smbrp	Status Date: 2016-12-07	
Special Program: Voluntary Agreement - Standard Voluntary Agreement	Site Management:	
Funding: Responsible Party	Restricted Use: Yes	
Potential Media Affected: Soil Vapor, Under Investigation		
Past Uses: Dry Cleaning		
Potential Contaminants: Tetrachloroethylene (Pce), Vinyl Chloride		
Confirmed Contaminants: Tetrachloroethylene (Pce), Vinyl Chloride		

EnviroStor ID: 19790003	
Ramona New Pc Aka Bowling Alley Santa Monica Boulevard/Kingsley Drive Los Angeles, CA 90029	Distance: 0.3 mi Direction: E Lat, Lon: 34.0907, -118.3032
NPL Status: No	Site Type: School Cleanup
Regulatory Agency: Smbrp	Site Status: No Further Action
Lead Agency: Smbrp	Status Date: 2002-05-17

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

EnviroStor Site Details (continued)

Special Program:	Site Management:	
Funding: School District	Restricted Use: No	
Potential Media Affected: Soil		
Past Uses: Recreation Services		
Potential Contaminants: Dichlorodifluoromethane, 1,3,5-Trimethylbenzene, Ethylbenzene, Benzene, Molybdenum, Tetrachloroethylene (Pce), Cobalt, Toluene, Xylenes, 1,2,4-Trimethylbenzene, Methylphenol, Chloroform, Chloromethane (Methyl Chloride)		
Confirmed Contaminants: None Specified		

EnviroStor ID: 60001863		
Deluxe Laboratories 1377 N. Serrano Avenue	Distance: 0.3 mi Direction: N	
Los Angeles, CA 90027	Lat, Lon: 34.0957, -118.3087	
NPL Status: No	Site Type: Evaluation	
Regulatory Agency: Smbrp, Los Angeles County	Site Status: Refer: 1248 Local Agency	
Lead Agency: Los Angeles County	Status Date: 2014-05-09	
Special Program:	Site Management:	
Funding: Epa Grant	Restricted Use: No	
Potential Media Affected: Indoor Air, Aquifer Used For Drinking Water Supply Affected, Soil, Under Investigation, Well Used For Drinking Water Supply Affected, Soil Vapor		
Past Uses: Photographic Processing		
Potential Contaminants: Tetrachloroethylene (Pce), Under Investigation		
Confirmed Contaminants: None Specified		

EnviroStor ID: 19880048	
Belmont/Hollywood No. 2 Harvard Boulevard/Romaine Street/Kingsley Drive Los Angeles, CA 90029	Distance: 0.4 mi Direction: SE Lat, Lon: 34.0884, -118.3031
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Needs Evaluation
Lead Agency: Smbrp	Status Date: 2000-02-11
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

EnviroStor Site Details (continued)

Confirmed Contaminants: None Specified


EnviroStor ID: 19820083 Distance: 0.4 mi Ramona Primary Site No. 1 Direction: NE Hobart Boulevard/Fountain Avenue/Harvard Blvd. Lat, Lon: 34.0950, -118.3037 Los Angeles, CA 90029 NPL Status: No Site Type: School Investigation Regulatory Agency: Smbrp Site Status: Inactive - Withdrawn Lead Agency: Smbrp Status Date: 2000-02-10 Special Program: Site Management: Funding: School District Restricted Use: No Potential Media Affected: None Specified Past Uses: Educational Services Potential Contaminants: None Specified Confirmed Contaminants: None Specified

EnviroStor ID: 19880045	
Ramona Primary Site No. 2 Kingsley Drive/Romaine Avenue/Ardmore Ave Los Angeles, CA 90029	Distance: 0.4 mi Direction: SE Lat, Lon: 34.0884, -118.3023
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Withdrawn
Lead Agency: Smbrp	Status Date: 2000-02-10
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	
Confirmed Contaminants: None Specified	

EnviroStor ID: 19880057	
Santa Monica/Vine Primary Site No. 10 Fountain Ave/Van Ness Ave/Wilton Place Los Angeles, CA 90028	Distance: 0.4 mi Direction: NW Lat, Lon: 34.0946, -118.3148
NPL Status: No	Site Type: School Investigation
Regulatory Agency: Smbrp	Site Status: Inactive - Withdrawn

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

EnviroStor Site Details (continued)

Lead Agency: Smbrp	Status Date: 2013-02-20
Special Program:	Site Management:
Funding: School District	Restricted Use: No
Potential Media Affected: None Specified	
Past Uses: Residential Area	
Potential Contaminants: None Specified	
Confirmed Contaminants: None Specified	

EnviroStor ID: 60003365	
Jasmine Cleaners 5409 Sunset Blvd Los Angeles, CA 90027	Distance: 0.5 mi Direction: N Lat, Lon: 34.0984, -118.3076
NPL Status: No	Site Type: Voluntary Cleanup
Regulatory Agency: Smbrp	Site Status: Active
Lead Agency: Smbrp	Status Date: 2022-04-01
Special Program: Voluntary Agreement - Standard Voluntary Agreement	Site Management:
Funding: Responsible Party	Restricted Use: No
Potential Media Affected: Soil Vapor	

Potential Contaminants: Trichloroethylene (Tce), 1,2-Dichloroethylene (Trans), Tetrachloroethylene (Pce),

1,1-Dichloroethylene, Vinyl Chloride, 1,2-Dichloroethylene (Cis)

Past Uses: Dry Cleaning

Confirmed Contaminants: 1,1-Dichloroethylene-Not Confirmed Above Risk Level, 1,2-Dichloroethylene (Cis)-Not Confirmed Above Risk Level, Vinyl Chloride-Not Confirmed Above Risk Level,

Tetrachloroethylene (Pce)-Not Confirmed Above Risk Level, 1,2-Dichloroethylene (Trans)-Not Confirmed


Above Risk Level, Trichloroethylene (Tce)-Not Confirmed Above Risk Level

Return to Quickview

Return to 1 Page NHDTM











REPORT #: 4074593 | REPORT DATE: 3/24/2025

SWIS Site Details

The Solid Waste Information System (SWIS) database is provided by the California Department of Resources and Recycling and Recovery (CalRecycle). The SWIS database contains information on regulated solid waste facilities, operations, and disposal sites throughout the State of California. The types of facilities found in this database include landfills, transfer stations, material recovery facilities, composting sites, transformation facilities, waste tire sites, and closed disposal sites. For more information contact CalRecycle at: Tel: (916) 322-4027, email: Cody.Oquendo@CalRecycle.ca.gov, and URL: http://www.calrecycle.ca.gov/SWFacilities/Directory.

This report lists SWIS sites identified as being within 1/2 mile of Subject Property, if any are found.

NO MAPPED SWIS SITES WERE FOUND IN PROXIMITY OF THE SUBJECT PROPERTY

GeoTracker Site Details

The GeoTracker is the State Water Board's system for managing sites that impact groundwater, especially those that require groundwater cleanup such as Leaking Underground Storage Tanks (LUST), Site Cleanup Program Sites, and Military Cleanup Sites. The GeoTracker system is also used to manage permitted facilities like land disposal sites. The sites monitored by the State Water Board through the GeoTracker system may currently have, or have had in the past, unauthorized releases (leaks) that can pose a danger to public health and the environment. Cleanup of soil and groundwater contamination is overseen by the State Water Board based on application of existing laws, regulations, plans, and policies.. Additional the State Water Board's GeoTracker information available on website http://geotracker.waterboards.ca.gov/.


This report lists GeoTracker sites identified as being within 1/2 mile of Subject Property, if any are found.

	3 1 37
GLOBAL ID: T0603700773	
EXXON #7-3233 (FORMER) 1075 WESTERN AVE N LOS ANGELES, CA 90029	Distance: 0.10 mi Direction: SW
Case Type: LUST Cleanup Site	Case Open Date: 1988-05-26 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 1998-04-28 00:00:00
Regional Board:	Regional Case No.: 900290107
Local Agency: LOS ANGELES, CITY OF	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4	4)
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Gasoline	
Site History:	

Return to Quickview


Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

GeoTracker Site Details (continued)

GLOBAL ID: T0603739186	
76 STATION #3739	Distance: 0.2 mi
1300 WESTERN AVE. N.	Direction: N
LOS ANGELES, CA 90027	
Case Type: LUST Cleanup Site	Case Open Date: 1997-10-01 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 2009-11-19 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900270252
Local Agency: LOS ANGELES, CITY OF	Local Case No.: 10715
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Gasoline	
Site History:	

GLOBAL ID: T10000010304	
CALTRANS PUMPING STATION 1260 SAINT ANDREWS PLACE N. LOS ANGELES, CA 90038	Distance: 0.2 mi Direction: NW
Case Type: LUST Cleanup Site	Case Open Date: 2017-04-07 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 2023-07-25 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900380170A
Local Agency:	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Data d'al Marilla Affrada de Arriga de del del del del del del del del del	

Potential Media Affected: Aquifer used for drinking water supply


Potential Contaminants: Gasoline

Site History: Caltrans had maintained a 100-gallon gasoline UST for this stormwater pumping station for about 30 years until its removal in 1989. Gasoline was observed to be leaking from small holes in the bottom of the UST when it was removed. Soil sampling in September 1989 identified petroleum impacts directly beneath the UST, while three deeper soil borings in January 1990 detected petroleum impacts especially at 15 feet below ground surface (bgs), which was just above the groundwater table of 16-17 feet bgs that was encountered when the three borings were drilled. The maximum concentrations of total petroleum hydrocarbons as gasoline (TPHG), benzene, toluene, ethylbenzene, and xylenes in the ten soil samples collected in September 1989 and January 1990 were 3,040 milligrams per kilogram (mg/kg) (TPHG), 55.7 mg/kg (benzene), 434 mg/kg (toluene), 120 mg/kg (ethylbenzene), and 740 mg/kg (xylenes), respectively. Caltrans and their consultant submitted a work plan in May 1990 for installation of three groundwater monitoring wells and associated soil sampling, and the Regional Board approved the work plan on June 1, 1990; however, Caltrans never installed these groundwater monitoring wells. The Regional Board closure form incorrectly stated that the soil contamination was highest at 5-10 feet

Return to Quickview

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

GeoTracker Site Details (continued)

bgs, but concentrations in soil at 15 feet bgs were higher than at 5 or 10 feet bgs. In 2016, the Former Gas-To-Go UST case (1353 Western Ave) found free product in monitoring wells MW-23, located just 50 feet away from the former Caltrans pumping station, so this historical case was re-opened.

GLOBAL ID: T0603766903	
CHEVRON STATION #8-8723 (FORMER STATION) 1276 WESTERN AVE. N. LOS ANGELES, CA 90029	Distance: 0.2 mi Direction: N
Case Type: LUST Cleanup Site	Case Open Date: 2005-06-13 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 2009-01-30 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900290052A
Local Agency: LOS ANGELES, CITY OF	Local Case No.: 212
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Tetrachloroethylene (PCE)	
Site History:	

GLOBAL ID: T0603729935		
FORMER MOBIL #18-H5D	Distance: 0.2 mi	
1277 WESTERN AVE. N. LOS ANGELES, CA 90029	Direction: N	
Case Type: LUST Cleanup Site	Case Open Date: 2002-11-21 00:00:00	
Recent Activity: Completed - Case Closed	Recent Activity Date: 2012-07-02 00:00:00	
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900290207	
Local Agency: LOS ANGELES, CITY OF	Local Case No.: 10714	
Lead Agency: LOS ANGELES RWQCB (REGION 4)		
Potential Media Affected: Aquifer used for drinking water supply		
Potential Contaminants: Gasoline		
Site History:		

GLOBAL ID: T0603700768	
CHEVRON #9-8723 1276 WESTERN AVE N	Distance: 0.2 mi Direction: N
LOS ANGELES, CA 90029	
Case Type: LUST Cleanup Site	Case Open Date: 1987-10-07 00:00:00

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

GeoTracker Site Details (continued)

	,
Recent Activity: Completed - Case Closed	Recent Activity Date: 1996-09-18 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900290052
Local Agency: LOS ANGELES, CITY OF	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Gasoline	
Site History:	

GLOBAL ID: T0603700928	
CALTRANS	Distance: 0.2 mi
1260 SAINT ANDREWS PL N	Direction: NW
HOLLYWOOD, CA 90038	
Case Type: LUST Cleanup Site	Case Open Date: 1990-02-01 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 1996-09-03 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900380170
Local Agency: LOS ANGELES, CITY OF	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Gasoline	
Site History:	

GLOBAL ID: UST100019230	
SUNRISE ENERGY #253739	Distance: 0.2 mi
1300 N WESTERN AVE	Direction: N
LOS ANGELES, CA 90027	
Case Type: Single-Walled UST	Case Open Date:
Recent Activity: SWT-No Plan Returned	Recent Activity Date: 2022-05-02 00:00:00
Regional Board:	Regional Case No.:
Local Agency:	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected:	
Potential Contaminants: Gasoline, Diesel	
Site History:	

Return to Quickview Return to 1 Page NHDTM









REPORT #: 4074593 | REPORT DATE: 3/24/2025

GeoTracker Site Details (continued)


GLOBAL ID: T0603700757	
USPS LA NORTH VEHICLE MAINT. 1375 WESTERN AVE N LOS ANGELES, CA 90028	Distance: 0.3 mi Direction: N
Case Type: LUST Cleanup Site	Case Open Date: 1990-01-01 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 2000-02-09 00:00:00
Regional Board:	Regional Case No.: 900280089
Local Agency: LOS ANGELES, CITY OF	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Gasoline	
Site History:	

GLOBAL ID: T0603742795	
GAS TO GO (FORMER) 1353 WESTERN AVE. N. LOS ANGELES, CA 90027	Distance: 0.3 mi Direction: N
Case Type: LUST Cleanup Site	Case Open Date: 1999-01-29 00:00:00
Recent Activity: Open - Remediation	Recent Activity Date: 2008-05-30 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900270243
Local Agency: LOS ANGELES, CITY OF	Local Case No.: 29668
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Diesel, Gasoline	
Site History:	

GLOBAL ID: SLT43206204	
DELUXE LABORATORIES 1377 N. SERRANO AVE	Distance: 0.3 mi Direction: N
HOLLYWOOD, CA 90027	Casa Open Date:
Case Type: Cleanup Program Site	Case Open Date:
Recent Activity: Completed - Case Closed	Recent Activity Date: 2015-09-08 00:00:00
Regional Board:	Regional Case No.:
Local Agency: LOS ANGELES COUNTY	Local Case No.:
Lead Agency:	

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

GeoTracker Site Details (continued)

Potential Media Affected:	
Potential Contaminants:	
Site History:	


GLOBAL ID: T0603700922	
SANTA MONICA BLVD ELM SCHOOL	Distance: 0.4 mi
1022 VAN NESS AVE N	Direction: W
HOLLYWOOD, CA 90038	
Case Type: LUST Cleanup Site	Case Open Date: 1991-06-21 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 1996-07-25 00:00:00
Regional Board: LOS ANGELES RWQCB (REGION 4)	Regional Case No.: 900380116
Local Agency: LOS ANGELES, CITY OF	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Soil	
Potential Contaminants: Other Solvent or Non-Petroleum Hydrocarbon	
Site History:	

GLOBAL ID: T0603700770	
SUPER CAR WASH 800 WESTERN AVE N	Distance: 0.5 mi Direction: S
LOS ANGELES, CA 90029	
Case Type: LUST Cleanup Site	Case Open Date: 1991-11-18 00:00:00
Recent Activity: Completed - Case Closed	Recent Activity Date: 2006-07-18 00:00:00
Regional Board:	Regional Case No.: 900290070
Local Agency: LOS ANGELES, CITY OF	Local Case No.:
Lead Agency: LOS ANGELES RWQCB (REGION 4)	
Potential Media Affected: Aquifer used for drinking water supply	
Potential Contaminants: Gasoline	
Site History:	

UNMAPPED SITES

Return to Quickview Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

Although the Environmental Site records are official, some of the records may contain missing, non-specific, or incorrect information regarding the names, addresses or other attributes, due to errors and omissions prior to their submission to the governing regulatory body. This factor prevents some sites from being precisely located. It is for this reason that a site may be listed in this "unmapped sites" section of the report.

The information in the environmental report comes directly from the official hazardous substance site lists, which include sites with incomplete information as well. Accordingly, Property I.D. includes those unmapped sites that may or may not be within one half-mile of the Subject Property, based upon the available information provided by the EPA and/or other regulatory bodies.

NPL/SEMS - Unmapped Site Details

EPA ID: CAN000909340 MAIN STREET ABANDONED DRUMS SOUTH MAIN AND 60TH STREET LOS ANGELES, CA,	Distance: (exact location not mapped) Direction: (exact location not mapped)
Region: 9.00000000	Active Site Indicator: Active
Site Status: Active	Federal Facility: No
NPL Status: Not NPL	Ready for Use: No
Non-NPL Status: Referred to Cleanup Program	Native American Interest: No
Non-NPL Status Sub Category: Submitted to or	Ecological Contaminant Concern: No
Non-NPL Status Date: 2011-08-12	Human Health Concern: No
Partial NPL Deletion: No	Human Exposure: Status Unavailable
Site Type: Other	Groundwater Mitigation: Status Unavailable
Site Type Sub Category: Spill or other one-time event	SAA: No
Contaminant Media:	
Contaminants:	

Return to Quickview







REPORT DATE: 3/24/2025



RCRA - Unmapped Site Details

RCRA SITE ID: CAP000035576 Home Savings Of America 5123 Marathon St Los Angeles, CA, 90038	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Home Savings Of America	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000074591 Giffith Park Boys Camp 4730 1/2 Crystal Springs Dr Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: City Of L A Dept Of Rec	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAP000121640 Griffith Park Merry Go Round Crystal Springs Dr And Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: City Of Los Angeles	Owner/Operator Type: Municipal /
Land Type: Municipal	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000081364 Shanes Inspiration 480 Griffith Park Dr Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: City Of L A Dept Rec Parks	Owner/Operator Type: Municipal /
Land Type: Municipal	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











ENVIRONMENTAL



RCRA SITE ID: CAP000291120 Construction On State Hwy For Safety Improvement Nb 5 Fwy (34.04 N, 118.21 W) Los Angeles, CA, 90029	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: State Of California	Owner/Operator Type: State /
Land Type: State	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Highway, street, and bridge construction
Misc Site Activities: Short-term generator	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000038141 El Capitan Theater 6834 Hollywood Blvd Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Cuna Mutual Life Insurance	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAP000037838 Home Savings Of America 1812 N Gramercy PI Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Home Savings Of America	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000056416 Tregnan Youth Golf Academy 4341 Griffith Park Dr Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: City Of L A Dept Of Rec And Parks	Owner/Operator Type: Municipal /
Land Type: Municipal	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview









REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAP000329698 Alsco Linen La (Brenntag) 900 N Highland Ave Los Angeles, CA, 90038	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Brenntag Pacific	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Drycleaning and laundry services (except coin-operated), other chemical and allied products merchant wholesalers
Misc Site Activities: Short-term generator	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000306894 Po Sunset, Llc 6200 W. Sunset Blvd. Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Po Sunset, Llc	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Site preparation contractors
Misc Site Activities: Short-term generator	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAP000032664 Home Savings Of America 6046_52 Romaine St Los Angeles, CA, 90038	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Home Savings Of America	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000065201 Lemon Grove Recreation Ctr 4959 Lemon Grove Ave Los Angeles, CA, 90029	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: City Of La Dept Of Rec And Parks	Owner/Operator Type: Municipal /
Land Type: Municipal	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)


RCRA SITE ID: CAR000318725 Target Store T3346 7021 Hollywood Blvd Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Street Retail West 7 L.P.	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000329219 L.A. Shares 3226 Riverside Dr. Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: City Of Los Angeles, Department Of Recreation And Parks	Owner/Operator Type: Municipal /
Land Type: Municipal	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: General warehousing and storage
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAR000320788 Last Good Film Lab 5427 Santa Monica Blvd Los Angeles, CA, 90029	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Damon Romero	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active /
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Photographic services
Misc Site Activities: Haz waste importer, haz waste recycler, haz waste transporter	
Active Site Activities: Handler activities	

RCRA SITE ID: CAC003011842 Aimee Gregory 4345 La Mirada Ave Los Angeles, CA, 90029	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Aimee Gregory	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview







REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)


RCRA SITE ID: CAP000294439 Project 07-296404 On State Hwy For Safety Distance: (exact location not mapped) Improvement Direction: (exact location not mapped) Nb 5 Fwy Sta 885+40 To 859+33 And Sb 5 Fwy Sta 865 Los Angeles, CA, 90029 Owner/Operator: Caltrans Owner/Operator Type: State / Land Type: State Activity/Generator Status: Active / Large quantity generator Environmental Controls: Environmental controls not Institutional Controls: in place Ground Water Controls: Groundwater controls not Human Exposure Controls: Human exposure not in place under control Industrial Activity Classification: Highway, street, Used Oil/Haz. Waste Type: / and bridge construction Misc Site Activities: Short-term generator Active Site Activities: Handler activities

RCRA SITE ID: CAC003017116 Craig Berberian 749/751 N El Centro Ave Los Angeles, CA, 90038	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Craig Berberian	Owner/Operator Type: Other /
Land Type: Not provided, though not located on indian land	Activity/Generator Status: Active / Not a generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: All other waste management services
Misc Site Activities: Universal waste generator or receiver, on site universal waste destination	
Active Site Activities: Handler activities	

Return to Quickview

Return to 1 Page NHDTM

Property ID







REPORT #: 4074593

REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)


RCRA SITE ID: CAR000316091 leh Auto Parts, Llc Dba Auto Plus #604 6125 Hollywood Boulevard Hollywood, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Shawn Nourafshan, Ivy Glen Properties Llc, C/O Reliable Properties	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Automotive parts and accessories stores
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000309070 Former Hyperion Cleaners 2829 Hyperion Avenue Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Frank Oh, Thomas Oh	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Lessors of nonresidential buildings (except miniwarehouses)
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAR000319020 Cvs Pharmacy 17794 5500 West Sunset Boulevard, Suite B Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Target Corporation	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active /
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Pharmacies and drug stores
Misc Site Activities:	
Active Site Activities: Handler activities	

RCRA SITE ID: CAP000071480 American Academy Of Dramatic Arts 1336 N La Brea Ave Holllywood, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: American Academy Of Dramatic Arts	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Small quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAP000334888 Television Center 6311 Romaine Street Los Angeles, CA, 90038	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Blt Cole Llc And Berdan Cole Llc	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Remediation services, motion picture and video production
Misc Site Activities: Short-term generator	
Active Site Activities: Handler activities	

RCRA SITE ID: CAR000313098 Target Store T2479 5500 W Sunset Blvd Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: The Chin Trust	Owner/Operator Type: Private /
Land Type: Private	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)


RCRA SITE ID: CAP000041707 Home Savings Of America 4233 39 Burns Ave Los Angeles, CA, 90029	Distance: (exact location not mapped) Direction: (exact location not mapped)				
Owner/Operator: Home Savings Of America	Owner/Operator Type: Private /				
Land Type: Private	Activity/Generator Status: Active / Small quantity generator				
Institutional Controls:	Environmental Controls: Environmental controls not in place				
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control				
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:				
Misc Site Activities:					
Active Site Activities: Handler activities					

RCRA SITE ID: CAR000326777 Cooper Properties 6075 Franklin Ave Los Angeles, CA, 90028	Distance: (exact location not mapped) Direction: (exact location not mapped)
Owner/Operator: Diane Cooper	Owner/Operator Type: Federal /
Land Type: Federal	Activity/Generator Status: Active / Large quantity generator
Institutional Controls:	Environmental Controls: Environmental controls not in place
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control
Used Oil/Haz. Waste Type: /	Industrial Activity Classification: Residential property managers
Misc Site Activities:	
Active Site Activities: Handler activities	

Return to Quickview











REPORT #: 4074593 | REPORT DATE: 3/24/2025

RCRA - Unmapped Site Details (continued)

RCRA SITE ID: CAP000074732 L A Orphans Home Society 815 N El Centro Ave Los Angeles, CA, 90038	Distance: (exact location not mapped) Direction: (exact location not mapped)				
Owner/Operator: L A Orphans Home Society	Owner/Operator Type: Private /				
Land Type: Private	Activity/Generator Status: Active / Small quantity generator				
Institutional Controls:	Environmental Controls: Environmental controls not in place				
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control				
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:				
Misc Site Activities:					
Active Site Activities: Handler activities					

RCRA SITE ID: CAP000053298 Griffith Park Traveltown 5200 W Zoo Dr Los Angeles, CA, 90027	Distance: (exact location not mapped) Direction: (exact location not mapped)			
Owner/Operator: City Of L A Dept Of Rec	Owner/Operator Type: Municipal /			
Land Type: Municipal	Activity/Generator Status: Active / Small quantity generator			
Institutional Controls:	Environmental Controls: Environmental controls not in place			
Ground Water Controls: Groundwater controls not in place	Human Exposure Controls: Human exposure not under control			
Used Oil/Haz. Waste Type: /	Industrial Activity Classification:			
Misc Site Activities:				
Active Site Activities: Handler activities				

Return to Quickview









REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES

<u>BUILDING ENERGY USE BENCHMARKING AND PUBLIC DISCLOSURE</u> <u>PROGRAM</u>

Assembly Bill 802 (Williams, 2015) directed the California Energy Commission to create a statewide building energy use benchmarking and public disclosure program for buildings larger than 50,000 square feet. The Commission's regulations require building owners to report building characteristic information and energy use data to the Commission by June 1 annually, beginning in 2018 for buildings with no residential utility accounts, and in 2019 for buildings with 17 or more residential utility accounts. Building owners will complete their reporting using ENERGY STAR Portfolio Manager, a free online tool provided by the United States Environmental Protection Agency.

Assembly Bill 802 also requires, effective January 1, 2017, that energy utilities provide building-level energy use data to building owners, owners' agents, and operators upon request for buildings with no residential utility accounts and for buildings with five or more utility accounts.

The Energy Commission will publicly disclose some of the reported information beginning in 2019 for buildings with no residential utility accounts, and 2020 for buildings with residential utility accounts.

Assembly Bill 802, Chapter 590:

http://energy.ca.gov/benchmarking/documents/AB_802_chapter_590.pdf

Building Energy Benchmarking Regulations:

http://docketpublic.energy.ca.gov/PublicDocuments/15-OIR-05/TN222916_20180307T143335_California_Benchmarking_Regulations_Final_20180301.pdf

ENERGY STAR Portfolio Manager:

https://www.energystar.gov/buildings/facility-owners-and-managers/existing-buildings/use-portfolio-manager

For further information, please visit http://www.energy.ca.gov/benchmarking/, or contact the CA Energy Commission Benchmarking Hotline at (855) 279-6460, or by email at Erik.Jensen@energy.ca.gov.

You may also contact the U.S. Environmental Protection Agency Energy Star Program for further information on Benchmarking and energy use at the following sites:

http://www.energystar.gov/buildings/index.cfm

http://www.energystar.gov/

Local Benchmarking and Public Disclosure Programs

The cities of San Francisco, Berkeley, and Los Angeles have local benchmarking and public disclosure programs whose requirements exceed those of the state program. Per the state regulations, a local jurisdiction may request that the Energy Commission provide an exemption from the state reporting requirement for buildings located in the local jurisdiction. If the exemption is approved, the owners of buildings in that jurisdiction may report to the local jurisdiction only, and will not be required to report to the Commission.

City of Los Angeles Local Disclosure Program: http://www.betterbuildingsla.com/

Return to Quickview

Return to 1 Page NHD™


Property ID

e answers









REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES (continued)

METHAMPHETAMINE & FENTANYL CONTAMINATION

Methamphetamine and Fentanyl use and production are growing throughout the State of California. Properties may be contaminated by hazardous chemicals used or produced in the manufacture of methamphetamine or fentanyl where those chemicals remain and where the contamination has not been remediated. Once the methamphetamine or fentanyl laboratories have been closed, the public may be harmed by the material and residues that remain.

Because the methamphetamine and fentanyl manufacturing processes lead to chemical contamination, the Methamphetamine or Fentanyl Contaminated Property Cleanup Act requires a property owner to disclose in writing to a prospective buyer if local health officials have issued an order prohibiting the use or occupancy of a property contaminated by methamphetamine or fentanyl laboratory activity. The owner must also provide the buyer with a copy of the pending order to acknowledge receipt in writing. Property owner(s) must retain a methamphetamine laboratory site remediation firm that is an authorized contractor meeting certain requirements, as defined, to remediate the contamination caused by a methamphetamine or fentanyl laboratory activity. Civil penalties up to \$5,000 can be imposed upon a property owner who does not provide a notice or disclosure required by the act, or upon a person who violates an order issued by the local health officer prohibiting use or occupancy of a property contaminated by a methamphetamine or fentanyl laboratory activity. In addition, local health and law enforcement agencies are required to take specified action, including the filing of a lien against a property for cleanup of the contamination.

Realtors and Property I.D. do not have the requisite expertise to determine the need for testing or cleanup of methamphetamine or fentanyl contamination and cannot verify the information provided about such contamination by others.

<u> MEGAN'S LAW - SEX OFFENDER DATABASE</u>

Pursuant to Section 290.46 of the Penal Code, information about specified registered sex offenders is made available to the public via an Internet website maintained by the Department of Justice at www.meganslaw.ca.gov. This site provides access to information on persons required to register in California as sex offenders. Specific home addresses are displayed for many offenders in the California communities; as to these persons, the site displays the last registered address reported by the offender. Additional offenders are included on the site with listing by ZIP Code, city, and county. Information on other offenders is not included on this site, but is known to law enforcement personnel.

The California Legislature has created this statewide website to enable the public to secure information regarding the location of registered sex offenders. Anyone who is interested in this information should go on-line at www.meganslaw.ca.gov prior to removing their inspection contingency. Brokers and Property I.D. cannot and will not verify the information provided by the Government. Neither Brokers nor Property I.D. make any representations or guarantees as to the timeliness or accuracy of the information supplied at this website.

MOLD NOTICE

Return to Quickview

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES (continued)

Mold is a kind of microscopic organism found nearly everywhere, indoors and outdoors, wherever moisture is present. Mold growing on surfaces can look like a stain, be fuzzy or slimy, in a variety of patterns. Typically, mold is white, gray, brown, or black, but can also be green, red, or other colors. To grow and reproduce, mold only needs moisture and organic matter, such as leaves, wood, paper, or even dust.

As organic matter is present in nearly any home, prospective purchasers are advised to thoroughly inspect the property for signs of mold, excessive moisture, water leaks, and evidence of previous water damage. Musty odors can be a sign of current or prior mold presence, and should mold be found, remediation should be completed. Without remediation, mold exposure can lead to a multitude of health problems, such as hay fever, asthma, and respiratory infections.

For more information on Mold and Moisture in the home, please see the government booklet "Mold in My Home: What Do I Do?", for which a link is included at the end of this report on the "Government Booklets, Handouts, and Safety Guides" page.

Note: Realtors and Property I.D. do not have the requisite expertise to determine the need for testing or cleanup of mold contamination and cannot verify the information provided about such contamination by others.

ABANDONED WELLS

The Department of Water Resources estimates that there are approximately 750,000 water wells scattered throughout the State of California - some of these wells are abandoned. Wells that have been abandoned pose a serious threat to the safety of humans, especially children, and to animals. Section 24400 of the California Health and Safety Code requires that abandoned excavations be fenced, covered, or filled. In addition, abandoned wells may act as conduits for the contamination of groundwater since inadequately constructed wells provide a physical connection between sources of pollution and useable water.

RADON NOTICE

Radon is a naturally occurring colorless, odorless radioactive gas formed by the natural disintegration of uranium in soil, rock and ground water as it radioactively transmutes to form stable lead.


Radon gas forms from the decay of radioactive elements at depth. Air pressure inside a building is usually lower than pressure in the soil around the building's foundation. Because of this difference in pressure, buildings can act like a vacuum, drawing radon in through foundation cracks and other openings. As cracks develop in rocks, radon gas can rise into the local ground water and may also be present in well water and can be released into the air in buildings when water is used for showering and other household uses. In most cases, radon entering a building through water is a small risk compared with radon entering a building from the soil. In a small number of homes, the building materials can give off radon, although building materials alone rarely cause radon problems. The Surgeon General has warned that radon is the second leading cause of lung cancer in the United States. Only smoking causes more lung cancer deaths. Smokers that live in homes with high radon levels, are at an especially high risk for developing lung cancer.

The U.S. Environmental Protection Agency's (EPA) action level for indoor radon levels is 4 pCi/L, at which homes should be fixed. Even at lower levels Radon can still be dangerous, so the EPA recommends homeowners consider fixing their homes when the radon levels are between 2 pCi/L and 4 pCi/L.

Return to Quickview

Return to 1 Page NHD™

Property ID









REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES (continued)

The only way to determine radon levels for a specific property is by testing. For further information about radon testing and mitigation, contact the California Department of Public Health at https://www.cdph.ca.gov/Programs/CEH/DRSEM/Pages/EMB/Radon/Radon.aspx, The National Environmental Health Association (NEHA) at http://www.neha.org, and the National Environmental Radon Safety Board (NRSB) at http://www.nrsb.org.

WELL STIMULATION TREATMENTS NOTICE: HYDRAULIC FRACTURING

Hydraulic fracturing, (also known as hydrofracturing, "fracking", or "fracing") is the process of creating small cracks, or fractures, in underground geological formations to allow oil or natural gas to flow into the wellbore and thereby increase production. Prior to initiating hydraulic fracturing, engineers and geologists study and model the physical characteristics of the hydrocarbon bearing rock formations, including the formation permeability, porosity, and thickness. Using this information, the well operator designs the process to keep the resulting fractures within the target formation.

In order to regulate well stimulation treatments such as hyrdraulic fracturing, California Senate Bill 4 was signed into law on September 20, 2013. On December 30, 2014 the California Office of Administrative Law approved the formal rulemaking process for Well Stimulation Treatment Regulations, which went into effect on July 1, 2015. Senate Bill 4 regulates the entire process from permits to disclosure of chemicals used in fracturing process to closure of the well.

For further information on SB4, Well Stimulation Treatment Locations, and many other issues surrounding well stimulation in California, please see the Division of Oil, Gas & Geothermal Resources Well Stimulation Page at http://www.conservation.ca.gov/dog/Pages/WST.aspx.

CARBON MONOXIDE DEVICES

Pursuant to the Carbon Monoxide Poisoning Prevention Act of 2010, carbon monoxide detectors must be installed in every dwelling unit intended for human occupancy. Carbon monoxide is a gas produced when any fuel is burned, such as gas, oil, kerosene, wood, or charcoal. Because it is not possible to see, taste, or smell it, carbon monoxide can kill in minutes at high levels. Carbon monoxide detectors are similar to smoke detectors in that they will signal detection of carbon monoxide in the air. These carbon monoxide detectors should be installed outside of each separate sleeping area in the immediate vicinity of bedrooms, on every level including basements within which fuel fired appliances are installed, and in dwellings that have attached garages.

Links to additional information on carbon monoxide:

U.S. EPA, An Introduction to Indoor Air Quality (IAQ), Basic Information on Pollutants and Sources of Indoor Air Pollution, Carbon Monoxide: http://www.epa.gov/iaq/co.html

Center for Disease Control and Prevention (CDC), Carbon Monoxide Poisoning:

http://www.cdc.gov/co

American Lung Association, Carbon Monoxide Indoors:

http://www.lungusa.org/healthy-air/home/resources/carbon-monoxide-indoors.html


Consumer Product Safety Commission (CPSC), Carbon Monoxide Questions and Answers:

http://www.cpsc.gov/en/Safety-Education/Safety-Education-Centers/Carbon-Monoxide-Information-Center/Carbon-Monoxide-Questions-and-Answers-/

Return to Quickview

Return to 1 Page NHD™

Property ID









REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES (continued)

NATURAL GAS AND HAZARDOUS LIQUID PIPELINES

NOTICE REGARDING GAS AND HAZARDOUS LIQUID TRANSMISSION PIPELINES

This notice is being provided simply to inform you that information about the general location of gas and hazardous liquid transmission pipelines is available to the public via the National Pipeline Mapping System (NPMS) Internet Web site maintained by the United States Department of Transportation at http://www.npms.phmsa.dot.gov/. To seek further information about possible transmission pipelines near the property, you may contact your local gas utility or other pipeline operators in the area, some of which are included below. Contact information for pipeline operators is searchable by ZIP Code and county on the NPMS Internet Web site.

SoCalGas Natural Gas Pipeline Maps:

https://www.socalgas.com/stay-safe/pipeline-and-storage-safety/natural-gas-pipeline-map

PG&E Gas Transmission Line Maps:

https://www.pge.com/en/about/pge-systems/gas-systems.html#tabs-fc6b80548f-item-727cbee02b-tab

SDG&E Natural Gas Pipeline Maps: https://www.sdge.com/safety/gas-safety/pipeline-map

This notice is made pursuant to Section 2079.10.5 to the California Civil Code which provides that upon delivery of this notice to the transferee of the real property, the seller or broker is not required to provide information in addition to that contained in this notice regarding gas and hazardous liquid transmission pipelines. The information in this notice shall be deemed to be adequate to inform the transferee about the existence of a statewide database of the locations of gas and hazardous liquid transmission pipelines and information from the database regarding those locations. Nothing in this section shall alter any existing duty under any other statute or decisional law imposed upon the seller or broker, including, but not limited to, the duties of a seller or broker under this article, or the duties of a seller or broker under Article 1.5 (commencing with Section 1102) of Chapter 2 of Title 4 of Part 4 of Division 2.

WATER CONSERVING PLUMBING FIXTURES

For All Real Estate Sales - Residential and Commercial: On and after January 1, 2017, a seller or transferor of single-family residential real property, multifamily residential real property, or commercial real property shall disclose to a purchaser or transferee, in writing, specified requirements for replacing plumbing fixtures, and whether the real property includes non-compliant plumbing fixtures.

For All Single Family Residences: On or before January 1, 2017, all non-compliant plumbing fixtures in any single-family residential real property shall be replaced by the property owner with water-conserving plumbing fixtures.

For Commercial and Multifamily Residences: On or before January 1, 2019, all non-compliant plumbing fixtures in multifamily residential real property and commercial real property, as defined, be replaced with water-conserving plumbing fixtures.

For Building Alterations - Single Family Residences: On and after January 1, 2014, for all building alterations or improvements to single-family residential real property, water-conserving plumbing fixtures shall replace other noncompliant plumbing fixtures as a condition for issuance of a certificate of final completion and occupancy or final permit approval by the local building department.

Return to Quickview

Return to 1 Page NHDTM

Property ID

answers





REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES (continued)

For Building Alterations - Commercial and Multifamily Residences: On and after January 1, 2014, for specified building alterations or improvements to multifamily residential real property and commercial real property, water-conserving plumbing fixtures shall replace other non-compliant plumbing fixtures as a condition for issuance of a certificate of final completion and occupancy or final permit approval by the local building department.

California Civil Code Sections 1101.1 et seg.

NOTICE OF DUCT SEALING REQUIREMENTS

The California Energy Commission's ("CEC") duct sealing requirements, applicable to all climate zones in California per California Code of Regulations, Title 24, are in effect for all residential and non-residential properties. If a central air conditioner or furnace is installed or replaced, mandatory duct system sealing and leakage testing is required. Alterations and additions to ducted systems in existing buildings in all climate zones are also required to comply with applicable maximum leakage criteria. If significant leakage is found, repairs may be required to seal the ducts, with additional testing required to confirm the work was done properly. It is strongly recommended that all of this work be done by licensed contractors who should obtain all required permits. These current duct sealing requirements may impact a Seller's disclosure obligations and/or any negotiations between principals regarding replacing heating, ventilating and air conditions (HVAC) systems. These requirements may increase the costs associated with replacing or installing an HVAC system. For further information, visit:

https://www.energy.ca.gov/programs-and-topics/programs/building-energy-efficiency-standards/2022-building-energy-efficiency

15 SEER - Seasonal Energy Efficiency Ratio is the Federal Government's minimum standard efficiency rating in California for heating, ventilating, air conditioning, and heat pumps. The US Department of Energy requires central air conditioners and heat pumps to meet an efficiency rating of 15 SEER in the Southwest. For further information contact the California Energy Commission at 800-772-3300.

NOTICE OF ASSEMBLY BILL 1482: TENANT PROTECTION ACT OF 2019

As of January 1, 2020, the State of California has implemented <u>AB 1482</u>, a statewide tenancy and rent control law, requiring "just cause" to terminate a tenancy, and limiting annual rent increases.

Tenancy


This bill would, with certain exceptions, prohibit an owner from terminating a tenancy without just cause when the tenant has continuously and lawfully occupied the residential real property for 12 months. This bill would not apply to residential real property subject to a local ordinance requiring just cause for termination adopted on or before September 1, 2019, or to residential real property subject to a local ordinance requiring just cause for termination adopted or amended after September 1, 2019, that is more protective than these provisions. The bill would void any waiver of the rights under these provisions. The bill would repeal these provisions as of January 1, 2030.

Rent Increases

Return to Quickview

Return to 1 Page NHD™

Property ID









REPORT #: 4074593

REPORT DATE: 3/24/2025

GENERAL NOTICES OF REQUIRED DISCLOSURES (continued)

This bill would prohibit an owner of residential real property from, over the course of any 12-month period, increasing the gross rental rate for a dwelling or unit more than 5% plus the percentage change in the cost of living, or 10%, whichever is lower, subject to specified conditions. The bill would prohibit an owner of a unit of residential real property from increasing the gross rental rate for the unit in more than 2 increments over a 12-month period, after the tenant remains in occupancy of the unit over a 12-month period. The bill would exempt certain properties from these provisions. The bill would void any waiver of the rights under these provisions.

Disclosure Requirement

Depending on the property type, property age, date of tenancy, ownership status, and other considerations, property owners must provide notification to tenants of the provisions of AB 1482, and their rights under the law. The text of these disclosures can be found in the text of the law.

Complete Text: AB 1482

CALIFORNIA WATERWAY SETBACK REQUIREMENTS

Creeks and streams are valuable resources providing pollutant removal, drainage, flood control, and necessary riparian habitats important to several species of plants and animals. With the numerous benefits provided by healthy waterways, regulating development near streams and other waterways in order to reduce the environmental impact has become an important part of watershed management throughout the state.

While the State of California provides its own set of regulations regarding development near streams and other protected waterways, several cities and counties have added their own stream protection ordinances to the local general plan or municipal code. It is important to check with your local regulatory agency to see what types of rules and regulations your property may be subject to regarding development, expansion, or even land use in relation to streams and other watershed features on or near your property.

Return to Quickview









REPORT #: 4074593

REPORT DATE: 3/24/2025

COMMERCIAL PROPERTY EARTHQUAKE SAFETY GUIDE

<u>FOR</u> COMMERCIAL PROPERTIES IN CALIFORNIA

The booklets listed below are prepared by governmental entities and are provided as links in the body of the original email sent by Property I.D. when delivering the report electronically, and as a printed booklet when a hardcopy report delivery is requested with the your NHD order. The booklets contain important information about various topics including radon, mold, lead hazards, environmental hazards, earthquake safety, and energy conservation. You can obtain another copy of these important booklets for free by clicking on the links below, or by going to https://propertyid.com/government-booklets.

CALFIRE Defensible Space (© 2020)

https://www.readyforwildfire.org/wp-content/uploads/DefensibleSpaceFlyer.pdf

CALFIRE Low Cost Retrofit List (© 2020)

http://www.readyforwildfire.org/wp-content/uploads/Low-cost-Retrofit-List-Final.pdf

Home Energy Rating Guide (© 2011)

https://propertyid.com/government-booklets

California Homeowner's Guide to Earthquake Safety (© 2020)

https://propertyid.com/government-booklets

Department of Health Services Residential Environmental Hazards (© 2011)

https://propertyid.com/government-booklets

EPA Lead in Your Home (© 2021)

https://propertyid.com/government-booklets

Department of Health Services Mold FAQ (© 2016)

https://propertyid.com/government-booklets

Note: Your signature on the NHDS Report Receipt page is sufficient to acknowledge delivery/receipt of the safety guides mentioned above. However, if you require a separate signature page, acknowledging receipt of these guides, one is available from the Property I.D. website: https://propertyid.com/government-booklets

California Homeowner's Guide to Earthquake Safety (© 2022)

https://ssc.ca.gov/wp-content/uploads/sites/9/2022/09/FINAL-Approved-Commercial-Property-Owners-Guide-to-Earthquake-Safety-2022.pdf

Return to 1 Page NHDTM

Property ID









REPORT #: 4074593 | REPORT DATE: 3/24/2025

This statement applies to the following property: 54	54 VIRGINIA AVE LOS ANGELES, CA 90029;	LOS ANGELES COUNTY; APN: 5536-010-006	Date: 03/24/2025
This disclosure statement is intended to be a part of AIR STANDARD OFFER AGREEMENT AND ES		REAL ESTATE or	
		(the "Purchase Agreement") dated	
wherein	is the Seller and	is the Buyer.	
Note: This disclosure statement is <u>not</u> designed nor THIS REAL PROPERTY LIES WITHIN THE F	·	d Property Information Sheet.	
	e Zone "A" or "V") designated by the Federa w and information not available from local	al Emergency Management Agency. Refer to Rep I jurisdiction	port.
	N ON A DAM FAILURE INUNDATION MA v and information not available from local	P pursuant to Section 8589.5 of the Government jurisdiction	t Code. Refer to Report.
		or of Forestry and Fire Protection pursuant to Section The owner of this property is subject to the maintena	
High FHSZ in a state responsibility area Very High FHSZ in a state responsibility area Very High or High FHSZ in a local responsibili			
property is subject to the maintenance requirem	ents of Section 4291 of the Public Resource ands unless the Department of Forestry and	HAZARDS pursuant to Section 4125 of the Public as Code. Additionally, it is not the state's responsi Fire Protection has entered into a cooperative ag	ibility to provide fire protection services to
AN EARTHQUAKE FAULT ZONE pursuant to Yes No _X_	Section 2622 of the Public Resources Code.	. Refer to Report.	
A SEISMIC HAZARD ZONE pursuant to Section Yes (Landslide Zone) Yes (Lique	n 2696 of the Public Resources Code. Refer faction Zone) No <u>X</u> Map not	r to Report. t yet released by state	
The items listed below indicate additional statutory of	lisclosures and legal information that are provide	ed in the report.	
ASSESSMENTS pursuant to Section 53311-5336 Additional Local Jurisdiction Hazards - May include Airports, Airport Influence Area, Avalanch Level Rise, Landslide, Liquefaction, Methane Gas Williamson Act, Wind Erosion. Refer to Report. General Notices: Methamphetamine Contamination, Megar Plumbing Fixtures, Notice of Supplemental Prope to Report. Governmental Guides are delivered with printed r	closed if ordered) TION (where available) (B) MILITARY ORDNANCE FAST.7 (53754 of the California Government Code; Refa the following: e, Coastal Protection, Conservation Areas, Critical H., Mines, Naturally Occurring Asbestos, Oil and Gas \(\) \(\) \(abitats, Dam Failure Inundation, Duct Sealing Requiremen Well Proximity, Petrochemical Contamination, Property Ta d Wells. Carbon Monoxide Devices, Natural Gas and Haza Je, CALFIRE Low Cost Retrofit List, SGMA Groundwater E	nts, Erosion, Fault Zone, Fire, Groundwater, Sea Ixes, Radon, Right to Farm, Soil Stability, Tsunam Irdous Liquid Pipelines, Water Conserving Basin Priority, Historical Significance Notice. Refer
	or consequences of this document, or the purc	ns or warranties the principal(s) may wish to obtain. No chase agreement to which it relates. The representation	
This Report contains the Mandatory Commercial Na please contact Property I.D. Customer Service at 80	·	ntal Risk Report is only enclosed if it has been ordered	d. To order the Environmental Risk Report,
Signature of Seller(s)		Date	
Print Name			
Signature of Seller(s) Print Name		Date	
Signature of Buyer(s)		Date	
Print Name			
Signature of Buyer(s)		Date	
Print Name			

Commercial Property Earthquake Risk Disclosure Report (2022 Edition)

Name APN				0-006			
Stre	et Address 5454 VIRGINIA AVE			Year Built .		_	
City	LOS ANGELES Co	unty_LOS ANC					
Anso 8 or know furth risks	wer these questions to the best of your knowledge. If any of questions 9 is answered "Yes," your property is likely to have an elevated/discloswledge as to whether these risks exist, answer "Don't Know." Question her evaluation. If your property does not have the feature, answer "Does, describe the work on a separate page. The page numbers in the right information on each of these features.	able earthquake s answered "Do sn't Apply." If yo	e risk. If g n't Knov ou corre	you do not v" may ind cted one o	have act icate a ne r more o	ual eed for f these	
		Yes	No	Doesn't Apply	Don't Know	See Page	
1.	Are water heater(s) braced, strapped, or anchored to resist falling during an earthquake?					14	
2.	If the building has precast (tilt-up) concrete or masonry walls (reinforce or unreinforced) with wood-frame floors or roof: Are walls adequately anchored to floors and roofs?	ed 🗆				15	
3.	If building walls are of unreinforced masonry:						
	a. Are these walls and parapets strengthened?					16	
	b. If load-bearing walls have not been strengthened, and the building is in Seismic Zone 4: Have warning signs been posted?	ng 🗆				17	
4.	If the building is a pre-1980 concrete building: Do walls or columns have adequate steel reinforcement?					18	
5.	If the building is a pre-1995 building with steel-moment framing: Has been inspected for fractures in welds in or near steel connections?	it \Box				19	
6.	If the building has a soft- or weak-story or open-front design: Has it be adequately strengthened?	een				20	
7.	Is exterior cladding and signage adequately anchored?					21	
	Yes" answer on Questions 8 and/or 9 could indicate that the property ore information is available at www.conservation.ca.gov/cgs/geohazar		rone to	earthquak	e damage	е.	
8.	Is the building in an Alquist-Priolo Earthquake Fault Zone (an area proto fault rupture)?	ne				6	
9.	Is the building in a Seismic Hazard Zone (zone identified as susceptibl to liquefaction or landslides)?	е				6	
	eller of the property described herein, I have answered the questions a lose fully any potential earthquake risks it may have.	bove to the bes	t of my	knowledge	in an eff	ort to	
EXE	CUTED BY						
Selle	er Seller	[Date				
ansv	knowledge receipt of this Disclosure Report, completed and signed by evered "No" to one or more questions 1–7 or "Yes" to question 8 or 9, or e may be one or more earthquake risks that could impact this property.	or if the seller ha	erstand t as indica	that if the s ited a lack	eller has of knowle	edge,	
D.	D	-	\ -+-				

DEPARTMENT OF HOMELAND SECURITY Federal Emergency Management Agency

STANDARD FLOOD HAZARD DETERMINATION FORM (SFHDF)

<u> </u>	7 11 12 7 11 12 1 2 1					
		SECTION I - LOAN	INFORMAT	ION		
1. LENDER/SERVICER NAME	2. COLLATERAL DE more information.)	COLLATERAL DESCRIPTION (Building/Mobile Home/Property) (See instructions for more information.)				
		5454 VIRGINIA A LOS ANGELES, CA APN: 5536-010-0 LOS ANGELES CO	A 90029 006			
3. LENDER/SERVICER ID#	4. LOAN IDENTIF	IER		5. AMOUN	T OF FLOOD INSURANCE REQUIR	ΞD
*		SECTIO	ON II			
A. NATIONAL FLOOD INSUR	ANCE PROGRAM			N		
1. NFIP Community Name		2. County(ies)	T	3. State	4. NFIP Community Number	
CITY OF LOS ANGELES		LOS ANGELES		CA	060137	
B. NATIONAL FLOOD INSUR	ANCE PROGRAM	I (NFIP) DATA AFFECT	ING BUILDIN	IG/MOBILE		
1. NFIP Map Number or Comr		· · ·		0.0	e a Letter of Map Change (LOMC)?	
(Community name, if not the s		Revised Date		⊘ NO		
06037C1610F		09/26/2008		OYES	(if yes, enter date and case no. belo	w.)
4. Flood Zone		5. No NFIP Map		-		
X (NOT AN SFHA)				Date	Case No.	
C. FEDERAL FLOOD INSURA	ANCE AVAILABIL	ITY (Check all that app	ly.)	d-		
1. 🗹 Federal Flood Insurance	e is available (com	munity participates in the	e NFIP). 🗹	Regular Pr	rogram Emergency Program of	NFIP
2. Federal Flood Insurance	e is not available (c	community participates in	the NFIP).			
3. Building/Mobile Home is may not be available.	s in a Coastal Barri	er Resources Area (CBF	RA) or Otherw	rise Protecte	ed Area (OPA). Federal Flood Insuran	ce
CBRA/OPA Designation	n Date:	~				
D. DETERMINATION						
IS BUILDING/MOBILE HOME	IN SPECIAL FLO	OD HAZARD AREA (ZO	ONES CONTA	AINING THE	ELETTERS "A" OR "V")? YES	√ NO
If yes, flood insurance is requir If no, flood insurance is not req not removed.				se note, the	risk of flooding in this area is only red	luced,
This determination is based on information needed to locate the				agement Ag	ency revisions to it, and any other	
E. COMMENTS (Optional) THE PROPERTY IS NOT LOCATED IN		AZARD AREA (SFHA).				
IT IS IN ZONE X (NOT AN SFHA)						
F. PREPARER'S INFORMATI	ON		PLAIN	I МА.		
NAME, ADDRESS, TELEPHO	NE NUMBER (If of	ther than Lender)	008	A CK	DATE OF DETERMINAT	ΓΙΟΝ
Property I.D.						
1001 Wilshire Blvd. Los Angeles, CA 90017 03/24/2025						
	26-0106	= -	PROPE		OrderID: 4074593	

FEMA FORM FF-206-FY-21-116 (formerly 086-0-32) (04/21)

CERTIFIED

TERMS AND CONDITIONS

The Property I.D. MAX Report (Report) is subject to each of the following Terms and Conditions. Each Recipient (as that term is defined below) of the Report hereby acknowledges and agrees that the Report is subject to the following Terms and Conditions, and each Recipient agrees to be bound by such Terms and Conditions. Use of this Report by any Recipient constitutes acceptance of the Terms and Conditions to the Report. The Terms and Conditions below are hereby incorporated by this reference into the Report. This Report is not an insurance policy.

The following persons or entities, if any, are deemed "Recipients" of this Report: (1) the seller of the real property that is the subject of the specific transaction for which this Report was issued; (2) that seller's agent and broker; (3) the buyer of the real property that is the subject of the specific transaction for which this Report was issued; (4) that buyer's agent and broker; (5) Transaction Coordinator; and (6) the escrow officer and escrow company handling the specific transaction for which this Report was issued. This Report is for the exclusive use of the Recipients. No person or entity, other than the Recipients, shall be entitled to use or rely on the Report. This Report may not be used, referred to, or relied upon by any person or entity other than the Recipients. No person or entity, other than the Recipients, shall be deemed, treated, or considered to be a beneficiary (intended or otherwise) of this Report. If any Recipients do not intend to be bound by the terms, conditions, limitations, and disclaimers in this Report, or if any of them otherwise determine this Report is unacceptable, Recipients should immediately cancel this Report by emailing their cancellation of this Report to: orders@propertyid.com. Recipients are obligated to make disclosures that are within their actual knowledge.

This Report has been issued in connection with a particular transaction for the sale of the real property described in the Report. The Report may only be used in connection with that particular transaction. If an escrow number has been provided to Property I.D., then this Report may only be used in connection with that particular escrow. The Report may not be used for any other transaction or escrow.

The Report may not be used, for any purpose, if the Recipients have not paid for the Report.

This Report is made for the real property specifically described in the Report (the "Subject Property"). The Subject Property shall not include any property beyond the boundaries of the real property described in the Report. The Subject Property shall not include any structures (whether located on the Subject Property, or not), easements, or any right, title, interest, estate, or easement in any abutting streets, roads, alleys, lanes, ways, or waterways.

No determination is made and no opinion is expressed, or intended, by this Report concerning the right, entitlement, or ability to develop or improve the Subject Property I.D. has no information concerning whether the Subject Property can be developed or improved. Property I.D. expresses no opinion or view, and assumes no responsibility, with respect to the development or improvement of the Subject Property.

No determination is made and no opinion is expressed, or intended, by this Report as to title to the Subject Property. No determination is made and no opinion is expressed, or intended, by this Report concerning whether the Subject Property is comprised of legal lots in conformance with the California Subdivision Map Act or local ordinances.

No determination is made and no opinion is expressed, or intended, by this Report concerning architectural, structural, mechanical, engineering, or legal matters. No determination is made and no opinion is expressed, or intended, by this Report concerning structures or soils on or outside of the Subject Property, including, without limitation, habitability of structures or the Subject Property suitability of the Subject Property for construction or improvement, potential for soil settlement, drainage, soil subsidence, or other soil or site conditions. No determination is made and no opinion is expressed, or intended, by this Report concerning the marketability or value of the Subject Property. Property I.D. has not conducted any testing of the Subject Property. Property I.D. has not conducted any physical or visual examination or inspection of the Subject Property. This Report is not a substitute for a physical or visual examination or inspection of the Subject Property. If detailed on-site information regarding geologic, environmental, engineering, planning, or other professional studies is desired, Property I.D. recommends that an appropriate qualified professional consultant be retained.

No determination is made and no opinion is expressed, or intended, by this Report concerning the existence of hazardous or toxic materials or substances, or any other defects, on or under the Subject Property, unless specifically described in the Report.

No determination is made and no opinion is expressed, or intended, by this Report concerning any condition of the Subject Property, unless that condition is specifically described in the Report. The Report is intended to address any matter (either expressly or impliedly) not specifically described in the text of the Report.

This Report is issued as of the date identified in the Report. Property I.D. shall have no obligation to advise any Recipient of any information learned or obtained after the date of the Report even if such information would modify or otherwise affect the Report. Subsequent to Property I.D.'s acquisition of Government Records, changes may be made to said Government Records and Property I.D. is not responsible for advising the Recipients of any changes. Property I.D. will update this Report upon request and at no charge during the transaction process for which this Report was issued, but not to exceed one year from the date of the Report. Likewise, Property I.D. is not liable for any impact on the Subject Property that any change to the Government Records may have.

No determination is made and no opinion is expressed, or intended, by this Report concerning the need to purchase earthquake, fire, or flood insurance, or any other insurance, for the Subject Property. In preparing the Report, Property I.D. has accurately reported on information contained in Government Records. Property I.D. has reviewed and relied upon those Government Records specifically identified in the Report. Property I.D. has not reviewed any parcel maps, plat maps, survey maps, surveyor maps, assessor maps, assessor parcel maps, developer maps, or engineering maps, whether or not such maps have been recorded. No determination is made and no opinion is expressed, or intended, by the Report concerning any matters identified in Government Records that were not reviewed by Property I.D. If any Recipient has a question concerning the specific Government Records reviewed (or not reviewed) by Property I.D., then the Recipients should contact Property I.D.'s Customer Service Department at (800) 920-5603.

Mapped hazard zones may represent generalized hazard information. If the questionable edge of a hazard zone impacts any portion of the Property, the report will reflect that the Property is "IN" the zone. If the Subject Property shares a common area with other properties (examples include condominiums, planned developments, town homes, and mobile homes) and any portion of the common area of the complex in which the Subject Property is located is situated in the specified hazard zone, due to the quality and availability of the parcel boundary information supplied by the county, "IN" may be reported even if the property/unit/lot that is the subject of this report is itself not in the specified hazard zone. If the county's parcel boundaries include only the individual unit's boundaries and do not include common areas for which property owners may also be responsible, hazards that exist only in the common areas may not be reported as "IN". When found in the hazard determination the terms "zone", "area", or "mapped" are words strictly defined as geographic locations delineated by specific boundaries identified in the maps and/or data prepared by the applicable governmental agency.

Property I.D. has relied upon the Government Records specifically identified in the Report without conducting an independent investigation of their accuracy. Property I.D. assumes no responsibility for the accuracy of the Government Records identified in the Report.

To the extent that any Recipient has provided information to Property I.D. (including, without limitation, a legal description of the Subject Property), Property I.D. has not conducted an independent investigation of the accuracy of the information provided by the Recipient. Property I.D. assumes no responsibility for the accuracy of information provided by the Recipient. Property I.D. shall be subrogated to all rights of any claiming party against anyone including, but not limited to, another party who had actual knowledge of a matter and failed to disclose it to the Recipients in writing prior to the close of escrow.

Except as specifically described in the Report, Property I.D. makes no warranty or representation of any kind, express or implied, with respect to the Report. Property I.D. expressly disclaims and excludes any and all other express and implied warranties, including, without limitation, warranties of merchantability or fitness for a particular purpose.

Property I.D. shall have no responsibility, or liability, for any lost profits, consequential damages, special damages, indirect damages, or incidental damages allegedly suffered as a result of the use of, or reliance on, the Report.

The Report shall be governed by, and construed in accordance with, the laws of the State of California.

This Report constitutes the entire, integrated agreement between Property I.D. and Recipients, and supersedes and replaces all prior statements, representations, negotiations, and agreements.

If any provision of the Terms and Conditions to this Report is determined to be invalid or unenforceable for any reason, then such provision shall be treated as severed from the remainder of the Terms and Conditions, and shall not affect the validity and enforceability of all of the other provisions of the Terms and Conditions.

Any dispute, controversy, or claim arising out of, or relating in any way, to the Report, shall be resolved by binding arbitration in Los Angeles, California, in accordance with the arbitration rules of the Judicial Arbitration and Mediation Service ("JAMS"). You hereby agree that, by agreeing to binding arbitration, you are waiving the right to a trial by jury and you are waiving the right to participate in a class action. The prevailing party in the arbitration shall be entitled to its attorneys' fees and costs, including, without limitation, the fees of the arbitrator.